1	Submit 1 Copy To Appropriate District Office State of New Mexico	Form C-103	
	District I – (575) 393-6161 Energy, Minerals and Natural Resources	Revised July 18, 2013	
	District II (575) 748 1282		
	811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION 5 Indicate Type of	of Lease	
	1000 Rio Brazos Rd., Aztec, NM 87410 STATE STATE	FEE 🛛	
	District IV – (505) 476-3460 Santa Fe, NM 87505 1220 S. St. Francis Dr., Santa Fe, NM 87505	s Lease No.	
		OT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A RENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH OSALS.) Type of Well: Oil Well Gas Well Other The one of Operator The operator of Operator of Operator The operator of Operator of Operator of Operator The operator of Operator	
	610 Reilly Ave, Farmington, NM 87401 W Kutz PC		
	4. Well Location		
	Unit LetterD:1115feet from theNorth line and865feet from theWest line		
		ounty	
	11. Elevation (Show whether DR, RKB, RT, GR, etc.) 5315 GL		
	3313 GL		
	12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
É	TEMPORARILY ABANDON	P AND A	
	Merrion Oil & Gas proposes to plug the above mentioned well. Please see the attached procedure and WBD.		
	NMOCD		
	FEB 27 2019 Notify NMOCD 24 hrs prior to beginning operations		
*	# Plug #3 is required from 170' to surface	me and the time.	
	pud Date: Rig Release Date:		
	I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE		
	Type or print namePhilana Thompson E-mail address:pthompson@merrion.bz PHONE: For State Use Only	_505-486-1171 Verbal g:ven	
	APPROVED BY: Bold Many: Conditions of Approval (if any): TITLE I & Superviso par		

PLUG AND ABANDONMENT PROCEDURE

January 17, 2019

Redfern Com #3

West Kutz Pictured Cliffs
1115' FNL & 865' FWL, Section 14, T29N, R13W, San Juan County, New Mexico
API 30-045-29610 / Lat: _____ / Long: ______

This procedure is revised based on the approved P&A sundry. All cement volumes use 100% excess outside pipe and 50' excess inside pipe. The stabilizing wellbore fluid will be 8.3 ppg. sufficient to balance all exposed formation pressures. All cement will be Class G, mixed at 15.8 ppg with a 1.15 cf/sx yield. 1. This project will use an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up. 2. Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well. Kill well with water as necessary and at least pump tubing capacity of water down the tubing. ND wellhead and NU BOP. Function test BOP. 3. Rods: Yes_X_, No___, Unknown__ Tubing: Yes X, No , Unknown , Size 2-3/8", Length 1230'. Packer: Yes____, No_X_, Unknown ___, Type ____ If this well has rods or a packer, then modify the work sequence in step #2 as appropriate.

- 4. NOTE: BLM requires a CBL log to be run on all wells where the cement did not circulate to surface or a CBL log was not previously run. This procedure is prepared with the understanding that it may be modified based on the TOC from the CBL.
- 5. Plug #1 (Pictured Cliff interval & Fruitland Coal top, 1143' 1043'): R/T 4.5" gauge ring or mill to 1143'. RIH and set 4.5" CIBP at 1143'. Pressure test tubing to 1000#. Attempt to pressure test casing to 800#. If casing does not test then spot or tag subsequent plugs as necessary. Mix and pump 12 sxs Class G cement and spot a balanced plug inside casing to isolate the perforations and the Fruitland Coal top. PUH.
- 6. Plug #2 (Fruitland top, 930' 830'): Mix and pump 12 sxs Class G cement and spot a balanced plug inside casing to cover the Fruitland top. PUH.
- 7. Plug #3 (7" Surface casing shoe, 120' Surface): Attempt to pressure test the bradenhead annulus to 300 PSI; note the volume to load. If the BH annulus holds pressure, then establish circulation out casing valve with water. Mix approximately 14 sxs cement and spot a balanced plug from 170' to surface, circulate good cement out casing valve. TOH and LD tubing. Shut well in and WOC. If the BH annulus does not test, then perforate at the appropriate depth and attempt to circulate cement to surface filling the casing and annulus from the squeeze holes to surface. Shut in well and WOC.


8. ND BOP and cut off wellhead below surface casing flange. Install P&A marker with cement to comply with regulations. Record GPS coordinate for P&A marker on tower report. Photograph P&A marker in place. Cut off anchors and clean up location. Restore location per BLM stipulations.

Redfern Com #3

Current

West Kutz Pictured Cliffs 1115' FNL & 865' FWL, Section 14, T29N, R13W, NMPM San Juan County, NM API# 30-045-29610

Today's Date: 1/17/2019



Redfern Com #3

Proposed P&A West Kutz Pictured Cliffs

Today's Date: 1/17/19 Spud: 9/29/98

Completed: 11/21/98

1115' FNL & 865' FWL, Section 14, T29N, R13W San Juan County, NM, API #30-045-29610

