	UNITED STATE DEPARTMENT OF THE I	NTERIOR	0	FORM APPROVED DMB NO. 1004-0137 pires: January 31, 2018	
BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on page 2				5. Lease Serial No. NMNM080273	
			6. If Indian, Al	lottee or Tribe Name	
			7. If Unit or Ca	7. If Unit or CA/Agreement, Name and/or No.	
I. Type of Well ☐ Gas Well ☐ G	Other			8. Well Name and No. HANSON FEDERAL 1	
2. Name of Operator MUSTANG RESOURCES LLC Contact: DEB LEMON E-Mail: dlemon@mustangresurcesllc.com			9. API Well No 30-039-20	0. 048-00-S1	
3a. Address 1660 LINCOLN ST. SUITE 1 DENVER, CO 80264	3b. Phone No. (include area cod Ph: 720-550-7507 Ext: 10		ool or Exploratory Area HACRA		
4. Location of Well (Footage, Sec.,	T., R., M., or Survey Description	n)	11. County or l	Parish, State	
Sec 3 T23N R7W NWSW 16 36.252731 N Lat, 107.56828			RIO ARRI	BA COUNTY, NM	
12. CHECK THE A	APPROPRIATE BOX(ES)	TO INDICATE NATURE	OF NOTICE, REPORT, OF	R OTHER DATA	
TYPE OF SUBMISSION		TYPE	OF ACTION		
Notice of Intent	Acidize	Deepen	Production (Start/Result	ne) 🔲 Water Shut-Off	
	□ Alter Casing	Hydraulic Fracturing	g 🗖 Reclamation	U Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplete	☑ Other Workover Operati	
□ Final Abandonment Notice	Change Plans	Plug and Abandon	Temporarily Abandon	workover Operation	
13. Describe Proposed or Completed C	Convert to Injection		UWater Disposal		
Mustang Resources, LLC re Federal #1.	quests approval to perform	n the attached squeeze proce	edure at the Hanson		
			NW	OCD	
			JUL 2	5 2019	
			DISTRI	CT III	
14. I hereby certify that the foregoing		4473053 verified by the BLM W	all Information System		
	For MUSTANG	RESOURCES LLĆ, sent to th	e Farmington		
Name(Printed/Typed) DEB LE		rocessing by JOE KILLINS on Title REGL	ILATORY MANAGER		
Signature (Electronic	e Submission)	Date 07/12			
	THIS SPACE FO	OR FEDERAL OR STATE	OFFICE USE		
Approved By JOE KILLINS		TitleENGINE	ER	Date 07/16/2	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		s not warrant or e subject lease			
Title 18 U.S.C. Section 1001 and Title 4	3 U.S.C. Section 1212, make it a	Office Farmir crime for any person knowingly at	nd willfully to make to any departr	nent or agency of the United	
States any false, fictitious or frauduler	it statements or representations as	s to any matter within its misting in			
States any false, fictitious or frauduler Instructions on page 2)					
States any false, fictitious or frauduler Instructions on page 2) ** BLM RE				VISED **	



Well Name:	Hanson Fed #1
API Number:	30-039-20048
Location:	S3, T23N, R7W
County:	San Juan

Note: Follow all NMOCD Rules and Regulations. Mustang Resources LLC Contact: Chuck Dobie 661-301-5802 Note: for all plugs, assume 15.8ppg Density and a 1.15 cf/sx yield.


4-1/2", 10.5#	Capacity	0.0896 ft3/ft
		0.01596 bbl/ft
	ID	4.052 Inches

Step **Description**

1	Prior to work, check lease roads, test rig anchors, arrange for fresh water on location
2	Prior to rig, verify wellhead connections for any flanges, DSA's and BOPE necessary.

Prior to rig, verify wellhead connections for any flanges, DSA's and BOPE necessary.

- 3 Notify NMOCD 48 hours before commencing rig operations
- 4 MIRU workover rig with 2M Class II BOPE.
- 5 Kill well, if necessary with produced water (well likely at low to no pressure)
- 6 Fill 400 bbl tank with produced water for kill operations to be used as necessary.
- 7 Keep hole to RBP full of fluid at all times
- 8 TOOH w/production tubing (2 3/8", 4.7 ppf, J-55 at 5363').
- 9 Visually inspect tubing. Move in work string if needed
- 10 RIH with 4-1/2" all weight scraper and bit in tandem to PBTD at 5695' (or at least to bottom perf at 5614')
- POOH and L/D bit and scraper. 11
- 11A TIH RBP to 800' and set
- 12 P/U and RIH with tubing open ended to 700'.
- 13 Plug 1 Circulate well. Balance plug from 700' - 500' with 19 sacks of Class 'G' Cement
- 14 POOH minimum 200' above cement. Reverse circ tubing clean. POOH standing back tubing.
- 15 Shut in Casing and pressure 4 1/2" casing to 750 psi.
- 16 Shut down rig and WOC
- 17 Rig up power swivel.
- RIH with bit on tubing. Drill out cement. 18
- 19 POOH and remove bit.
- 19A Pressure Test casing to 600 psi for 30 minutes w/chart recorder
- 19B TIH and retrieve RBP at 800'
- 20 Run tubing back in hole with pump shoe to mid perf
- 21 RIH with rods and insert pump.
- 22 RTP



Hanson Federal #1

.

۰.

8/6/1998 Spot 130.2 gal 15% HCl, pump 1890 gal 15% HCl @ 2.6 BPM

gal 15% HCI, pump 1890 gal 1

4-1/2" 10.5# 0.0896 ft3/ft

· · · ·

Plug #1

-----Balanced Plug-----

.

500	
700	
21.5	cf x 20% S:
22	cf
19.1	sx
	700 21.5 22

Assume 1.15 cf/sk