Forin 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

Lease Serial No. JIC38

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.	6. If Indian, Allottee or Tribe Name JICARILLA APACHE
SUBMIT IN TRIPLICATE - Other instructions on page 2	7. If Unit or CA/Agreement, Name and/or No.

SUBMIT IN TRIPLICATE - Other ins	7. If Unit or CA/Agreement, Name and/or No.	
Type of Well Oil Well		8. Well Name and No. AXI APACHE H 1
2. Name of Operator Contact: DJR OPERATING LLC E-Mail: amascare	ALICE MASCARENAS nas@djrllc.com	9. API Well No. 30-039-05170-00-S1
3a. Address 1600 BROADWAY SUITE 1600 DENVER, CO 80202	3b. Phone No. (include area code) Ph: 505-632-3476	10. Field and Pool or Exploratory Area BALLARD
4. Location of Well (Footage, Sec., T., R., M., or Survey Description	1)	11. County or Parish, State
Sec 5 T23N R5W SENE 1980FNL 990FEL 36.256606 N Lat, 107.378754 W Lon		RIO ARRIBA COUNTY, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
□ Notice of Intent	☐ Acidize ☐ Alter Casing	☐ Deepen ☐ Hydraulic Fracturing	☐ Production (Start/Resume) ☐ Reclamation	☐ Water Shut-Off ☐ Well Integrity
Subsequent Report ☐ Final Abandonment Notice	☐ Casing Repair ☐ Change Plans ☐ Convert to Injection	□ New Construction☑ Plug and Abandon□ Plug Back	☐ Recomplete ☐ Temporarily Abandon ☐ Water Disposal	☐ Other

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

This subject well was P&A'd on 12/11/19 per attached EOW Report, plugged wellbore diagram and marker.

> NMOCD CEC 13 2019 DISTRICT III

14. I hereby certify that	the foregoing is true and correct. Electronic Submission #495652 verifie For DJR OPERATING LL Committed to AFMSS for processing by JOH	c. sent	to the Rio Puerco	
Name (Printed/Typed)	ALICE MASCARENAS	Title	REGULATORY TECHNICIAN	
Signature	(Electronic Submission) THIS SPACE FOR FEDERA	Date	12/12/2019 STATE OFFICE USE	
Approved By AC	CEPTED any, are attached. Approval of this notice does not warrant or		OHN HOFFMAN PETROLUEM ENGINEER	Date 12/13/201
certify that the applicant he which would entitle the ap	olds legal or equitable title to those rights in the subject lease plicant to conduct operations thereon.		Rio Puerco	east or exercise Challeited

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



DJR Operating LLC

Plug And Abandonment End Of Well Report

AXI Apache H #001

1980' FNL & 990' FEL, Section 5, T23N, R5W Rio Arriba County, NM / API 30-039-05170

Work Summary:

- 11/17/19 Made BLM, NMOCD, Jicarilla P&A operations notifications at 9:00 AM MST.
- **11/18/19** MOL and R/U P&A unit. Checked well pressures: Tubing: 0 psi, Casing: 0 psi, Bradenhead: 0 psi.
- 12/3/19 Checked well pressures: Tubing: 0 psi, Casing 0 psi, Bradenhead: 0 psi. Bled down well. Worked on breaking wellhead bolts for approximately 4 hours. Could not get tubing hangar pins out. Waited on WSI to bring grinder to grind tubing hanger pins. Pulled tubing hangar and made sure production tubing was not stuck. Reset tubing hangar. Shut-in well for the day.
- 12/4/19 Checked well pressures: Tubing: 0 psi, Casing: 0 psi, Bradenhead: 0 psi. Bled down well. N/D wellhead, N/U BOP and function tested. TOOH with 68 joints of production tubing. P/U casing scraper and round tripped above top perforation at 2039'. P/U CR, TIH and set at 2005'. Pressure tested tubing to 1000 psi in which it successfully held pressure. Stung out of CR. TOOH and shut-in well for the day. Leo Pacheco was BLM inspector on location.
- 12/10/19 Checked well pressures: Tubing: 0 psi, Casing: 0 psi, Bradenhead: 0 psi. Bled down well. Circulated the wellbore clean with 43 bbls of fresh water. Attempted to pressure test casing to 800 psi in which it failed to hold pressure. R/U wire line services. Ran CBL from CR at 2005' to surface. CBL results were sent to BLM/NMOCD offices for review. CBL indicated good cement throughout wellbore. R/U

cementing services. Pumped plug #1 from 2005'-1393' to cover the Pictured Cliffs perforations and formation top and Fruitland, Kirtland, and Ojo Alamo formation tops. WOC overnight. Shut-in well for the day. Leo Pacheco was BLM inspector on location.

12/11/19 Checked well pressures: Tubing: 0 psi, Casing: 0 psi, Bradenhead: 0 psi. Bled down well. TIH and tagged plug #1 top at 1413'. Attempted to pressure test casing to 800 psi in which it failed to hold pressure. L/D 12 joints of tubing. R/U cementing services. Pumped plug #2 from 1019'-800' to cover the Nacimiento formation top. WOC 4 hours. TIH and tagged plug #2 top at 815'. L/D 13 joints of tubing. R/U cementing services. Pumped surface plug from 378'-surface to cover the surface casing shoe. N/D BOP and cut-off wellhead. Ran weighted tally tape down production casing and tagged cement 4' down. Cement was at surface in surface casing. Installed P&A marker per BLM/NMOCD standards. Topped-off well with 51 sx of cement. Photographed the P&A marker in place and recorded it's location via GPS coordinates. R/D and MOL. Leo Pacheco was BLM inspector on location.

Plug Summary:

Plug #1: (Pictured Cliffs Perforations and Formation Top, Fruitland, Kirtland, and Ojo Alamo Formation Tops 2005'-1413', 75 Sacks Class G Cement)

Mixed 75 sx Class G cement and spotted a balanced plug to cover the Pictured Cliffs perforations and formation top, Fruitland, Kirtland, and Ojo Alamo formation tops.

Plug #2: (Nacimiento Formation Top 1019'-815', 27 Sacks Class G Cement)

Mixed 27 sx Class G cement and spotted a balanced plug to cover the Nacimiento formation top.

Plug #3: (Surface Casing Shoe 378'-Surface, 120 Sacks Class G Cement(51 Sacks for top-off))

Pumped surface plug from 378'-surface to cover the surface casing shoe. N/D BOP and cut-off wellhead. Ran weighted tally tape down production casing and tagged cement 4' down. Cement was at surface in surface casing. Installed P&A marker per BLM/NMOCD standards. Topped-off well with 51 sx of cement. Photographed the P&A marker in place and recorded it's location via GPS coordinates. R/D and MOL.

Wellbore Diagram

AXI Apache H #001 API #: 3003905170 Rio Arriba County, New Mexico

Plug 3

378 feet - Surface 378 feet plug 120 sacks of Class G Cement

51 sacks for top-off

Plug 2

1019 feet - 815 204 feet plug 27 sacks of Class G Cement

Plug 1

2005 feet - 1413 592 feet plug 75 sacks of Class G Cement

Surface Casing

8.625" 24# @ 315 ft

Formation Pictured Cliffs - 2053 ft

Retainer @ 2005 feet

Production Casing 5.5" 14# @ 2152 ft

