

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

14-20-603-1043

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Navajo

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Navajo Table Mesa

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Undesignated Paradox

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 27, T-28-N, R-17-W

12. COUNTY OR PARISH 13. STATE

San Juan

New Mexico

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
SUN OIL COMPANY - OX Division

3. ADDRESS OF OPERATOR

P. O. Box 1416, Roswell, New Mexico 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface

790' FSL & 1850' FWL, Section 27, T-28-N, R-17-W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5349 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*


(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Estimated starting date: 6/30/69

Well has reached its economic limit (2 BOPD, 365 BOPD)

1. Pull tubing, rods & pump.
2. Fill hole with mud.
3. Run tubing & stinger through packer at 7200' and set 50 sx plug from TD 7411 to 7200' over productive zone.
4. Cut 5 1/2" csg w/jet cutter @ 6000' or above, and POOH.
5. Cut 8 5/8" csg w/jet cutter @ approx. 3000' and POOH.
6. Set 25 sx plug in and out of 5 1/2" csg stub, from 6075-5925' w/tubg.
7. Set 25 sx plug in and out of base of 8 5/8" csg @ 5000' from 5020-4950 w/tubg.
8. Set 50 sx plug from 1700' to 1600' to cover water zone.
9. Set 25 sx plug in 13 3/8" csg from surface to 60'.
10. Install dry hole marker, clear location, and make ready for inspection by est. 7/15/69.



RECEIVED

JUN 17 1969

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

18. I hereby certify that the foregoing is true and correct

SIGNED

J.B. Hille

TITLE

Acting District Engineer

DATE

6/16/69

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE