

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Energen Resources, Inc.	Contact: Ed Hasely	
Address: 2010 Afton Place, Farmington, NM 87401	Telephone No: 505-324-4131	
Facility Name: LDS 29-10-31 #1S; API No. 3004532904	Facility Type: Oil/Gas Well Site	
Surface Owner: Federal	Mineral Owner: Federal	Lease No. NM0702

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	31	29N	10W	1980	South	660	East	San Juan

Latitude 36.68083

Longitude -107.91833

NATURE OF RELEASE

Type of Release: Compressor Engine Fire	Volume of Release: <1 MCF - Natural Gas	Volume Recovered: 0
Source of Release: Compressor Engine	Date and Hour of Occurrence: 9/16/09	Date and Hour of Discovery: 9/16/09
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom: Brandon Powell - NMOCD; Kevin Schneider (BLM)	
By Whom? Ed Hasely	Date and Hour: 9/17/09 1:30 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. NA RCVD SEP 28 '09	
If a Watercourse was Impacted, Describe Fully.* NA OIL CONS. DIV. DIST. 3		



Describe Cause of Problem and Remedial Action Taken.*

A small compressor fire was discovered on the subject location on 9/16/09. Investigations point to the possibility that a spike in line pressure caused the gasket between the gear housing and the rotor housing to blow out at the top of the compressor. The resulting released gas may have been ignited by the exhaust or the engine ignition wiring.

Describe Area Affected and Cleanup Action Taken.*

Fire was confined to the compressor unit.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Ed Hasely		Approved by District Supervisor:  For: CP	
Title: Sr Environmental Engineer		Approval Date: 10-7-09	Expiration Date:
E-mail Address: ed.hasely@energen.com		Conditions of Approval:	
Date: 9/24/09 Phone: 505-324-4131 / 505-330-3584(cell)		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

Incident# 11 RND 0928129142