UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

AIG 30 2010

	Sundry Notices and Report	rts on wells			
					on Field Office
			Bure	eau53f L	and ease number
1	Type of Well			6.	SF - 078917 If Indian, All. or
1.	GAS			υ.	Tribe Name
			•		
				7.	Unit Agreement Name
2.	Name of Operator	#D 43/17			San Juan 29-5 Unit
	CONOCOPHILLIPS CON	IPANY		- 8.	Well Name & Number
3.	Address & Phone No. of Opera	itor		- 0.	San Juan 29-5 Unit 100
	.				
	PO Box 4289, Farmington, NM	87499 (505) 326-9700		9.	API Well No.
-				_	30-039-22534
4.	Location of Well, Footage, Sec.	, T, R, M			30-037-44334
					Field and Pool
	Course Huite C (CMANIE) 1902) ENIV 0, 1142) EEU Continue 25 Taan Deni Naadas				Blanco MV/Gobernador P
	Surf: Unit G (SWNE), 1885' FNL & 1165' FEL, Section 25, T29N, R5W, NMPM				County and State
					Rio Arriba Co., NM
12.		of Action			
12.			E OF NOTICE, REPORT, O Change of Plans		Other – Water shut off for
12.	Type of Submission Type X Notice of Intent	of Action Abandonment Recompletion	Change of Plans New Construction		
	Type of Submission Type	of Action Abandonment Recompletion Plugging	Change of Plans New Construction Non-Routine Fracturing		Other – Water shut off for
	Type of Submission Type X Notice of Intent	of Action Abandonment Recompletion	Change of Plans New Construction		Other – Water shut off for
- 13. Co	Type of Submission Type X Notice of Intent Subsequent Report	of Action Abandonment Recompletion Plugging Casing Repair Altering Casing ed Operations rform flow test, isolate water	Change of Plans New Construction Non-Routine Fracturing Water Shut off Conversion to Injection	<u>x</u>	Other – Water shut off for producing water zone
13. Co Pro	Type of Submission X Notice of Intent Subsequent Report Final Abandonment Describe Proposed or Complete nocoPhillips wishes to pull tbg, per ocedure and well bore schematic. I hereby certify that the foregound of the proposed or Complete nocoPhillips wishes to pull tbg, per ocedure and well bore schematic.	Abandonment Recompletion Plugging Casing Repair Altering Casing ed Operations rform flow test, isolate water ing is true and correct. Jamie Good	Change of Plans New Construction Non-Routine Fracturing Water Shut off Conversion to Injection	X 	Other – Water shut off for producing water zone Dessary per attached RCVD SEP 8 '10 OIL CONS. DIV. DIST. 3
13. Co Pro	Type of Submission X Notice of Intent Subsequent Report Final Abandonment Describe Proposed or Complete nocoPhillips wishes to pull tbg, per ocedure and well bore schematic. I hereby certify that the foregound its space for Federal or State Office.	Abandonment Recompletion Plugging Casing Repair Altering Casing ed Operations rform flow test, isolate water ing is true and correct. Jamie Good	Change of Plans New Construction Non-Routine Fracturing Water Shut off Conversion to Injection er source and replace any bad ju	X 	Other – Water shut off for producing water zone Dessary per attached RCVD SEP 8 '10 OIL CONS. DIV. DIST. 3
13. Co Pro	Type of Submission X Notice of Intent Subsequent Report Final Abandonment Describe Proposed or Complete nocoPhillips wishes to pull tbg, per ocedure and well bore schematic. I hereby certify that the foregound of the proposed or Complete nocoPhillips wishes to pull tbg, per ocedure and well bore schematic.	Abandonment Recompletion Plugging Casing Repair Altering Casing ed Operations rform flow test, isolate water ing is true and correct. Jamie Good et use tephen Mason Title	Change of Plans New Construction Non-Routine Fracturing Water Shut off Conversion to Injection er source and replace any bad ju	X 	Other – Water shut off for producing water zone essary per attached RCVD SEP 8 '10 OIL CONS. DIV. DIST. 3 Date08/30/2010

ConocoPhillips SAN JUAN 29-5 UNIT 100 Expense - Water Shut Off

Lat 36° 41' 55.141" N

Long 107° 18' 21.24" W

PROCEDURE

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations. Test rig anchors prior to moving in rig.
- 2. MIRU work over rig. Check casing, tubing, and bradenhead pressures and record them in Wellview.
- 3. RU blow lines from casing valves and begin blowing down casing pressure. Kill well with 2% KCl, if necessary.
- 4. ND wellhead and NU BOPE. PU and remove tubing hanger and tag for fill, adding additional joints as needed (tubing currently landed @ 5810', PBTD @ 6118') . Record fill depth in Wellview.
- 5. TOOH with tubing (details below).

Number	Description		
169	2-3/8" Tubing joints		
1	2-3/8" pup joint (2.1') 2-3/8" tubing joint (30') 2-3/8" F nipple (ID 1.78")		
1	2-3/8" tubing joint (30')		
1	2-3/8" F nipple (ID 1.78")		
1	2-3/8" Mule shoe guide		

Use Tuboscope Unit to inspect tubing and record findings in Wellview. Make note of corrosion or scale. LD and replace any bad joints. If needed, contact Rig Superintendent or engineer for acid, volume, concentration, and displacement volume.

NOTE: In the last remedial perfromed in **5/6/2010**, the RBP was set at 5568' above MV perfs and the tubing was set at 3833' below PC perfs. Start air, unload 55 bbls of water from the well, then a flow test was run for 2 hrs. Hr1: 4.5 bbls, Hr2: 1.75 Next day **5/7/2010**. star air unload 22 bbls of water from 3833'. Dry up to light mist. Release RBB from 5568' In **5/10/2010**. Blow around PBTD w/ 1100 CFM air, flow test 4 hrs. 1st hr: 13.5 bbls of water. 2dn hr: 13.0 bbls of water. 3rd hr: 11.0 bbls of water and 4th hr: 11.0 bbls of water. Based on this flow test it means the water source is MV.

- 6. TIH with RBP and Packer, set the RBP 50 ' above top MV perfs at 5560', set packer and test RBP to 500 psi for 10 min, unset the packer and perform flow test for 6 hrs. If the water source is isolated proceed to install a CIBP at 5560'. Notify Production Engineer water rate. **NOTE: Inform regulatory agency 24 hrs before perform a squeez, install CIBP to isolate water source.**
- 7. TIH with tubing using Tubing Drift Procedure. (detail below).

Recommended

Tubing Drift ID:	1.901"
Land Tubing At:	3795'
Land F-Nipple At:	3794'

Number	Description
1	2-3/8" Mule shoe guide
1	2-3/8" F nipple (ID 1.78")
1	2-3/8" Tubing joint (31')
1	2-3/8" Marker joint (4.1')
118	2-3/8" tubing joints

- 8. If there is an air package on location, skip to the next step. Run standing valve on shear tool, load tubing, and pressure test to 500#. Monitor pressure for 15 mins, and make a swab run to remove the fluid from the tubing. Retrieve standing valve.
- 9. ND BOPE, NU Wellhead. Pressure test tubing slowly with an air package as follows: pump 3 bbls pad, drop steel ball, pressure tubing up to 500 psi, and bypass air. Monitor pressure for 15 mins., then complete the operation by pumping off the expendable check. Note in Wellview the pressure in which the check pumped off. Notify the MSO that the well is ready to be turned over to Production Operations. Make swab run to kick-off the well, if necessary, then RDMO.

Tubing Drift Check

Procedure

- 1. Set flow control in tubing. With air, on location, use expendable check. With no air on location, use wire line plug.
- 2. RU drift tool to a minimum 70' line. Drift tool will have an OD of at least the API drift specification of 1.901" for the 2 3/8",4.7# tubing, and will be at least 15" long. The tool will not weigh more than 10# and will have an ID bore the length of the tool, so fluids may be pumped through the tool if it becomes stuck.
- 3. Drop the tool into the tubing string and retrieve it after every 2 joints of tubing ran in hole. If any resistance to the tool movement is noticed, going in or out, that joint will be replaced.
- 4. In order to stimulate the plunger lift operation, all equipment must be kept clean and free of debris.

The drift tool should be measured with calipers before each job, to ensure the OD is the correct size for the tubing being checked. The maximum allowable wear of the tool is .003".

