

Submit 3 Copies To Appropriate District Office
 District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 1301 W. Grand Ave., Artesia, NM 88210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Jun 19, 2008

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-045-11325
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator Burlington Resources Oil Gas Company LP		6. State Oil & Gas Lease No.
3. Address of Operator P.O. Box 4289, Farmington, NM 87499-4289		7. Lease Name or Unit Agreement Name Allison Unit
4. Well Location Unit Letter E : 1750 feet from the North line and 990 feet from the West line Section 20 Township 32N Range 6W NMPM San Juan County		8. Well Number 10
11. Elevation (Show whether DR, RKB, RT, GR, etc.) ' GR		9. OGRID Number 14538
10. Pool name or Wildcat Blanco Mesaverde		12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPL <input type="checkbox"/> DOWNHOLE COMMINGLE <input type="checkbox"/>		SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> P AND A <input type="checkbox"/> CASING/CEMENT JOB <input type="checkbox"/>	
OTHER: <u>Bradenhead Repair</u> <input checked="" type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Burlington Resources requests permission to repair the BH on the subject well per the attached procedure and current wellbore schematic. The subject well is being repaired in reference to RBDMS KGR1104054915.

Submit CBL & discuss Remediation

Spud Date: Rig Released Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Crystal Tafoya* TITLE Staff Regulatory Technician DATE 4/12/11

Type or print name Crystal Tafoya E-mail address: crystal.tafoya@conocophillips.com PHONE: 505-326-9837

For State Use Only
 APPROVED BY: *Monica Kuehling* TITLE Deputy Oil & Gas Inspector, District #3 DATE APR 20 2011
 Conditions of Approval (if any):



PC

ConocoPhillips
ALLISON UNIT 10
Expense - Repair Bradenhead
Lat 36° 58' 5.844" N Long 107° 29' 14.604" W

PROCEDURE

1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations. Test rig anchors prior to moving in rig.
2. MIRU work over rig. Check casing, tubing, and bradenhead pressures and record them in Wellview.
3. RU blow lines from casing valves and begin blowing down casing pressure. Kill well with 2% KCl, if necessary.
4. ND wellhead and NU BOPE. PU and remove tubing hanger and tag for fill, adding additional joints as needed (tubing currently landed @ 5766', PBTD @ 5813'). Record fill depth in Wellview.
5. TOOH with tubing (details below).

Number	Description
193	2 3/8" Tubing joints
1	2 3/8" Seat nipple (1.780" ID)
1	2 3/8" Tubing Joint
1	2 3/8" Expendable Check with Mule Shoe

Use Tuboscope Unit to inspect tubing and record findings in Wellview. **Make note of corrosion, scale, or paraffin and save a sample for further analysis.** LD and replace any bad joints. If needed, contact Rig Superintendent or engineer for acid, volume, concentration, and displacement volume.

6. PU RBP and packer. TIH and set the RBP at 4378' (40' above top perforation). PUH, set packer, and pressure test RBP. Release packer and load hole. Close pipe rams.
7. POOH with packer. RU wireline and run CBL and Casing Inspection Log tools. Notify Production Egnineer and Rig Superintendent of logging results.
8. Remove tubing head and inspect secondary seals. If no seal is found, contact wellhead vendor to repair wellhead. NU tubing head and close bradenhead. Keep shut in and monitor pressure.
9. Pressure test the 5 1/2" casing to 550 psi for 30 minutes for MIT. Monitor the bradenhead for any communication. If the casing does not test, notify Rig Superintendent and Production Engineer for instructions.
10. Use tubing to cleanout fluid to prevent fallback onto formation. Release RBP and TOOH. LD RBP.
11. If fill is tagged, PU bailer and CO to PBTD (5813'). If fill is too hard or too much to bail, utilize the air package. Save a sample of the fill and contact engineer for further analysis. TOOH. LD tubing bailer (if applicable). If fill could not be CO to PBTD, please call Production Engineer to inform how much fill was left and confirm/adjust landing depth.
12. TIH with tubing using Tubing Drift Procedure. (detail below).

Recommended	
Tubing Drift ID:	1.901"
Land Tubing At:	5791'
Land F-Nipple At:	7408'

Number	Description
1	2 3/8" Mule Shoe/Expendable Check
1	2-3/8" F-Nipple (1.78" ID)
1	2-3/8" Tubing Joint
1	2-3/8" Pup Joint (4')
192	2-3/8" Tubing Joints
XX	2-3/8" Pup Joints as needed
1	2-3/8" Tubing Joint

13. If there is an air package on location, skip to the next step. Run standing valve on shear tool, load tubing, and pressure test to 500 psi. Monitor pressure for 15 mins, and make a swab run to remove the fluid from the tubing. Retrieve standing valve.
14. ND BOPE, NU Wellhead. Pressure test tubing slowly with an air package as follows: pump 3 bbls pad, drop steel ball, pressure tubing up to 500 psi, and bypass air. Monitor pressure for 15 mins., then complete the operation by pumping off the expendable check. Note in Wellview the pressure in which the check pumped off. Notify the MSO that the well is ready to be turned over to Production Operations. Make swab run to kick-off the well, if necessary, then RDMO.

Tubing Drift Check

Procedure

1. Set flow control in tubing. With air, on location, use expendable check. With no air on location, use wire line plug.
2. RU drift tool to a minimum 70' line. Drift tool will have an OD of at least the API drift specification of 1.901" for the 2 3/8", 4.7# tubing, and will be at least 15" long. The tool will not weigh more than 10# and will have an ID bore the length of the tool, so fluids may be pumped through the tool if it becomes stuck.
3. Drop the tool into the tubing string and retrieve it after every 2 joints of tubing ran in hole. If any resistance to the tool movement is noticed, going in or out, that joint will be replaced.
4. In order to stimulate the plunger lift operation, all equipment must be kept clean and free of debris.

The drift tool should be measured with calipers before each job, to ensure the OD is the correct size for the tubing being checked. The maximum allowable wear of the tool is .003".

Current Schematic

ConocoPhillips

Well Name: ALLISON UNIT #10

API/ UWI 3004511325	Service Legal Location E-020-032N-006W	Field Name BASIN DAKOTA (PRODUCED GAS)	License No.	State/Province NEW MEXICO	Well Configuration Type Edit
Ground Elevation (ft) 6,530.00	Original KB/RT Elevation (ft) 6,540.00	KB-Ground Distance (ft) 10.00	KB-Casing Flange Distance (ft) 6,540.00	KB-Tubing Hanger Distance (ft) 6,540.00	

Well Config: - Original Hole, 4/4/2011 10:14:29 AM

