

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division

Sundry Notices and Reports on Wells

1. Type of Well OIL	API # (assigned by OCD) 30-031-05385
	5. Lease Number Fee
	6. State Oil & Gas Lease #
2. Name of Operator Geo Engineering	7. Lease Name/Unit Name Santa Fe Pacific I
	8. Well No. #8
3. Address & Phone No. of Operator P.O.Box 2966 Santa Fe, NM 87505	9. Pool Name or Wildcat
4. Location of Well, Footage, Sec., T, R, M Sec. 29 T-20-N, R-9-W, NMPM, McKinley County Unit A, 5 $\frac{1}{2}$ FNL and 1130' FEL	10. Elevation:

Type of Submission

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment

Type of Action

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other -

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut off

☐ Conversion to Injection

13. Describe Proposed or Completed Operations

A-Plus Well Service, contractor, plugged and abandoned said well according to the attached Daily Report.

This work was completed under State of New Mexico Contract No. 98-521.25-059

RECEIVED
MAR 13 1998

SIGNATURE

William F. Clark
William F. Clark

Contractor

OIL CON. DIV.

DIST. 3

March 4, 1998

(This space for State Use)

Approved by

John Robinson

DEPUTY OIL & GAS INSPECTOR, DIST. #3

Title

Date

MAR 13 1998

Daily Report

A - PLUS WELL SERVICE

P.O. BOX 1979 • FARMINGTON, NM 87499

505-325-2627 • FAX (505) 325-1211

Rig No 6-7

Date 2/23/98

Well No. Sante Fe Pacific I #8 Location Sec 29-20N - 9W Company Geo Engineering

FROM	TO	DESCRIPTION OF OPERATION
2/23/98		
11:15		move to Well Run WH to 3' dug out 2" Found it to be 2" Flow Line started digging Around Loc. Approx 4' Away from Flowline Found well it was Full of dirt dig out Approx 2' of dirt Then Tie PT on Well Pressured up to 500 PSI Found Sucker Run work it down Approx 20' Tie on PT & Pump down Well w/ 4 BBL. Pressured up to 500 PSI started Bleeding off Then Pump 5 BBL. at 400 PSI at 1BPM Run WH to 386 Tag.
1PM		Pump down 2" csg w/ 4 BBL. at 350 PSI at 1BPM Plug #2. Mix 12 SX start to displace it to 300'
1:15		Pump 2 BBL. Lockup. PSI at 800 Holding. Bleed down
1:15		Run WH to 41' tag wouldn't go any deeper.
1:30		Perf 1 Hole at 35' w/ 1 1/16 Biwire shot
1:30		Plug #2 Pump 2 BBL water. got circulation Behind 2" csg. Mix 16 SX cement Pump down 2" got 1 BBL good cement Returns shut Well IN Wash PT Install
2PM		Dry Hole marker.

Fuel & Motor Oil _____ Water Hauled _____

Rental Equipment _____ Cement Retainers _____

Cementing Plug #1 12.5v Plug #2 16.5v

Wireline Perf 1 H₂O at 35' w/ 1 1/16 Bi wire shot