

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division

Sundry Notices and Reports on Wells

1. Type of Well
OIL

RECEIVED
MAR 13 1998

2. Name of Operator
Geo Engineering

OIL CON. DIV.
DIST. 3

3. Address & Phone No. of Operator
P. O. Box 2966
Santa Fe, NM 87505

4. Location of Well, Footage, Sec., T, R, M
Sec. 29 T-20-N, R-9-W, NMPM, McKinley County
Unit B, 160' FNL and 2135' FEL

API # (assigned by OCD)
30-031-20397

5. Lease Number
Fee

6. State Oil & Gas Lease #

7. Lease Name/Unit Name
Santa Fe Pacific

8. Well No.
#35

9. Pool Name or Wildcat

10. Elevation:

Type of Submission

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment

Type of Action

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other -

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut off

☐ Conversion to Injection

13. Describe Proposed or Completed Operations

A-Plus Well Service, contractor, plugged and abandoned said well according to the attached Daily Report.

This work was completed under State of New Mexico Contract No. 98-521.25-059.

SIGNATURE William F. Clark Contractor
William F. Clark

March 4, 1998

(This space for State Use)

Approved by Johnny Robinson

DEPUTY OIL & GAS INSPECTOR, DIST. #3
Title

Date MAR 13 1998

Daily Report

A - PLUS WELL SERVICE

P.O. BOX 1979 • FARMINGTON, NM 87499
505-325-2627 • FAX (505) 325-1211

Rig No 6-7

Date 2/13/98

Well No Sante Fe Pacific #35 Location (B) 29-20N-9W Company Geo Engineering

FROM	TO	DESCRIPTION OF OPERATION
2/13/98		
9AM	9:30	Move to Well set up PT + WL Truck.
9:30	10:AM	Took 36" Pipe winch. + started Turning 2" pipe in top of well work Free & Pull out 7' of 2" pipe That was Bent up Remove 4 1/2 - 5" swage
10AM	10:30AM	Run WL to 435' ^{1" 19} Pull out of Hole
10:30	10:45	Tie in to top of 5" csg. + Pump down csg. into open Hole from (428 - 440') Pump 10 BBL at 500PSI AT 1 BPM
10:45	11:15	Plug #1 Mix 52 SX class B at 15.6# Pump down Csg. Displace to 30' shut well In w/ 500PSI
11:15	12:15	WOC. Open well standing Full
12:15	12:30	Perf 2 Holes at 30' w/ 2 1/8 Biwire shot
12:30	12:45	Pump down 5" csg. + out perf w/ 5 BBL at 0 PSI No circulation Behind csg.
12:45	1:15PM	Plug #2 mix 20 SX at 15.6# cement Pump down 5" csg. + out perf at 30' shut well In wash up PT Open well standing Full Set Dry Hole Marker. move to SFP #20

Fuel & Motor Oil _____ Water Hauled _____

Rental Equipment _____ Cement Retainers _____

Cementing Plug #1 52 sv Plug #2 20 sv

Wireline 2-2¹⁰ Biwire shot at 30 FT