

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division

Sundry Notices and Reports on Wells

1. Type of Well
OIL

RECEIVED
MAR 13 1998

2. Name of Operator
Geo Engineering

OIL CON. DIV.
DIST. 3

3. Address & Phone No. of Operator
P. O. Box 2966
Santa Fe, NM 87505

4. Location of Well, Footage, Sec., T, R, M
Sec. 20 T-20-N, R-9-W, NMPM, McKinley County
Unit O, 275' FSL and 2450' FEL
2510

API # (assigned by OCD)
30-031-20426
5. Lease Number
Fee
6. State Oil & Gas Lease #
7. Lease Name/Unit Name
Santa Fe Pacific
8. Well No.
#38
9. Pool Name or Wildcat
10. Elevation:

Type of Submission

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment

Type of Action

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other -

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut off

☐ Conversion to Injection

13. Describe Proposed or Completed Operations

A-Plus Well Service, contractor, plugged and abandoned said well according to the attached Daily Report.

This work was completed under State of New Mexico Contract No. 98-521.25-059.

SIGNATURE William F. Clark Contractor

March 4, 1998

(This space for State Use)

Approved by Johnny Robinson Title

DEPUTY OIL & GAS INSPECTOR, DIST. #3

Date MAR 13 1998

Daily Report

A - PLUS WELL SERVICE

P.O. BOX 1979 • FARMINGTON, NM 87499
505-325-2627 • FAX (505) 325-1211

Rig No 6-7Date 2/6/98Well No Santa Fe Pacific #36 Location Sec 20 T20N R9W Company Geo Engineering

FROM	TO	DESCRIPTION OF OPERATION
2/6/98		
12:00 PM	1 PM	Run WL in Well to 460' + Tag.
2/26/98		
8:30 AM	9 AM	Move to Well set up Cement Equipment
9 AM		Tie in to 5" csg Pump in to Well w/10 BBL. AT 300 PSI
	9:30	1 1/2 BPM
9:30		Plug #1 Mix 27 sx AT 15.4" Pump in to open Hole
	9:45 AM	Disp to 300' Shut Well In w/ 200 PSI WOC
9:45		WOC Run WL to 323' Tag Plug #1 Pull up + Perf
	10:45	2 Hole AT 300' w/ 2- 2 1/2 Biwire shd
10:45	11 AM	Pump in to Perf w/10 BBL. AT 100 PSI 2 BPM
11 AM		Plug #2 Mix 39 sx cement Displace to 30' shut Well in w/
	11:15	400 PSI
11:15		Perf 2 Hole AT 30' Pump in to Perf AT 30' w/2 BBL get
		Circulation Behind 5" csg. Plug #3 Mix 15 sx cement Pump down
		5 csg get 1/4 BBL cement Returns Shut Well In Washup PT
	12 NOON	Install Dry Hole Marker move off

Fuel & Motor Oil _____ Water Hauled _____

Rental Equipment _____ Cement Retainers _____

Cementing Plug #1 27 sx Plug #2 39 sx Plug #3 15 sx

Wireline Perf 2 Hole w/2 1/2 Biwire AT 300' Perf 2 Hole w/2 1/2 Biwire AT 30'