Form 9-331 (May 1963)

## UNITED STATES SUBMIT IN TRIPLICATE (Other instructions on reverse side) Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

LOGICAL	SURVEY		NM-7250

				6.	IF INDIAN, ALLOTTE	OR TRIBE NAME			
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals.)  1.  OIL  WE'LL   GAS  WELL   OTHER					N/A				
					7. UNIT AGREEMENT NAME				
					N/A 8. FARM OR LEASE NAME				
2. NAME OF OPERATOR									
Basin Fuels, Inc.					Easter Flats				
3. ADDRESS OF OPERA		Plda Farminaton	New Mexico 87401	"	1				
152 Petroleum Center Bldg, Farmington, New Mexico 8/401  4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*  See also space 17 below.)  At surface  330' FEL & 2310' FNL					). FIELD AND POOL, O	R WILDCAT			
					Wildcat				
					11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA				
					SURVEI OR AREA	·			
000 122 0	330 TEE & 2310 THE					Sec 12, T20N, R6W			
14. PERMIT NO.		15. ELEVATIONS (Show who	ether DF, RT, GR, etc.)	12	COUNTY OR PARISH	L .			
		6794 GR			McKinley	New Mexic			
16.	Charle A	naronrieto Boy To India	rate Nature of Notice Repo	rt or Othe	er Data	4			
20.	Circle , (ppiophare Dox to measure that the circle of the					QUENT REPORT OF:			
	NOTICE OF INTE	NTION TO:	,		REFORT VE	<del></del>			
TEST WATER SHU	T-OFF	PULL OR ALTER CASING	WATER SHUT-OFF		REPAIRING !	<u> </u>			
FRACTURE TREAT		MULTIPLE COMPLETE	FRACTURE TREATMEN	<del>-^</del>	ALTERING C	<u> </u>			
SHOOT OR ACIDIZE	·	ABANDON*	SHOOTING OR ACIDIZ	ING	ABANDONME	NT-			
REPAIR WELL		CHANGE PLANS	(Other)(Nore: Report	results of	multiple completion	on Well			
(Other)		un impose (Cleanly state all n	Completion or ertinent details, and give pertinence locations and measured and tru		n Report and Log for				
8-2-76	2832-36,	2806-2810, and 27	nit - ran CCL & CBL. 194-2800 feet with tw	o jets	per foot.	.ookout			
8-3-76	750 gallo	n 15% MCA. Swab		perfora	tions with				
8-4-76	Swab 2.6 BFWPH with trace oil.								
8-5-76	Pull tubing. Set cast iron bridge plug at 2735'. Perforate Menefee 2304-10 with two jets per foot. Run tubing. Swab test.								
8-6-76	Acidize p	erforations 2304-	·10 with 500 gallons	15% MCA	<ol> <li>Swab test</li> </ol>				
8-7-76	Set cas	it iron bridg	je						
		285'. Perforate	1 2250-6	60'. Run tub	oing.				
	Swab test								
8-8-76	Shut down	- W - C		)	1050 60 with	- 11 <u>-</u> 1			
8-9-76	Pull tubi	ng. Frac Menetee	perforations 2232-3	so and a	(250-60 WITH	4			
	14,000 ga	110NS 1% KUL Wate	er containing 30# per	thing Live	Swab test.				
0 10 76	100 mesn	and 12,000# 20-40	)- mesh sand. Run t	ip ing.	Swan cest.	V			
8-10-76	Run pump	roduction equipme	nt /	The state of the s					
8-11 thru 8-24-76	secong p	roduction equipme							
0-24-70			A 16	776 <b>l</b>					
_	7		SEP 2 4 "	-0M.	•				
18. I hereby certify the	at the foregoing	is true and eothect	SEP 2 CON CONT.	3	0.00	76			
SIGNED_	//////////////////////////////////////	k TITLE	Adant \ U'		DATE 9-20	)-76			
(This space for F	ederal or State of	fice use)							
APPROVED BY _		TITLE	]		DATE	,			
CONDITIONS OF	APPROVAL, IF	ANY:							