Form 3160-5 November 1983) Formerly 9-331)

UNITED STATES DEPARTMENT OF THE INTERIOR SUBMIT IN TRIPLICATE* (Other instructions on reverse side)

Form approved. Budget Bureau No. 1004-0135 Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

MM	1953	

BUREAU OF LAND MANAGEMENT

	SUNDRY NOTICES AND REPORTS ON WELLS	
(Do not	t use this form for proposals to drill or to deepen or plug back to a different red Use "APPLICATION FOR PERMIT—" for such proposals.)	Bervoir.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

UNIT	AGREEMENT	NAME

8. FARM OR LEASE NAME

Federal 15

9. WBLL NO.

2 H

1:55 GAS WELL X OTHER WELL

NAME OF OPERATOR

Meriron Oil & Gas Corporation

3. ADDRESS OF OPERATOR

P. O. Box 840, Farmington, New mexico 87499

LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.) At surface

10. FIELD AND POOL, OR WILDCAT

Papers Wash Entrada 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 15, T19N, R5W 12. COUNTY OR PARISH | 13. STATE

15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6,617' KB 6604 6L

Χ.

McKinley

NM

14. PERMIT NO

TEST WATER SHUT-OFF

FRACTURE TREAT

REPAIR WELL

SHOOT OR ACIDIZE

16

1,980' FNL and 990' FWL

Check Appropriate Box To Indicate Nature of Notice, Report, o NOTICE OF INTENTION TO

PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON CHANGE PLANS

WATER SHUT

6 1990 ALTERING CASING

SHOOTING OR ACIDIZING (Other)

competion on Well er)
Norr: Report test
Completion or Reco port and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent details, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) nent to this work.

Merrion requests permission to conduct remedial cementation on the 4-1/2" liner.

During primary cementation procedures an open hole inflatable packer was not inflated and due to failure of a drain sleeve, cement equalized inside and out of 4-1/2" liner. After liner cleanout our swab tests of Entrada show high water cut. We suspect the Morrison could be the culprit and proposed to cement as follows:

- Perf 2 squeeze holes a 5,060' K3 \pm and 2 squeeze holes a 4,830' KB \pm . 1.
- Set drillable bridge plug $0.5,180 \pm .$
- Set cement retainer a 5,050' KB ±. 3.
- Establish circulation under retainer through squeeze holes to upper squeeze holes. 4.
- Cement with ≈ 30 sx class "G" cement. 5.
- Drill out and run bond log to Evaluate. (Schematic attached) ó.

(Verbal okay received from Steve Mason February 27, 1990)

I hereby certiff that the foregoing is true and corn	rect	
SIGNED II	TITLE Operations Manager	DATE MAR ^{7/} 1990
The space for Federal or State office use)		Approved
APPROVED BY	TITLE	Toge for w
CONDITIONS OF APPROVAL, IF ANY: BLM - 5	The state of the s	Chief, Branch of Mineral Resources
Pitco - 1 Aviva, Inc 1	*See Instructions on Reverse Side	Parmington Resource Area

