

SUNDRY NOTICES AND REPORTS ON WELLS

1. oil well ☒ gas well ☐ other ☐

2. NAME OF OPERATOR

Cities Service Company

3. ADDRESS OF OPERATOR

Box 1919, Midland, Texas 79702

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 330' FNL & 1650' FEL

AT TOP PROD. INTERVAL: Same as above

AT TOTAL DEPTH: Same as above

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,
REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☒

(other) _____

100

SUBSEQUENT REPORT OF

PO
RECEIVED
OCT 15 1982
(NOTES: Report results of multiple change on Form 230.)
U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.
DIST. 3

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

OTD 5460' Sandstone, OPBTD 5438'. It is proposed to plug and abandon this well in the following manner:

1. MIRU pulling unit. POOH w/rods. NU BOP. POOH w/2-7/8" tbg.
 2. RU wireline. RIH w/5-1/2" gauge ring to approx. 5100'. RIH w/CIBP & set at approx. 5125'. Dump 35' cmt (5 sx) on CIBP. RD wireline.
 3. RIH w/open ended tbg to approx. 4200'. Circ hole w/9.2#/gal mud laden fluid. Spot 12 sx C1 B neat cmtplug from approx. 4200-4100' (100' across top of Dakota zone).
 4. Pull tbg to approx 3080'. Spot 25 sx C1 B neat cmt plug from approx. ~~3080-2880'~~ (200').
 5. Pull tbg to approx. 550'. Spot 12 sx C1 B neat cmt plug from approx. 550-450' (100').
- (SEE REVERSE SIDE)

Subsurface Safety Valve: Manu. and Type

Set @ 100 Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Reg.Opr.Mgr.-Prod

DATE _____

October 13, 1982

APPROVED BY
CONDITIONS C

APPROVED, 19 JAN 1982

TITLE

DATE _____

AS AMENDED

For **JAMES F. SIMS**
DISTRICT ENGINEER

NMOCC

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

GPO : 1976 O - 214-149

6. Pull tbg to approx. 255'. ~~12' ext (100') C1 B neat emt plug 50' above and 50' below 8-5/8" csg shoe @ 205'. RU to 2-7/8" tbg.~~ ~~Establish injection rate.~~ Spot 12' sx cmt 50' above and 50' below 8-5/8" csg shoe @ 205'. 50' to surface.
7. POOH w/tbg. Cut of WH. Spot 6' sx C1 B neat surface plug approx. 30' to surface.
8. Install 4" dry marker 4' above and 6' below ground level to designate a P&A location. Clear location.