

**GILA EXPLORATION CO INC
HOGAN STATE #2, B-16-18N-12W**

Downhole Conditions & Equipment:

8 5/8 " @ 42' with 30 sacks.

7 7/8" hole to 1195'.

5 1/2" 15.5# casing @ 1193' cemented to surface w/200 sacks 65/35 POZ with 3% gel, 10% calseal and 12 1/2# gilsonite/sack.

Perforations 1144-1147 w/4 SPF.

2 3/8" tubing @ 1086'.

Division Approved Plugging Program

1. Pull tubing (may be used as work string if OK).
2. Go in hole with tubing to PBTD @ 1166' and set a cement plug 1166' - 1016' inside 5 1/2" casing.
3. Pull out of hole to 800' and reverse out tubing. WOC 4 hours and tag cement. If plug is in place, go to step 4. If not, fill to 1016'.
4. Pull out of hole to 150 and circulate cement to surface up 5 1/2" casing.
5. Set marker, fill pits, clean and level location.

GILA EXPLORATION INC.
HOGAN STATE #2, B-16-18N-12W
McKINLEY COUNTY
WILDCAT

