

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-039-05077
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. NA
7. Lease Name or Unit Agreement Name Florence Millenbaugh
8. Well No. #1
9. Pool name or Wildcat South Blanco Pictured Cliffs

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	2. Name of Operator EOG (New Mexico) Inc.
3. Address of Operator 621 17th Street, Suite 1800, Den, CO 80293	4. Well Location Unit Letter B : 990 Feet From The north Line and 1650 Feet From The east Line Section 18 Township 23N Range 1W NMPM Rio Arriba County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 7402 DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Operator requests approval to plug and abandon the subject well per attached procedure.

RECEIVED
OCT 16 1995
OIL CON. DIV.
DIST. 3

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE	Will Hardin	TITLE Consultant	DATE 10-12-95
TYPE OR PRINT NAME		(303) 293-9999	TELEPHONE NO.

(This space for State Use)

APPROVED BY ORIGINAL SIGNED BY ERNIE BUSCH DEPUTY OIL & GAS INSPECTOR, DIST. #3 OCT 18 1995

CONDITIONS OF APPROVAL, IF ANY:
* Notify OGD in time to witness

PLUG AND ABANDONMENT PROCEDURE

10-6-95

Florence Millenbaugh #1 (PC)
NE, Sec. 18, T23N, R1W
Rio Arriba County, New Mexico

Note: All cement volumes use 100% excess outside pipe and 50' excess inside pipe. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures.

1. Install and test rig anchors. Prepare blow pit. Comply to all NMOCD, BLM and EOG safety rules and regulations.
2. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. NU relief line to flow back tank. Blow well down; kill with water as necessary. ND wellhead and NU BOP and stripping head; test BOP.
3. PU 2" tubing workstring and RIH with open ended tubing. Tag CIBP at 3006' or as deep as possible.
4. **Plug #1 (Fruitland, Kirtland and Ojo Alamo tops, 3006' - 2746')**: Pump 20 bbls water down tubing. Mix 24 sxs Class B cement and spot a balanced plug from the CIBP to over the Ojo Alamo top. While WOC, PU 4-1/2" casing scraper or wireline gauge ring and round-trip to 1520'. RIH and tag cement. Pull above cement and load well with water; circulate casing clean. Pressure test casing to 500#. POH with tubing.
5. **Plug #2 (Nacimiento top, 1570' - 1470')**: Perforate 3 or 4 squeeze holes at 1570'. Establish rate into squeeze holes if casing tested. PU 4-1/2" cement retainer and RIH; set at 1520'. Pressure test tubing to 1000#. Establish rate into squeeze holes. Mix and pump 51 sxs Class B cement, squeeze 39 sxs cement outside casing and leave 12 sxs cement inside casing to cover Nacimiento top. POH and LD tubing and setting tool.
6. **Plug #3 (Surface)**: Perforate 2 or 3 squeeze holes at 199'. Establish circulation out bradenhead valve. Mix approximately 56 sxs Class B cement and pump down 4-1/2" casing, circulate good cement out bradenhead valve. Shut in well and WOC.
7. ND BOP and cut off well head below surface casing flange. Install P&A marker with cement to comply with regulations. RD, MOL and cut off anchors. Restore location.

Florence Millenbaugh #1

CURRENT

Blanco Pictured Cliffs South

NE Section 18, T-23-N, R-1-W, Rio Arriba County, NM

Today's Date: 10/6/95

Spud: 8/14/59

Completed: 8/18/59


Nacimiento @ 1520'

Ojo Alamo @ 2796'

Kirtland @ 2879'

Fruitland @ 2985'

Pictured Cliffs @ 3045'



Florence Millenbaugh #1

Proposed P & A

Blanco Pictured Cliffs South
NE Section 18, T-23-N, R-1-W, Rio Arriba County, NM

Today's Date: 10/6/95
Spud: 8/14/59
Completed: 8/18/59

