Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED				
Budget	Bureau	No.	1004-0	135
Evn	res M	arch	31 100	1

Lease Designation and Serial No. NMSF-078359

SUNDRY NOTICES Do not use this form for proposals to di Use "APPLICATION FO	6. If Indian, Allottee or Tribe Name	
SUBMIT	7. If Unit or CA, Agreement Designation	
1. Type of Well Oil Gas Other Well Other Well Other Other Other Other		8. Well Name and No. Vandengurg \$11 9. API Well No. 30-039-05089 10. Field and Pool, or Exploratory Area Lybrook Gallup 11. County or Parish, State Rio Arriba, New Mexico
12. CHECK APPROPRIATE BOX	(s) TO INDICATE NATURE OF NOTICE, REPO	RT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent Subsequent Report Final Abandonment Notice	Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well
		Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Propose to plug and abandon this well per the attached procedure.

OIL CON. DIV. DIST. 3

4. I hereby certify that the foregoing is true and correct Signed Me Mylich	_{_ Title} Regulatory Analyst	Date9/8/94
(This space for Federal or State office (see) Approved by Conditions of approval, if any:	Title	APPROVED

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United Staj or representations as to any matter within its jurisdiction.


Vandenburg 11-#1 (Gi) SW, Sec. 11, T23N, R7W Rio Amba County, New Mexico

PLUG AND ABANDONMENT PROCEDURE:

(All cement volumes use 100% excess outside pipe and 50' inside)

- 1. Install and/or test rig anchors. Prepare blow pit. Comply to all NMOCD, BLM and Bannon safety rules and regulations.
- 2. MOL and RUSU. Blow well down; kill with water if necessary; an 8.3 ppg wellbore fluid exceeds the exposed reservoirs' pressure. ND wellhead and NU BOP and stripping head; test BOP. POH and tally 2-3/8" tubing, visually inspect.
- 4. Plug #1 (Gallup perfs): RIH with open ended tubing to PBTD; pump 20 bbls water down tubing. Mix 92 sxs Class B cement and spot balanced plug over Gallup perfs from 5770' to 5362'. POH to 4000' and WOC. RIH and tag cement. POH above top of cement. Load well with water and circulate clean. Pressure test casing to 500#. POH with tubing.
- 5. Plug #2 (Mesaverde top): Perforate 4 squeeze holes at 3630'. Establish rate into squeeze holes if casing tested. PU 5-1/2" cement retainer and RIH; set at 3580'. Pressure test tubing to 1000#; establish rate into squeeze holes. With retainer at 3580' mix and spot 47 sxs Class B cement, squeeze 30 sxs outside casing from 3630' to 3530' through squeeze holes and leave 17 sxs inside casing. POH with tubing.
- 6. Plug #3 (PC & Ft tops): Pressure test casing to 500#. Perforate 4 squeeze holes at 2124'. Establish rate into squeeze holes if casing tested. PU 5-1/2" cement retainer and RIH; set at 2080'. Establish rate into squeeze holes. With retainer at 2080' mix and spot 118 sxs Class B cement, squeeze 81 sxs outside casing from 2124' to 1848' through squeeze holes above Fruitland and leave 37 sxs inside casing. POH with tubing.
- 7. Plug #4 (Kt & OA tops): Pressure test casing to 500#. Perforate 4 squeeze holes at 1615'. Establish rate into squeeze holes if casing tested. PU 5-1/2" cement retainer and RIH; set at 1565'. Establish rate into squeeze holes. With retainer at 1565' mix and spot 97 sxs Class B cement, squeeze 66 sxs outside casing from 1615' to 1390' through squeeze holes above Ojo Alamo and leave 31 sxs inside casing. POH and LD tubing and setting tool.
- 8. Plug #5 (Surface) Perforate 2 holes at 280'. Establish circulation out bradenhead valve. Mix approximately 80 sxs Class B cement and pump down 5-1/2" casing, circulate good cement out bradenhead valve. Shut in well and WOC.
- 9. ND BOP and cut off well head below surface casing flange and install P&A marker to BLM specs. RD and MOL. Cut off anchors. Restore location per BLM stipulations.

BANNON ENERGY INC.



BANNON ENERGY INC.

