Form 3160-5 (November 1983) (Formerly 9: 331)	DEPARTM	INITED STATES ENT OF THE IN	Terior 🕷	BMIT IN THIPLE ther instructions se side)	CATE!	Coim approved, Ridget Harena No Expires August 31 BE DENIGNATION AN	1084	
(no not me thi	NDRY NOTIC	CES AND REPOR	RTS ON W	ELLS different recorvoir.	6. IP	1-6682 Indiam, allottee of	TRIBB HAME	
OIL X GAR WELL	OTHER	,				MAR THEMESEOA T		
BCO, Inc.		<u> </u>			8. FAR	M OR LEASE HAME		
8. ADDRESS OF OPERATO					Fe 9. was	deral "B"		
4. LOCATION OF WELL (See also apace 17 bel At surface		Fe, New Mexico	87501 th any State requ	irements.*	1	amito Gallur		
1830' FNL - 1840' FEL Sec 34 T23N R7W						URVAT OR ARMA	ARD	
16. PERMIT NO. 15. ELEVATIONS (Show whether pr. st. gr. stc.) GR: 6936						Sec 34 T23N R7W 12. COUNTY OF PARISE 18. STATE Sandoval. New Mexico		
16.	Check Appr	opriate Box To Indica	ate Nature of	Notice, Report,	or Other Do	ria Ne	M MGX1CO	
NOTICE OF INTENTION TO:								
PRACTURE TREAT RHOOT OR ACIDIES REPAIR WELL. (Other)	I NEI	L OR ALTER CASING TIPLE COMPLETE NDON* NOE PIANE	22.5 22.0	CTURE TREATMENT COTING OR ACIDISMO		BUPARRING WELL ALTERING CABING AFANDONMENT		
17. DESCRIME PROPUSED OF Proposed work. If nent to this work.)				nd give perilbent : easured und true :	dates, including rertical depths		starting any access perti-	
10/13/92	Discus	sed inten- cordance Memo	hón	to rep	air l	vell		
	in acc	condance	with	Harry	L. E	sigbee's		
	(HLB)	Memo	to Fil	e date	d Oc	tober		
EGEIVE	13,199	2 with k	ien T	own s end	of Bu	reau of		
ECEIVE	pland	Managen	ent.	Copy of	mem	o pue	RE(
OCT 2 2 1992	two ex	hibits atta	iched.			6 A		
DIL CON. DIV.	Intend	to proceed.	with r	repair C	October	AMII: 38	(ED	
	19, 1992	•				. 		
·• ·								
18. I hereby certify that the Signan Elegal	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	. ,	Presiden	t	DA	- 10/13/g	7.2	
(This space for Peders	u or State office us	e)			ACCI	-NIFD EUS WE	<u> JUNU</u>	
CONDITIONS OF APP	PROVAL, LF ANY:	TITLE _			DA:	ÖTT 4 1997		
		*See Instructi	ons on Reven	e Side	rátiki. av	NGTON HESOURCE	- ARen	

10.7 000.0M CH.Ft

Title 18 1! S.F. Service 1001 makes it a crime for any ca

HLB Memo to File Federal B-2 October 13, 1992

The B-2 started making around a barrel a day of fresh drinkable water. The pump failed. It was determined to mill out the 10 foot casing patch. This patch was installed because of small hole in casing that prevented piston operation. The patch was approximately 315 feet from the surface.

Tubing was pulled. Reason for pump failure was hole in tubing. No evidence of drilling mud was observed. We obtained a Homco mill to mill out patch. Upon reaching the bottom of the patch the mill could not be raised. It remained stuck after use of drill pipe and jars.

We obtained washover pipe and a Homco mill to reduce diameter of stuck mill. It was recovered but could not go below this point.

Went in hole with bottom joint of 2 7/8 and then with 2 3/8 tubing. Could not get to within 2 1/2 feet of bottom of previously stuck mill. Went in hole with impression block. Copy of tracing faxed to this office attached. Exhibit 1. Interpeted impression block to establish casing had parted below patch. Verified by visual view when light in casing.

October 13th went in hole with Homco tapered mill pushed junk (patch residue) to bottom.

Cementing information. This well initially had a two stage cement job. Top of second stage is approximately 1350. I determined this top on 10/14/76 on running cement log in hole. I made notes on depths at that time. Exhibit 2. Attached find copy of cement log as we went in hole. Showing top of 2nd stage at 1350. Also shows D.V. tool slightly below 3700 feet. Detailed log with depths confirmed by Gamma Ray Neutron log of 10/14/76 correlated with open hole logs of 10/3/78 shows D.V. tool at 3734 to 3437.

1st Stage did not circulate. 140 feet below 3437 (3437 to 3577 has no cement) See cement log of 10/14/76 correlated for depths Gamma Ray Neutron Log of 10/14/76). Zone from PBTD 5390 to 3577 has cement.

Proposed program: Cover perforations with sand. Run 2 7/8 tubing to below 4150 and above 4200. Run sufficient cement to circulate to surface. When cement at surface close braden head valve and force sufficient cement in casing break at approximately 325 to fill casing above 1350 with cement.

We pushed patch residue to below 5300 feet. All perforations are open.

