

400-100

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDY NOTICES AND REPORTS ON WELLS

For information to drill or to deepen or plug back to a different depth
APPLY IN FOR PERMIT for such purposes.

1. DATE	2. NAME OF OPERATOR	3. ADDRESS OF OPERATOR	4. LOCATION OF WELL	5. PERMIT NO.
10-10-69	ARMY CORPS OF ENGINEERS	PC BOX 227	at section line 18, Texas 76321	16-10000
6. NUMBER OF HOURS		7. TIME OF DRILLING		
Re-drill space 17 hrs		10 AM - 1 PM		
8. DEPTH OF WELL		9. DEPTH OF WELL		
At surface		66' from the North line of Sec. 12, 18 3W		
		2850' from the East line of sec. 33, 18 3W		
10. DRAINS				
11. PERMIT NO.				
12. OTHER ORGANIZATION OR STATE				

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Document									
13. NOTICE OR INSTRUCTION TO:					SUBSEQUENT REPORT OR:				
<input type="checkbox"/> FIRST FILTER SPACER	<input type="checkbox"/> FILTER OR SPACER CAVING	<input type="checkbox"/> RE	<input type="checkbox"/> WATER SHUTOFF	<input type="checkbox"/> RE	14. REPORTS OR RECORDS:				
<input type="checkbox"/> PRODUCTIVE	<input type="checkbox"/> MULTIPLE COMPLETION	<input type="checkbox"/> RE	<input type="checkbox"/> FRACTURE TREATMENT	<input type="checkbox"/> RE	15. TESTS:				
<input type="checkbox"/> SHOT IN SPACER	<input type="checkbox"/> ABANDONED	<input type="checkbox"/> RE	<input type="checkbox"/> PRODUCTION ASSESSMENT	<input type="checkbox"/> RE	16. DRILLING:				
<input type="checkbox"/> SPACER	<input type="checkbox"/> CHAMFER ROCK	<input type="checkbox"/> RE	<input type="checkbox"/> OTHER: RE REPORT	<input type="checkbox"/> RE	17. DRILLING:				
18. INSPECTOR OR OWNER OR CONTRACTOR: (Name, address, and copy of permit issued) (If multiple completion, give subsurface location and measured and true vertical depths for all completions and connections to this work)									

SEE BACK SIDE

ILLEGIBLE

18. I hereby certify that the foregoing is true and correct.

SIGNED


FILE - CARRIER

(This space for Federal or State date)

APPROVED BY
CONDITIONS OF APPROVAL IF ANY

TITLE

U. S. GEOLOGICAL SURVEY
DURANGO, COLO.



See Instructions on Reverse Side

It

20141201-46
НОВОЕ МЯСО 100% (БАКАЛ)

SURVEY NOTICES AND REPORTS ON MELTS

1940-1941. The first year of the new program was a success.


1960 - annual rainfall estimate for 1961
is 15.5 inches. It will drop off about 1964.
At 15.5 inches it will drop off again.

6-20-94

Group A: Assigning a box of matches. Note: Report to Other Date

卷之三

• 194 民國廿年(1931)正月 謝子雲



三九五

U.S. GOVERNMENT PRINTING OFFICE 1914 2. 20-1000000-1

卷之三

卷之三

Table 2. Summary of morphometric data

Instructions

General: This form is designed for submitting proposals to perform certain well operations and reports of such operations when conducted, as both land or offshore and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, pursuant to its applicable State law and regulations. Any necessary special instructions concerning the use of this form, and the number of copies to be submitted, particularly with regard to form, area, or regional procedures and practices, either are shown below or will be learned by, or may be obtained from, the local Federal and/or State office.

Note 4: If there are no applicable laws or regulations, locations as Federal or Indian land should be described in accordance with Federal requirements. Consult form.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as required by local Federal and/or State offices and constituents involved, or by contract or otherwise, (top and bottom) and method of placement of cement plug, and/or method of purging of any casing, liner or tubing pulled and the depth to top of any left in the hole, method of capping top of well, and other details.

The complete reworking and testing of the Ann #10 well has been completed for this year. The accomplishment of this re-work and testing has been to get the well back on the ping and produce oil, and to prove to our satisfaction that our extensive engineering and research program was right in its conclusions.

The Oil is present in this formation and from tests it is all grades, but because of the bentonitic condition of the formation plus the lack of pressure to move the oil type is #1 place, a natural gasohole or removing the oil might be impossible.

We are now preparing to formulate a new approach to this problem, at first it was thought that a regular water flood was the answer to the production problem, but because of the bentonitic condition that would completely seal off the formation under normal waterflood conditions, we are in the process of working out a formula involving a massive (pusher) injection flood along with an Ionic chemical. The profile of the sand formation being from 4 very low (thin streaks) permeability to a very encouraging 257 m. thickness taking the use of perches to accomplish procedure from the standpoint of an even pressure flood and avoiding the possibility of an early breakthrough of water, thereby bypassing most of the oil in place.

The Ionic chemical will neutralise the bentonite in the formations thus allowing the oil to flow freely through the sand to the borehole. This method has been tried successfully and we feel that once we get the program under way we also, will give a successful conclusion.

Because of the nature of the weather, from December through February, we are not able to apply the treatment of the wells at this time, but a complete outline of our program will become apparent as we begin to refine our procedure for the re-working of certain wells and the proposal of drilling, right away as soon as possible.



ILLEGIBLE

To prevent damages after my stay I have been asked to instruct the authorities to release all
valuables left at the hotel and get them back again. This has been done.

difference although not so exact as it was at first, but now it is very great. The difference between the two methods is, however, still considerable, and it is evident that the method of calculating the mean error of the observations is not correct.

and the other side of the vessel was cut out, so that the two sides were joined together by a single row of rivets.

the same time, the author has been compelled to make some changes in his original plan, and has omitted the first part of the book, which was to contain a history of the early days of the colony, and a description of the manners and customs of the Indians.

