Submit 3 Copies To Appropriate District Office State of New Mexico	Form C-103
District I Energy, Minerals and Natural Reso	ources Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 87240 District II	WELL API NO.
81! South First, Artesia, NM 87210 OIL CONSERVATION DIVIS	ION 30-045-22568
District III 2040 South Paghage	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	STATE FEE X
2040 South Pacheco, Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK!	Santa Fe H 20 (17343)
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH, PROPOSALS.)	(1/3/3)
1. Type of Well:	
Oil Well X Gas Well Other Other	
Oil Well X Gas Well Other 2. Name of Operator Synergy Operating LLC	8. Well No
Synergy Operating LLC 3 Address of Operator	3 de 3
3. Address of Operator	9. Pool name or Wildcat
P.O.Box 5513, Farmington, NM 87499 4. Well Location	Snake Eyes Entrada
4. Well Location	and the same of th
Unit Letter H : 2220 feet from the North line	and 000 c c
Total inc	and 990 feet from the East line
Section 20 Township 21N Range	8W NMPM San Juan County
10. Elevation (Show whether DR, RKB, R	T, GR, etc.)
6573' GR	
11. Check Appropriate Box to Indicate Nature of	Notice, Report or Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDI	AL WORK ALTERING CASING
TEMPORARILY ABANDON	NCE DRILLING OPNS. PLUG AND . X
PULL OR ALTER CASING MULTIPLE CASING	☐ ABANDONMENT ☐
	TEAT AND
CASING	TEST AND
COMPLETION CEMENT	TEST AND
COMPLETION CEMENT OTHER: OTHER:	TEST AND STORE STO
OTHER: OTHER: OTHER: OTHER: OTHER:	TEST AND JOB
OTHER: OTHER:	TEST AND JOB
OTHER: OTHER:	TEST AND JOB
OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: 12. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompilation. 7/15/99:	TEST AND JOB
OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: 12. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompilation. 7/15/99: MI RU Key Energy rig #8. TOOH, laying down, 13-Jts 3-1/2" tbg, incomplete. 7/16/99:	TEST AND JOB ils, and give pertinent dates, including estimated date s: Attach wellbore diagram of proposed completion
OTHER: It will be a submersible numb. RIH wild 1/2" gives:	ils, and give pertinent dates, including estimated date s: Attach wellbore diagram of proposed completion
OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: 12. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompilation. 7/15/99: MI RU Key Energy rig #8. TOOH, laying down, 13-Jts 3-1/2" tbg, incomplete. 7/16/99: Cont. TOOH, laying down 3-1/2" tbg & submersible pump. RIH w/ 4-1/2" guage apprv'd change in procedure) RIH w/ 4-1/2" CIBP on W/L & set @ 5550' TI	ils, and give pertinent dates, including estimated date s: Attach wellbore diagram of proposed completion
OTHER: OTHER: OTHER: OTHER: OTHER: 12. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompilation. 7/15/99: MI RU Key Energy rig #8. TOOH, laying down, 13-Jts 3-1/2" tbg, incomplete. 7/16/99: Cont. TOOH, laying down 3-1/2" tbg & submersible pump. RIH w/ 4-1/2" guage apprv'd change in procedure) RIH w/ 4-1/2" CIBP on W/L & set @ 5550'. TI 7/19/99:	ils, and give pertinent dates, including estimated date s: Attach wellbore diagram of proposed completion ering on W/L & tagged fill @ 5580°. (NMOCD H, picking up 2-3/8" tbg & tagged CIBP @ 5550°.
OTHER: OTHER: OTHER: OTHER: 12. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompilation. 7/15/99: MI RU Key Energy rig #8. TOOH, laying down, 13-Jts 3-1/2" tbg, incomplete. 7/16/99: Cont. TOOH, laying down 3-1/2" tbg & submersible pump. RIH w/ 4-1/2" guage apprv'd change in procedure) RIH w/ 4-1/2" CIBP on W/L & set @ 5550'. TI 7/19/99: Circ hole clean w/ fresh water. Pressure Test Csg to 500# for 15-minutes held Others.	ils, and give pertinent dates, including estimated date s: Attach wellbore diagram of proposed completion ering on W/L & tagged fill @ 5580°. (NMOCD H, picking up 2-3/8" tbg & tagged CIBP @ 5550°.
OTHER: OTHER: OTHER: OTHER: OTHER: 12. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompilation. 7/15/99: MI RU Key Energy rig #8. TOOH, laying down, 13-Jts 3-1/2" tbg, incomplete. 7/16/99: Cont. TOOH, laying down 3-1/2" tbg & submersible pump. RIH w/ 4-1/2" guage apprv'd change in procedure) RIH w/ 4-1/2" CIBP on W/L & set @ 5550'. TI 7/19/99: Circ hole clean w/ fresh water. Pressure Test Csg to 500# for 15-minutes, held OI Plug #1: Spot 12-sxs Cl 'B" cmt from 5550-5400' inside 7" Csg. PUH to 5201'	ils, and give pertinent dates, including estimated date s: Attach wellbore diagram of proposed completion ering on W/L & tagged fill @ 5580°. (NMOCD H, picking up 2-3/8" tbg & tagged CIBP @ 5550°.
OTHER: In the starting any proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompilation. 7/15/99: MI RU Key Energy rig #8. TOOH, laying down, 13-Jts 3-1/2" tbg, incomplete. 7/16/99: Cont. TOOH, laying down 3-1/2" tbg & submersible pump. RIH w/ 4-1/2" guage apprv'd change in procedure) RIH w/ 4-1/2" CIBP on W/L & set @ 5550'. TI 7/19/99: Circ hole clean w/ fresh water. Pressure Test Csg to 500# for 15-minutes, held Ol Plug #1: Spot 12-sxs Cl 'B" cmt from 5550-5400' inside 7" Csg. PUH to 5201'. Plug #2: Spot 23-sxs Cl 'B' cmt from 5201-5051' inside 7" Csg. PUH to 4633'.	ils, and give pertinent dates, including estimated date s: Attach wellbore diagram of proposed completion ering on W/L & tagged fill @ 5580°. (NMOCD H, picking up 2-3/8" tbg & tagged CIBP @ 5550°.
OTHER: In the starting any proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompilation. 7/15/99: MI RU Key Energy rig #8. TOOH, laying down, 13-Jts 3-1/2" tbg, incomplete. 7/16/99: Cont. TOOH, laying down 3-1/2" tbg & submersible pump. RIH w/ 4-1/2" guage apprv'd change in procedure) RIH w/ 4-1/2" CIBP on W/L & set @ 5550'. TI 7/19/99: Circ hole clean w/ fresh water. Pressure Test Csg to 500# for 15-minutes, held Of Plug #1: Spot 12-sxs Cl 'B" cmt from 5550-5400' inside 7" Csg. PUH to 5201'. Plug #2: Spot 23-sxs Cl 'B' cmt from 5201-5051' inside 7" Csg. PUH to 4635'. Plug #3: Spot 28-sxs Cl 'B' cmt from 4635-4485' inside 7" Csg. PUH to 3386'.	ils, and give pertinent dates, including estimated date s: Attach wellbore diagram of proposed completion ering on W/L & tagged fill @ 5580°. (NMOCD H, picking up 2-3/8" tbg & tagged CIBP @ 5550°.
OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: 12. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompilation. 7/15/99: MI RU Key Energy rig #8. TOOH, laying down, 13-Jts 3-1/2" tbg, incomplete. 7/16/99: Cont. TOOH, laying down 3-1/2" tbg & submersible pump. RIH w/ 4-1/2" guage apprv'd change in procedure) RIH w/ 4-1/2" CIBP on W/L & set @ 5550'. TI 7/19/99: Circ hole clean w/ fresh water. Pressure Test Csg to 500# for 15-minutes, held Ol Plug #1: Spot 12-sxs Cl 'B" cmt from 5550-5400' inside 7" Csg. PUH to 5201'. Plug #2: Spot 23-sxs Cl 'B' cmt from 5201-5051' inside 7" Csg. PUH to 4635'. Plug #3: Spot 28-sxs Cl 'B' cmt from 4635-4485' inside 7" Csg. PUH to 935'. Plug #4: Spot 28-sxs Cl 'B' cmt from 3386-3236' inside 7" Csg. PUH to 935'.	ils, and give pertinent dates, including estimated date s: Attach wellbore diagram of proposed completion ering on W/L & tagged fill @ 5580°. (NMOCD H, picking up 2-3/8" tbg & tagged CIBP @ 5550°.
OTHER: OTHER: OTHER: OTHER: OTHER: 12. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompilation. 7/15/99: MI RU Key Energy rig #8. TOOH, laying down, 13-Jts 3-1/2" tbg, incomplete. 7/16/99: Cont. TOOH, laying down 3-1/2" tbg & submersible pump. RIH w/ 4-1/2" guage apprv'd change in procedure) RIH w/ 4-1/2" CIBP on W/L & set @ 5550'. TI 7/19/99: Circ hole clean w/ fresh water. Pressure Test Csg to 500# for 15-minutes, held Of Plug #1: Spot 12-sxs Cl 'B" cmt from 5550-5400' inside 7" Csg. PUH to 5201'. Plug #2: Spot 23-sxs Cl 'B' cmt from 5201-5051' inside 7" Csg. PUH to 4635'. Plug #3: Spot 28-sxs Cl 'B' cmt from 4635-4485' inside 7" Csg. PUH to 935'. Plug #4: Spot 28-sxs Cl 'B' cmt from 3386-3236' inside 7" Csg. PUH to 935'. Plug #5: Spot 28-sxs Cl 'B' cmt from 935-785' inside 7" Csg. PUH to 255'.	TEST AND JOB ils, and give pertinent dates, including estimated date s: Attach wellbore diagram of proposed completion e ring on W/L & tagged fill @ 5580'. (NMOCD H, picking up 2-3/8" tbg & tagged CIBP @ 5550'.
OTHER: OTHER:	TEST AND JOB ils, and give pertinent dates, including estimated date so: Attach wellbore diagram of proposed completion ering on W/L & tagged fill @ 5580'. (NMOCD H, picking up 2-3/8" tbg & tagged CIBP @ 5550'.
OTHER: OTHER: OTHER: OTHER: OTHER: Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompilation. 7/15/99: MI RU Key Energy rig #8. TOOH, laying down, 13-Jts 3-1/2" tbg, incomplete. 7/16/99: Cont. TOOH, laying down 3-1/2" tbg & submersible pump. RIH w/ 4-1/2" guage apprv'd change in procedure) RIH w/ 4-1/2" CIBP on W/L & set @ 5550'. TI 7/19/99: Circ hole clean w/ fresh water. Pressure Test Csg to 500# for 15-minutes, held Ol Plug #1: Spot 12-sxs Cl 'B" cmt from 5550-5400' inside 7" Csg. PUH to 5201'. Plug #2: Spot 23-sxs Cl 'B' cmt from 5201-5051' inside 7" Csg. PUH to 4635'. Plug #3: Spot 28-sxs Cl 'B' cmt from 4635-4485' inside 7" Csg. PUH to 935'. Plug #4: Spot 28-sxs Cl 'B' cmt from 3386-3236' inside 7" Csg. PUH to 935'. Plug #5: Spot 28-sxs Cl 'B' cmt from 935-785' inside 7" Csg. PUH to 255'. Plug #6: Circ 48-sxs Cl 'B' cmt from 255'-Surface inside 7" 23# Csg. TOOH. N Level. Cmt level at surface. RD Key Energy rig #8. Weld on & Install permanen	TEST AND JOB ills, and give pertinent dates, including estimated date so: Attach wellbore diagram of proposed completion e ring on W/L & tagged fill @ 5580'. (NMOCD H, picking up 2-3/8" tbg & tagged CIBP @ 5550'. K. ID BOP. Dig cellar, cut-off WH 3' below Ground t P&A marker.
OTHER: OTHER: OTHER: OTHER: OTHER: Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompilation. 7/15/99: MI RU Key Energy rig #8. TOOH, laying down, 13-Jts 3-1/2" tbg, incomplete. 7/16/99: Cont. TOOH, laying down 3-1/2" tbg & submersible pump. RIH w/ 4-1/2" guage apprv'd change in procedure) RIH w/ 4-1/2" CIBP on W/L & set @ 5550'. TI 7/19/99: Circ hole clean w/ fresh water. Pressure Test Csg to 500# for 15-minutes, held Ol Plug #1: Spot 12-sxs Cl 'B" cmt from 5550-5400' inside 7" Csg. PUH to 5201'. Plug #2: Spot 23-sxs Cl 'B' cmt from 5201-5051' inside 7" Csg. PUH to 4635'. Plug #3: Spot 28-sxs Cl 'B' cmt from 4635-4485' inside 7" Csg. PUH to 935'. Plug #4: Spot 28-sxs Cl 'B' cmt from 3386-3236' inside 7" Csg. PUH to 935'. Plug #5: Spot 28-sxs Cl 'B' cmt from 935-785' inside 7" Csg. PUH to 255'. Plug #6: Circ 48-sxs Cl 'B' cmt from 255'-Surface inside 7" 23# Csg. TOOH. N Level. Cmt level at surface. RD Key Energy rig #8. Weld on & Install permanen	TEST AND JOB ills, and give pertinent dates, including estimated date so: Attach wellbore diagram of proposed completion e ring on W/L & tagged fill @ 5580'. (NMOCD H, picking up 2-3/8" tbg & tagged CIBP @ 5550'. K. ID BOP. Dig cellar, cut-off WH 3' below Ground t P&A marker.
OTHER: OTHER: OTHER: OTHER: 12. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompilation. 7/15/99: MI RU Key Energy rig #8. TOOH, laying down, 13-Jts 3-1/2" tbg, incomplete. 7/16/99: Cont. TOOH, laying down 3-1/2" tbg & submersible pump. RIH w/ 4-1/2" guage apprv'd change in procedure) RIH w/ 4-1/2" CIBP on W/L & set @ 5550'. TI 7/19/99: Circ hole clean w/ fresh water. Pressure Test Csg to 500# for 15-minutes, held Ol Plug #1: Spot 12-sxs Cl 'B' cmt from 5550-5400' inside 7" Csg. PUH to 5201'. Plug #2: Spot 23-sxs Cl 'B' cmt from 5201-5051' inside 7" Csg. PUH to 4635'. Plug #3: Spot 28-sxs Cl 'B' cmt from 4635-4485' inside 7" Csg. PUH to 935'. Plug #4: Spot 28-sxs Cl 'B' cmt from 3386-3236' inside 7" Csg. PUH to 935'. Plug #5: Spot 28-sxs Cl 'B' cmt from 935-785' inside 7" Csg. PUH to 255'. Plug #6: Circ 48-sxs Cl 'B' cmt from 255'-Surface inside 7" 23# Csg. TOOH. N. Level. Cmt level at surface. RD Key Energy rig #8. Weld on & Install permanen.	TEST AND JOB ils, and give pertinent dates, including estimated date so: Attach wellbore diagram of proposed completion ering on W/L & tagged fill @ 5580'. (NMOCD H, picking up 2-3/8" tbg & tagged CIBP @ 5550'. K. ID BOP. Dig cellar, cut-off WH 3' below Ground t P&A marker. nowledge and belief.
OTHER: OTHER: OTHER: OTHER: 12. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompilation. 7/15/99: MI RU Key Energy rig #8. TOOH, laying down, 13-Jts 3-1/2" tbg, incomplete. 7/16/99: Cont. TOOH, laying down 3-1/2" tbg & submersible pump. RIH w/ 4-1/2" guage apprv'd change in procedure) RIH w/ 4-1/2" CIBP on W/L & set @ 5550'. TI 7/19/99: Circ hole clean w/ fresh water. Pressure Test Csg to 500# for 15-minutes, held Ol Plug #1: Spot 12-sxs Cl 'B' cmt from 5550-5400' inside 7" Csg. PUH to 5201'. Plug #2: Spot 23-sxs Cl 'B' cmt from 5201-5051' inside 7" Csg. PUH to 4635'. Plug #3: Spot 28-sxs Cl 'B' cmt from 4635-4485' inside 7" Csg. PUH to 935'. Plug #4: Spot 28-sxs Cl 'B' cmt from 3386-3236' inside 7" Csg. PUH to 935'. Plug #5: Spot 28-sxs Cl 'B' cmt from 935-785' inside 7" Csg. PUH to 255'. Plug #6: Circ 48-sxs Cl 'B' cmt from 255'-Surface inside 7" 23# Csg. TOOH. N. Level. Cmt level at surface. RD Key Energy rig #8. Weld on & Install permanen.	TEST AND JOB ills, and give pertinent dates, including estimated date so: Attach wellbore diagram of proposed completion e ring on W/L & tagged fill @ 5580'. (NMOCD H, picking up 2-3/8" tbg & tagged CIBP @ 5550'. K. ID BOP. Dig cellar, cut-off WH 3' below Ground t P&A marker.
OTHER: OTHER: OTHER: OTHER: 12. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompilation. 7/15/99: MI RU Key Energy rig #8. TOOH, laying down, 13-Jts 3-1/2" tbg, incomplete. 7/16/99: Cont. TOOH, laying down 3-1/2" tbg & submersible pump. RIH w/ 4-1/2" guage apprv'd change in procedure) RIH w/ 4-1/2" CIBP on W/L & set @ 5550'. TI 7/19/99: Circ hole clean w/ fresh water. Pressure Test Csg to 500# for 15-minutes, held Ol Plug #1: Spot 12-sxs Cl 'B' cmt from 5550-5400' inside 7" Csg. PUH to 5201'. Plug #2: Spot 23-sxs Cl 'B' cmt from 5201-5051' inside 7" Csg. PUH to 4635'. Plug #3: Spot 28-sxs Cl 'B' cmt from 4635-4485' inside 7" Csg. PUH to 935'. Plug #4: Spot 28-sxs Cl 'B' cmt from 3386-3236' inside 7" Csg. PUH to 935'. Plug #5: Spot 28-sxs Cl 'B' cmt from 935-785' inside 7" Csg. PUH to 255'. Plug #6: Circ 48-sxs Cl 'B' cmt from 255'-Surface inside 7" 23# Csg. TOOH. N. Level. Cmt level at surface. RD Key Energy rig #8. Weld on & Install permanen.	TEST AND JOB ills, and give pertinent dates, including estimated date so: Attach wellbore diagram of proposed completion ering on W/L & tagged fill @ 5580°. (NMOCD H, picking up 2-3/8" tbg & tagged CIBP @ 5550°. K. ID BOP. Dig cellar, cut-off WH 3° below Ground t P&A marker. nowledge and belief. tions Manager DATE 7/23/99
OTHER: OTHER: OTHER: OTHER: OTHER: Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompilation. 7/15/99: MI RU Key Energy rig #8. TOOH, laying down, 13-Jts 3-1/2" tbg, incomplete. 7/16/99: Cont. TOOH, laying down 3-1/2" tbg & submersible pump. RIH w/ 4-1/2" guage apprv'd change in procedure) RIH w/ 4-1/2" CIBP on W/L & set @ 5550'. TI 7/19/99: Circ hole clean w/ fresh water. Pressure Test Csg to 500# for 15-minutes, held Of Plug #1: Spot 12-sxs Cl 'B" cmt from 5550-5400' inside 7" Csg. PUH to 5201'. Plug #2: Spot 23-sxs Cl 'B' cmt from 5201-5051' inside 7" Csg. PUH to 4635'. Plug #3: Spot 28-sxs Cl 'B' cmt from 4635-4485' inside 7" Csg. PUH to 3386'. Plug #4: Spot 28-sxs Cl 'B' cmt from 3386-3236' inside 7" Csg. PUH to 935'. Plug #5: Spot 28-sxs Cl 'B' cmt from 935-785' inside 7" Csg. PUH to 255'. Plug #6: Circ 48-sxs Cl 'B' cmt from 255'-Surface inside 7" 23# Csg. TOOH. Nevel. Cmt level at surface. RD Key Energy rig #8. Weld on & Install permanen I hereby certify that the information above is true and complete to the best of my k SIGNATURE TITLE Operation of the total complete to the best of my k SIGNATURE	TEST AND JOB ills, and give pertinent dates, including estimated date so: Attach wellbore diagram of proposed completion ering on W/L & tagged fill @ 5580°. (NMOCD H, picking up 2-3/8" tbg & tagged CIBP @ 5550°. K. ID BOP. Dig cellar, cut-off WH 3' below Ground t P&A marker. nowledge and belief.
OTHER: 12. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompilation. 7/15/99: MI RU Key Energy rig #8. TOOH, laying down, 13-Jts 3-1/2" tbg, incomplete. 7/16/99: Cont. TOOH, laying down 3-1/2" tbg & submersible pump. RIH w/ 4-1/2" guage apprv'd change in procedure) RIH w/ 4-1/2" CIBP on W/L & set @ 5550'. TI 7/19/99: Circ hole clean w/ fresh water. Pressure Test Csg to 500# for 15-minutes, held Ol Plug #1: Spot 12-sxs Cl 'B" cmt from 5550-5400' inside 7" Csg. PUH to 5201'. Plug #2: Spot 23-sxs Cl 'B' cmt from 5201-5051' inside 7" Csg. PUH to 4635'. Plug #3: Spot 28-sxs Cl 'B' cmt from 4635-4485' inside 7" Csg. PUH to 3386'. Plug #4: Spot 28-sxs Cl 'B' cmt from 3386-3236' inside 7" Csg. PUH to 935'. Plug #5: Spot 28-sxs Cl 'B' cmt from 935-785' inside 7" Csg. PUH to 255'. Plug #6: Circ 48-sxs Cl 'B' cmt from 255'-Surface inside 7" 23# Csg. TOOH. N. Level. Cmt level at surface. RD Key Energy rig #8. Weld on & Install permanen Type or print name Glen O. Papp (This space for State use)	TEST AND JOB ills, and give pertinent dates, including estimated date so: Attach wellbore diagram of proposed completion ering on W/L & tagged fill @ 5580°. (NMOCD H, picking up 2-3/8" tbg & tagged CIBP @ 5550°. K. ID BOP. Dig cellar, cut-off WH 3° below Ground t P&A marker. nowledge and belief. tions Manager DATE 7/23/99
OTHER: 12. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompilation. 7/15/99: MI RU Key Energy rig #8. TOOH, laying down, 13-Jts 3-1/2" tbg, incomplete. 7/16/99: Cont. TOOH, laying down 3-1/2" tbg & submersible pump. RIH w/ 4-1/2" guage apprv'd change in procedure) RIH w/ 4-1/2" CIBP on W/L & set @ 5550'. TI 7/19/99: Circ hole clean w/ fresh water. Pressure Test Csg to 500# for 15-minutes, held Of Plug #1: Spot 12-sxs Cl 'B' cmt from 5550-5400' inside 7" Csg. PUH to 5201'. Plug #2: Spot 23-sxs Cl 'B' cmt from 5201-5051' inside 7" Csg. PUH to 4635'. Plug #3: Spot 28-sxs Cl 'B' cmt from 4635-4485' inside 7" Csg. PUH to 3386'. Plug #4: Spot 28-sxs Cl 'B' cmt from 3386-3236' inside 7" Csg. PUH to 935'. Plug #5: Spot 28-sxs Cl 'B' cmt from 935-785' inside 7" Csg. PUH to 255'. Plug #6: Circ 48-sxs Cl 'B' cmt from 255'-Surface inside 7" 23# Csg. TOOH. N. Level. Cmt level at surface. RD Key Energy rig #8. Weld on & Install permanen. I hereby certify that the information above is true and complete to the best of my k. SIGNATURE TITLE Operatory.	TEST AND JOB ills, and give pertinent dates, including estimated date so: Attach wellbore diagram of proposed completion ering on W/L & tagged fill @ 5580°. (NMOCD H, picking up 2-3/8" tbg & tagged CIBP @ 5550°. K. ID BOP. Dig cellar, cut-off WH 3° below Ground t P&A marker. nowledge and belief. tions Manager DATE 7/23/99