Form 3160-5 (August 1999)

UNITED STATES

FORM APPROVED OMB NO. 1004-0135

BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					Expires: 1	Expires: November 30, 2000		
					5. Lease Serial No. CONT 360 6. If Indian, Allottee or Tribe Name JICARILLA APACHE			
JAN 2000								
	PLICATE - Other instru	ctions on rev	rse sidel EC	EIVED	7. If Unit or CA/Ag	reement, Name and/or No.		
1. Type of Well Gas Well Oth	DIET BIV			8 Well Name and No. NORTHEAST HAYNES 8				
Name of Operator CONOCO INC.	YOLANDA PEREZO, P. API Well No. E-Mail: yolanda.perezousa.conoco.com 30-039-05437							
3a. Address P. O. BOX 2197, DU 3084 HOUSTON, TX 77252-2197	3b. Phone No. (include area and C. Ph. 281.293.1613 Fx: 281.293.5090			10. Field and Pool, or Exploratory OTERO GALLUP/BASIN DAKOTA				
4. Location of Well (Footage, Sec., T)			11. County or Parish, and State				
Sec 15 T24N R5W SESE 911				RIO ARRIBA COUNTY, NM				
12. CHECK APPI	ROPRIATE BOX(ES) TO	O INDICATE :	NATURE OF	NOTICE, R	EPORT, OR OTH	ER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION							
Notice of Intent ■	☐ Acidize	☐ Deep	en	☐ Production (Start/Resume)		■ Water Shut-Off		
☐ Alter Casing		☐ Fracture Treat		☐ Reclam	ation	□ Well Integrity		
☐ Subsequent Report	Casing Repair		☐ New Construction		olete	□ Other		
☐ Final Abandonment Notice	☐ Change Plans	🔁 Plug	Plug and Abandon		arily Abandon			
	☐ Convert to Injection	☐ Plug I	☐ Plug Back		Disposal			
If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final Abdetermined that the site is ready for fi While attempting to repair brauneconomical to repair well. Oper attached procedure.	k will be performed or provide operations. If the operation repart of the operation repart of the control of th	the Bond No. on sults in a multiple ed only after all re	Tile with BLM/BI completion or rec quirements, inclu	A. Required sultennial in a liding reclamation and it is now	osequent reports shall t new interval, a Form 3 n, have been completed	e filed within 30 days 60-4 shall be filed once		
14. I hereby certify that the foregoing is	Electronic Submission	#9938 verified b NOCO INC., sei			System			
Name(Printed/Typed) YOLANDA	Title COORDINATOR				· · · · · · · · · · · · · · · · · · ·			
Signature (Electronic S	- JOHANG C	2/ 5	Date 01/04/2					
$\overline{}$	THIS SPACE FO	JR FEDERAL	OR STATE	OFFICE U	SE			
Approved By S	£=		Title A Shi	AFM M	ulfi Ros. Date	4 January 2002		
Conditions of approval, if any, are attached certify that the applicant holds legal or equi which would entitle the applicant to condu	itable title to those rights in the		Office A	u FO		•		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

** ORIGINAL ** ORIGINAL ** ORIGINAL ** ORIGINAL ** ORIGINAL **

PLUG AND ABANDONMENT PROCEDURE

1/3/02

NE Haynes #8

Basin Dakota / Gallup 911' FSL and 1033' FWL, Section 15, T24N, R5W Rio Arriba County, New Mexico, API 30-039-05437 Lat: N 36^ 18' 26" / Long: W 107^ 20' 31"

Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures.

All cement will be ASTM Type II, mixed at 15.6 ppg with a 1.18 cf/sx yield.

- Install and test rig anchors. Prepare blow pit. Comply to all NMOCD, BLM and Conoco safety
 rules and regulations. Conduct safety meeting for all personnel on location. MOL and RU
 daylight pulling unit. NU relief line and blow well down; kill with water as necessary. ND wellhead
 and NU BOP and stripping head; test BOP.
- 2. If necessary LD tubing and PU 2-3/8" tubing workstring. Casing scraper has been run to 5600'.
- 3. Plug #1 (Dakota perforations and top, 6832' 6610'): TIH and set a 5-1/2" CR at 6660'. Pressure test tubing to 1000#. Mix and pump 62 sxs cement, squeeze 50 sxs below CR to fill Dakota perforations and then spot 12 sxs cement above retainer. TOH with tubing.
- 4. Plug #2 (Gallup perforations and top, 5860' 5555'): Set 5-1/2" CR at 5605'. Load casing with water and circulate well clean. Pressure test casing to 500#. If casing does not test, then spot or tag subsequent plug as appropriate. Mix and pump 70 sxs cement, squeeze 58 sxs below CR and spot 12 sxs above to fill the Gallup perforations and cover the top. PUH to 3980'.
- 5. Plug #3 (Mesaverde top, 3980' 3880'): Mix 17 sxs cement and spot a balanced plug inside the casing to cover the Mesaverde top. TOH with tubing.
- 6. Plug #4 (Pictured Cliffs and Fruitland tops, 2460' 2250'): Mix and pump 92 sxs cement, squeeze 62 sxs outside casing and spot 30 sxs inside casing to cover the PC and Fruitland tops.
- 7. Plug #5 (Kirtland and Ojo Alamo tops, 2140' 1870'): Mix and pump 117 sxs cement, squeeze 80 sxs outside casing and leave 37 sxs inside casing to cover the Ojo Alamo. TOH and LD tubing.
- 8. Plug #6 (Nacimiento top and 8-5/8" casing shoe, 580' Surface): Perforate 3 HSC holes at 580'. Establish circulation to surface with water. Mix approximately 250 sxs cement and pump down the 5-1/2" casing to circulate good cement out bradenhead. Shut in well and WOC.
- ND BOP and cut off wellhead below surface casing flange. Install P&A marker with cement to comply with regulations. RD, MOL and cut off anchors. Restore location per BLM stipulations.

NE Haynes #8

Proposed P&A

Basin Dakota / Gallup

SE, Section 15, T-24-N, R-5-W, Rio Arriba County, NM

Lat: N 36^ 18' 26" / Long: W 107^ 20' 31'

Today's Date: 1/3/02

Spud: 8/23/63

Completed: 9/9/63

Elevation: 6659' GL 6670' KB

12-1/4" hole

Nacimiento @ 530'

Ojo Alamo @ 1920'

Kirtland @ 2090'

Fruitland @ 2300'


Pictured Cliffs @ 2410'

Mesaverde @ 3930'

Gallup @ 5650'

Dakota @ 6780'

7-7/8" hole



TD 8127'

8-5/8" 32.4#, K-55 Csg set @ 315' Cmt with 200 sxs (Circulated to Surface)

Plug #6: 580' - Surface Cmt with 250 sxs

Perforate @ 580'

Plug #5: 2140' - 1870'

Cmt with 117 sxs, 80 sxs outside casing and 37 sxs inside.

Perforate @ 2140'

Cmt Rt @ 2090'

Cmt Rt @ 2410'

Plug #4: 2460' - 2250' Cmt with 92 sxs, 62 sxs outside casing And 30 sxs inside.

Perforate @ 2460'

TOC @ 2620'

Plug #3: 3980' - 3880' Cmt with 17 sxs

DV Tool @ 4741' Cmt with 450 sxs (490 cf)

Cmt Rt @ 5605'

Plug #2: 5860' - 5555' Cmt with 70 sxs,

58 sxs below CR

Gallup Perforations: 5655' - 5860'

and 12 sxs above.

Cmt Rt at 6660'

Baker Model "D" Packer @ 6667'

Dakota Perforations: Cmt with 62 sxs, 6784' -- 6832'

Plug #1: 6832' - 6610' 50 sxs below CR

and 12 sxs above.

5-1/2" 15.5#, K-55 Casing set @ 6900' Cmt with 150 sxs (177 cf)

7.483 94/93

NE Haynes #8

Basin Dakota / Gallup

SE, Section 15, T-24-N, R-5-W, Rio Arriba County, NM API #30-039-05437

Lat: N 36^ 18' 26" / Long: W 107^ 20' 31'

