

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Compass Exploration, Inc.			Address 1645 Court Place, Denver 2, Colorado			
Lease State	Well No. 2-16	Unit Letter L	Section 16	Township 24 North	Range 7 West	
Date Work Performed	Pool Escrito-Gallup			County Rio Arriba		

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations ☐ Casing Test and Cement Job ☐ Other (Explain):
☐ Plugging ☒ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Approximately 275 MLO to recover.**Well completed and remedial action taken as follows:**

10/29/60 Initial frac of well: 18,000 20/40 sd. and 18,000 gals LSR crude - BHP 30000, AIR 22.6 BPM/30000, banded out on frac:
11/3/60 Cleaned out and. to 6001' PBTB - Swab lead oil back @ 25 BOPD rate.
12/13/60 Put well on pump - Rate 10 bbls. now oil per day.
(See Addendum)

RECEIVED
FEB 17 1961
OIL CON
DIST

Witnessed by A. S. Johnson	Position Retrol. Engineer	Company Compass Exploration, Inc.
--------------------------------------	-------------------------------------	---

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev. 7063'	T D 6150'	P B T D 6001	Producing Interval 5005-5032	Completion Date -
Tubing Diameter 2-3/8"	Tubing Depth 5000'	Oil String Diameter 4-1/2"	Oil String Depth 6140'	
Perforated Interval(s) 5005-5032				
Open Hole Interval -		Producing Formation(s) Gallup- (Lower)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by <i>[Signature]</i>	Name <i>P. J. Farrelly</i>
Title Supervisor Dist. # 3	Position <i>Chief Geologist</i>
Date FEB 17 1961	Company <i>Compass Exploration, Inc.</i>

1. The first of these is the fact that the
 2. Government has been unable to obtain the
 3. necessary funds to carry out its policy.
 4. The second is the fact that the Government
 5. has been unable to obtain the necessary
 6. funds to carry out its policy.
 7. The third is the fact that the Government
 8. has been unable to obtain the necessary
 9. funds to carry out its policy.
 10. The fourth is the fact that the Government
 11. has been unable to obtain the necessary
 12. funds to carry out its policy.

Addendum:

- 1/13/61** Moved in and rigged up workover rig. Pulled rods, pump, and tubing.
- 1/14** Went back in hole with Dowell abrasi-jet tool on 2" tubing. Loaded hole with oil and then abrasi-jetted notches at 5916' and 5928'. Avg. pumping press. - 4300 psi. Pumping time on each notch - 25 min. Reversed out sand fillup.
- Spotted 500 gallons break down acid opposite pay zone. Came out of hole with tubing.
- Fraced well as follows: 30,000 gal lease crude w/Adomite admix and 30,000# sand. Form. started taking fluid at 2500 psi. Frac press. - 3500 psi at 25 BPM. One Allison broke down during job. Rate fell to 22 BPM. Avg. rate - 24 BPM. ISIP - 1600 psi. 10 min. SIP - 1450 psi. Shut well in after frac.
- 1/15** Bled off remaining pressure. Went in hole open ended with tubing and circulated out sand fillup. Came out of hole, ran production tubing, rods and pump. Nippled up well head and released workover unit.
- 1/16** Placed well on pump.
- Presently swabbing well to recover load oil.

