



PLUGGING PROCEDURE

Federal #31-25

Sec. 25, T25N-R3W

Rio Arriba County, New Mexico

1. Set a cement plug from 3557' - 3457'.
2. Set a cement plug from 3428' - 3328'.
3. Set a cement plug from 3275' - 3175'.
4. Set a cement plug from 3078' - 2978'.
5. Pull out of hole and lay down tubing.
6. Shoot off casing at cement top (approximately 2600').
7. Set a cement plug 50' in and out of cut off pipe.
8. Set a cement plug 50' in and out of surface casing.
9. Set a cement plug from 50' to surface.
10. Put up dry hole marker.
11. Displace all plugs with 9.2 ppg mud.

