		•	
NO. OF COPIES RECEIVED			Form C-103
DISTRIBUTION			Supersedes Old C-102 and C-103
SANTA FE	NEW MEXICO OIL CONS	ERVATION COMMISSION	Effective 1-1-65
FILE			
U.S.G.S.			5a. Indicate Type of Lease
LAND OFFICE			State Fee X
OPERATOR			5. State Oil & Gas Lease No.
SUNDRY (DO NOT USE THIS FORM FOR PROPC) USE "APPLICATION	INDICES AND REPORTS ON S. S TO DRILL OR TO DEEPEN OR PLUG B	WELLS ACK TO A DIFFERENT RESERVOIR. H PROPOSALS.)	
OIL GAS X	THER-		7. Unit Agreement Name
2. Name of Operator			8. Farm or Lease Name
NANCO, INC		•	Locer
3. Address of Operator			9. Well No.
611 Philtower Buildin	us. Tulsa, OK. 74103		#1 10. Field and Pool, or Wildcat
1	7 FEET FROM THE West	LINE AND933FEET FROM	Gavilan
THE North LINE, SECTION	15 TOWNSHIP 25N	RANGE 2W NMPM	
mmmmm	15. Elevation (Show whether	DF, RT, GR, etc.)	12. County
	7355 GL	,,,	Rio Arriba
	<u> </u>	(1) : D	
Check Appropriate Box To Indicate Nature of Notice, Report of Other Data			
NOTICE OF INT	E ITION TO:	SUBSEQUEN'	T REPORT OF:
		ļ <u>-</u>	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OFNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	anneas Doment
		OTHER Completion Pro	ogress Report
OTHER			
18 Describe Described on Completed One	a one (Clearly state all pertinent det	ails and give pertinent dates, including	estimated date of starting any proposed
17. Describe Proposed or Completed Opera ons (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.			
Ran 3663' of 4-1/2" 3 with 50 sacks lite flu pletion procedure, el	-55 11 lb. Casing. The casing to the case of the case	-19-80. Logged to total free stage casing ceme lar. 3. 50 sacks regul sts attached hereto. G mpany. Well is not yet	nt job. 1. Cement lar flush. Com- as contract has
18. I hereby certify that the information a	b e is true and complete to the best	of my knowledge and belief.	DATE 7-15-81
SIGNED	11116		
APPROVED BY Original Sinned by FRA	N. T CHAVE? TITLE	SUPERVISOR DISTRICT # 3	AUG 6 - 1981
	· ····································		

CLIFTON and ASSOCIATES INC.



Registered Professional Engireer

7010 So. Yale, Suite 101 Tulsa, Oklahoma 74136 J.L. (Clif) CLIFTON Off. (918) 496-0480

Res. (918) 299-9741

MACO INC. LOCER #1 Sec 15 - 25M - 2W Rio Arriba Co., W. Nexico

Completion Proceedure

Weld on Bell Tipple and attach Well Head. Move in Double Drum Completion Package. Move in 2 3/8" tubing plus seating nipple, choke, fittings, thread sealant & pressure gauge.

Rig up BOP Run tubing/secting nipple to TD, $3650\pm$ (Mote inspect tubing and run rabbit) Swab down to 1,500' and pull tubing.

Run Bond & Correlation Collar logs. Perforate 2 slots/ft 3534' to 3543' - 14' and 3570' to 3586' - 16'

Casing swab is practical otherwise run tubing & seating nipple to $3475\mbox{{\ }'}$ approx the swab test.

Breakdown perconations using 1,500 gal acid and 30 ball sealers.

Swab test & pill tubing.

Fracture treat down $4\frac{1}{2}$ " casing using 75,000 gal 75 Quality Foam and 75,000 $\#1^{\prime}$ -20 sand.

Flow back to recover load and test well perforate 3510' to 3518' 3528' to 3534' 3552' to 3553' 3562' to 3568'

Test then shut in for pipeline & surface equipment.

* if well is (iving up appreciable gas it may not be necessary to run tubing un il after Frac treatment.

