

Submit 1 Copy to Appropriate District Office

Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 80-039-22495
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name JELLY DOG JERRY
8. Well No. 2
9. Pool name or Wildcat So. Blanco PC

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
 OIL WELL  GAS WELL  OTHER \_\_\_\_\_

2. Name of Operator  
 NASSAU RESOURCES, INC.

3. Address of Operator  
 P O BOX 809, Farmington, NM 87499

4. Well Location  
 Unit Letter G : 1520 Feet From The North Line and 1850 Feet From The East Line

Section 33 Township 24N Range 2W NMPM Rio Arriba County \_\_\_\_\_

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
7148 GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: _____ <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: _____ <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to plug and abandon this well as shown on attached Plug and Abandonment Procedure.

RECEIVED  
JUN - 9 1994  
OIL CON. DIV.  
DIST. 3

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Fran Perrin TITLE Regulatory Liaison DATE 6/9/94

TYPE OR PRINT NAME Fran Perrin Regulatory Liaison TELEPHONE NO. 505 326-7793

(This space for State Use)

APPROVED BY Charles Holton DEPUTY OIL & GAS INSPECTOR, DIST. 3 TITLE \_\_\_\_\_ DATE JUN 9 1994

CONDITIONS OF APPROVAL, IF ANY:  
 WCC A minimum of 4 hours before Pressure Test  
 c.m

May 17, 1994

J. P. McHugh

**Jelly Dog Jerry #2 (PC)  
NE, Sec. 33, T24N, R2W  
Rio Arriba County, New Mexico**

**PLUG AND ABANDONMENT PROCEDURE:**

(All cement volumes use 100% excess outside pipe and 50' inside;  
a 8.3 ppg plugging fluid exceeds the exposed reservoirs' pressure.)

1. Install and/or test rig anchors. Prepare blow pit. Comply to all NMOCD, BLM and McHugh safety rules and regulations.
2. MOL and RUSU. Blow well down; kill with water if necessary. ND wellhead and NU BOP and stripping head; test BOP.
3. POH and tally 1-1/4", 2.4# EUE tubing; visually inspect.
4. **Plug #1 (PC perfs):** RIH with open ended tubing to 3083'; pump 20 bbls of water down tubing. Mix 23 sxs Class B cement and spot balanced plug from 3083' to 2933'. POH to 1000' and WOC. RIH and tag cement; then LD one joint. Load well with water and circulate clean, pressure test casing to 500#.
5. **Plug #2 (Ft, Kt & OA tops):** Mix 28 sxs Class B cement and spot balanced plug from 2933' (or top of cement) to 2615'. POH and LD tubing.
6. **Plug #3 (Surface):** Perforate 2 holes at 189'. Establish circulation out bradenhead. Mix 31 sxs Class B cement and pump down 4-1/2" casing, circulate good cement out bradenhead valve. Shut in well and WOC.
7. ND BOP and cut off wellhead below surface casing flange and install P&A marker to BLM spec. RD and MOL. Cut off anchors.
8. Restore location per surface agreement.