

SUNDRY NOTICES AND REPORTS ON WELLS

1. oil well ☒ gas well ☐ other

2. NAME OF OPERATOR
Chace Oil Company, Inc.

3. ADDRESS OF OPERATOR
313 Washington, SE, Albuquerque, NM 87108

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) Unit "C" - 660 FNL and 1650' FWL
AT SURFACE:
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,
REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>
(other) _____	

SUBSEQUENT REPORT OF:

<input type="checkbox"/>
<input checked="" type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input checked="" type="checkbox"/>
<input type="checkbox"/>

RECEIVED

SEP 01 1982

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

See workover and recompletion report attached.

Subsurface Safety Valve: Manu. and Type

18. I hereby certify that the foregoing is true and correct

SIGNED

hereby certify that the foregoing is true and correct.

S. W. Miller

President

DATE _____

August 30

Ft.

APPROVED BY **ACCEPTED FOR RECORD** TITLE
CONDITIONS OF APPROVAL, IF ANY:

DATE _____

SEP 02 1982

***See Instructions on Reverse Side**

BY FAC FARMINGTON DISTRICT

NMOCC

WORKOVER AND RECOMPLETION JICARILLA 70-10:

7-29-82:

Drill back plug to 6:00 P. M. Circulated hole clean. Out of hole. Tubing twisted off at 5373'.

7-30-82:

Ran 3 5/8" overshot. Got over fish. Pulled off. Pulled out of hole. Ran 3 7/8" mill. Milled 3' of fish. Pulled out of hole. Ran 3 5/8" overshot. Caught fish. Pulled off of fish. Pulled out of hole. 2" piece of tubing in overshot. Ran impression block. Showed slivered tubing. Workover skirted mill. Ran mill. Milled over 5' of tubing. Circulated hole clean.

7-31-82:

Pulled out of hole. Ran 3 5/8" overshot. Pulled off fish. 10,000# over weight. Pulled out of hole with overshot. Had junk in overshot. Ran 3 7/8" mill. Milled over 8½' tubing. Pulled out of hole. Ran 3 7/8" skirted mill. Milled over 3' tubing. Pulled out of hole. Ran 3 3/4" impression block.

8-1-82:

Ran overshot. Caught fish. Pulled and jarred 55000# over the weight. Tried to break circulation. Wait on Brand X to free point. Tool wouldn't go. Ran Newsco endless tubing. Overshot @ 5363'. Couldn't get any lower than 5368'.

8-2-82:

Release overshot. Pulled out of hole. Ran 2 joints of 3 3/4" wash pipe. Had 5' of junk on 1st collar, 2' on 2nd collar. Circulated hole clean. Pulled out of hole. Ran outside cutters. Made cut @ 5413'. Pulled out of hole with cutters and fish. Ran 3 3/4" overshot. Caught fish. Ran 3 point. Tubing free @ 6790'. Cut off @ 6772'. Ran 2 joints wash over pipe, drill collars and tubing.

8-3-82:

Washed over 42'. Pulled out of hole. Ran overshot, jars, drill collar and tubing. Caught fish. Jarred on fish 3 hours. Pulled out of hole. Ran wash over. Washed over 1'. Pulled out of hole. Ran new shoe. Washed over 6'.

8-4-82:

Pulled out of hole. Ran overshot. Caught fish. Jarred 1 hour. Pulled out of hole. Ran outside cutters. Couldn't get over 1st collar. Pulled out of hole. Left cutters in hole. Ran 3 3/4" junk mill. Milling on junk.

8-5-82:

Pulled out of hole. Ran mill #2. Milled on tubing. Made approximately 2½'.

Jicarilla 70-10:

Pulled out of hole. Ran mill #3. Milled 2'. Come out of hole. Ran overshot.

8-7-82:

Drilled down 3' with overshot. COH with tool. WBIW overshot and jars. Latched on to fish. Tried to circulate. Would not circulate through fish. Jarred on fish for 12 hours.

8-8-82:

Came out of hole with overshot and jars, and prepared to run impression block. W. O. Hot Shot truck.

8-9-82:

Ran impression block. Showed Homco overshot sub spinning on cuttings with tbq. in center. W. O. O.

8-10-82:

Decided to abandon fish, and test upper zones, while trying to figure out a method to get fish out of hole. Ran tubing and seating nipple in well. Landed tubing at 6700'.

8-11-82:

Ran rods and hooked up pump. Started pumping. Estimated 10,000 barrels water put in hole.

8-12-82:

Pumping water. Trace of oil.