(June 1990) DEPARTM. BUREAU OF SUNDRY NOTICE Do not use this form for proposals to	NITED STATES ENT OF THE INTERIOR F LAND MANAGEMENT S AND REPORTS ON WELLS drill or to deepen or reentry to a different reservoir. OR PERMIT—" for such proposals	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993  5. Lease Designation and Serial No. NM 03453  6. If Indian, Allottee or Tribe Name NA	
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation	
1. Type of Well  Oil Gas Well Other  2. Name of Operator  EOG (New Mexico) Inc.  3. Address and Telephone No.		NA  8. Well Name and No.  Wasson Federal  9. API Well No.  #2  10. Field and Pool, or Exploratory Area	
17th St., Ste. 1800, Den, CO 80293 (303) 293-9999  Location of Well (Footage: Sec., T., R., M., or Survey Description)  UNit Letter E: 1750' FNL, 1050' FWL  Sec. 26-24N-1W		Blanco Pictured Cliffs  11. County or Parish, State  Rio Arriba, NM	
	X(s) TO INDICATE NATURE OF NOTICE, REPO	RT, OR OTHER DATA	
give subsurface locations and measured and true ve	Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other Call pertinent details, and give pertinent dates, including estimated date of starting rical depths for all markers and zones pertinent to this work.)*  roval to plug & abandon the subject well attached prodedure.		
(This space for Federal or State office use)	in Tide Consultant  Tide Chief, Lands and Mineral Fasources	OCT 2 7 1995	

(8

#### PLUG AND ABANDONMENT PROCEDURE

10-6-95

Wasson Federal #2-26 (PC) NW, Sec. 26, T24N, R1W Rio Arriba County, New Mexico

Note: All cement volumes use 100% excess outside pipe and 50' excess inside pipe. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures.


- 1. Install and test rig anchors. Prepare blow pit. Comply to all NMOCD, BLM and EOG safety rules and regulations.
- MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location.
   NU relief line to flow back tank. Blow well down; kill with water as necessary. ND wellhead and NU BOP and stripping head; test BOP.
- 3. Plug #1 (Fruitland, Kirtland and Ojo Alamo tops, 2835' 2566') PU 2" tubing workstring and RIH with open ended tubing. Tag CIBP at 2881' or as deep as possible. POH to 2835'. Pump 20 bbls water. Mix 24 sxs Class B cement and spot a balanced plug over Ojo Alamo top. RIH and tag cement. Pull above cement and load well with water; circulate casing clean. Pressure test casing to 500#. POH 1837'.
- 4. Plug #2 (Nacimiento top, 1837' 1737'): Mix 12 sxs Class B cement and spot a balanced plug inside casing over the Nacimiento top. POH and LD tubing.
- 5. Plug #3 (Surface): Perforate 2 or 3 holes at 397'. Establish circulation out bradenhead valve. Mix approximately 113 sxs Class B cement and pump down 4-1/2" casing, circulate good cement out bradenhead valve. Shut in well and WOC.
- 6. ND BOP and cut off well head below surface casing flange. Install P&A marker with cement to comply with regulations. RD, MOL and cut off anchors. Restore location.

## Wasson Federal #2-26

#### **CURRENT**

South Blanco Pictured Cliffs

NW Section 26, T-24-N, R-1-W, Rio Arriba County, NM



TD 3050'

# Wasson Federal #2-26

### Proposed P & A

South Blanco Pictured Cliffs

NW Section 26, T-24-N, R-1-W, Rio Arriba County, NM

Today's Date: 10/6/95 Spud: 10/8/81 Completed: 10/11/81

Nacimiento @ 1787

Ojo Alamo @ 2616'

Kirtland @ 2762'

Fruitland @ 2785'

