RECEIVED DEC2 9 1989

RECOMMENDED PLUGGING PROCEDURE

File

F. DAVIS #1 GAL-DK Section 1, T25N-R3W

OIL CON. DIV.

- 1. Test anchors, dig blow pit.
- 2. MIRUSU. Blow well down. TOH with 2-3/8" tubing.
- 3. TIH with 2-3/8" tubing open-ended to 7850' and pump 47 sx (55 ft³) cement to cover Dakota and Greenhorn inside pipe 7850'-8210' plus 75%. Tag cmt
- 4. Pull tubing up to 6950' and pump 13 sx (16 ft³) cement to cover Gallup top 7080'- 6980' inside pipe plus 75%.
- 5. Pull tubing up to 6200' and perf 2 squeeze holes through tubing at 6300'. Pressure up to 1000 PSI.

a. If squeeze holes take fluid, pump 386 sx (456 ft³) cement to cover 6300'-5300' (50' above Cliffhouse) behind pipe plus 100%.

- b. If squeeze holes do not take fluid, proceed to Step #6.
- 6. Pull 2-3/8" tubing up to 5350' and pump 13 sx (16 ${\rm ft}^3$) cement to cover top of Cliffhouse 5350'-5450' plus 75%.
- 7. Pull tubing up to 3535'. If perfs at 6300' took eament, perf 2 squeeze holes through tubing at 3585', close pipe rams, and pressure to 1000 PSI. If perfs take fluid, pump 37 sx (46 ft) cement to cover 3535'-3635' behind pipe plus 100%. This will segregate Ojo Alamo from Fruitland behind pipe.
- 8. With 2-3/8" tubing at 3535' with pipe rams open, pump 13 sx (16 ft³) cement to segregate Ojo Alamo from Fruitland 3535'-3635' inside pipe plus 75%.
- 9. With 2-3/8" tubing at 402' and pipe rams open, pump 13 sx (16 ft³) cement to place cement inside 4-1/2" casing 50' above and below surface casing shoe (352') plus 75%.
- 10. Spot 10 sx cement at surface, cut off wellhead below casing flange, and install dry hole marker.

P. M. Pippin

Production Engineer

N. K. Buller

Sr. Drilling Foreman