Form 9-331 Dec. 1973

outs tagenauts

UNITED STATES DEPARTMENT OF THE INTERIOR

Form Approved. Budget Bureau No. 42-R1424
5. LEASE
Contract No. 108
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
Jicarilla Tribal
8. FARM OR LEASE NAME Jicarilla G
9. WELL NO. 12
10. FIELD OR WILDCAT NAME
So. Blanco P.C.
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 13, T26N, R5W
12. COUNTY OR PARISH 13. STATE
Rio Arriba New Mexico
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD) 7199' DF
(NOTE: Report results of multiple completion or zone change on Form 9–330.)
DIV. change on Form 9–330.)
3
e all pertinent details, and give pertinent dates, rectionally drilled, give subsurface locations and t to this work.)*
the P.C. perforations. Displace
lama 03/50! snot a 60 sv (71 cu

GEOLOGICAL SURVEY	6. AF INDIAN, ALLOTTEE OR TRIBE NAME
	/ Jicarilla Tribal
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
Do not use this form for proposals to drill or to deepen or plug back to a different eservoir. Use Form 9-331-C for such proposals.)	Jicarilla Tribal
eservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas to other	Jicarilla G
Well - Well Guisi	9. WELL NO. 12
2. NAME OF OPERATOR E1 Page Natural Cas Company	10. FIELD OR WILDCAT NAME
El Paso Natural Gas Company 3. ADDRESS OF OPERATOR	So. Blanco P.C.
P. O. Box 289, Farmington, N. M. 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	AREA Sec. 13, T26N, R5W
AT SURFACE: 1095'S, 1065'E	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	Rio Arriba New Mexico
AT TOTAL DEPTH:	14. API NO.
6. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT PROTECTION	7199' DF
EST WATER SHUT-OFF	
RACTURE TREAT	<u>U</u>
HOOT OR ACIDIZE APR2 41	987 NOTE: Report results of multiple completion or zone
REPAIR WELL MF (12 4)	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
MULTIPLE COMPLETE	DIV.
ABANDON* DIST.	3
other)	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is di measured and true vertical depths for all markers and zones pertinen	irectionally drilled, give subsurface locations and
MOL & RU. Circulate hole. Spot a 30 sx (35 cu. ft.) cement plug across 4 sx into perforations. Pull tbg. Perforate 2 holes @ base of Ojo A cement plug to cover the Ojo Alamo from 3220 perforations. Perforate 2 squeeze holes @31 Circulate w/80 sx. (94 cu. ft.) thru the squ a 200' cement plug in casing from 110' to 31 Spot a 10 sx (12 cu. ft.) cement plug @ the	lamo @3450', spot a 60 sx (71 cu.f -3450. Displace 34 sx. into 0' (150' below surface casing.) heeze holes to the surface leaving 0'.
Spot a 30 sx (35 cu. ft.) cement plug across 4 sx into perforations. Pull tbg. Perforate 2 holes @ base of Ojo A cement plug to cover the Ojo Alamo from 3220 perforations. Perforate 2 squeeze holes @31 Circulate w/80 sx. (94 cu. ft.) thru the squ	lamo @3450', spot a 60 sx (71 cu.f -3450. Displace 34 sx. into 0' (150' below surface casing.) heeze holes to the surface leaving 0'.
Spot a 30 sx (35 cu. ft.) cement plug across 4 sx into perforations. Pull tbg. Perforate 2 holes @ base of Ojo A cement plug to cover the Ojo Alamo from 3220 perforations. Perforate 2 squeeze holes @31 Circulate w/80 sx. (94 cu. ft.) thru the squ a 200' cement plug in casing from 110' to 31 Spot a 10 sx. (12 cu. ft.) cement plug @ the marker.	lamo @3450', spot a 60 sx (71 cu.f -3450. Displace 34 sx. into 0' (150' below surface casing.) heeze holes to the surface leaving 0'. surface and install a dry hole
Spot a 30 sx (35 cu. ft.) cement plug across 4 sx into perforations. Pull tbg. Perforate 2 holes @ base of Ojo A cement plug to cover the Ojo Alamo from 3220 perforations. Perforate 2 squeeze holes @31 Circulate w/80 sx. (94 cu. ft.) thru the squ a 200' cement plug in casing from 110' to 31 Spot a 10 sx. (12 cu. ft.) cement plug @ the marker.	lamo @3450', spot a 60 sx (71 cu.f -3450. Displace 34 sx. into 0' (150' below surface casing.) heeze holes to the surface leaving 0'. surface and install a dry hole
Spot a 30 sx (35 cu. ft.) cement plug across 4 sx into perforations. Pull tbg. Perforate 2 holes @ base of Ojo A cement plug to cover the Ojo Alamo from 3220 perforations. Perforate 2 squeeze holes @31 Circulate w/80 sx. (94 cu. ft.) thru the squ a 200' cement plug in casing from 110' to 31 Spot a 10 sx. (12 cu. ft.) cement plug @ the marker. Subsurface Safety Valve: Manu. and Type 18. Thereby Partify that the foregoing is true and correct Production	lamo @3450', spot a 60 sx (71 cu.f -3450. Displace 34 sx. into 0' (150' below surface casing.) heeze holes to the surface leaving 0'. surface and install a dry hole
Spot a 30 sx (35 cu. ft.) cement plug across 4 sx into perforations. Pull tbg. Perforate 2 holes @ base of Ojo A cement plug to cover the Ojo Alamo from 3220 perforations. Perforate 2 squeeze holes @31 Circulate w/80 sx. (94 cu. ft.) thru the squ a 200' cement plug in casing from 110' to 31 Spot a 10 sx. (12 cu. ft.) cement plug @ the marker. Subsurface Safety Valve: Manu. and Type 18. Thereby entity that the foregoing is true and correct Production	lamo @3450', spot a 60 sx (71 cu.f -3450. Displace 34 sx. into 0' (150' below surface casing.) Heeze holes to the surface leaving 0'. surface and install a dry hole Set @Ft.