

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT - " for such proposals.

5. Lease Designation and Serial No.

Jic 97

6. If Indian, Allottee or Tribe Name

Jicarilla Apache

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Jicarilla 97 #3

9. API Well No.

30-039-06605

10. Field and Pool, or exploratory Area

Tapacito Pictured Cliffs

11. County or Parish, State

Rio Arriba NM

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

ENERGEN RESOURCES CORPORATION

3. Address and Telephone No.

2198 Bloomfield Highway, Farmington, NM 87401

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1650' FNL, 990' FEL, Sec. 8, T26N, R3W, N.M.P.M.

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice


TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other _____
- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well was plugged and abandoned on 8/23/00 as per the attached plugging summary.



14. I hereby certify that the foregoing is true and correct

Signed John Graham

Title Drilling & Completion Foreman

Date 9/11/00

(This space for Federal or State office use)

Approved by /s/ Patricia M. Hester

Title Lands and Mineral Resources

Date SEP 20 2000

Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

A - PLUS WELL SERVICE, INC.

P.O. BOX 1979
FARMINGTON, NM 87499
505-325-2627 • FAX: 505-325-1211

Energen Resources Corp.

August 24, 2000

Jicarilla 97 #3

Page 1 of 1

1650' FNL and 990' FSL, Section 8, T-26-N, R-3-W

Rio Arriba County, NM

Jicarilla Contract #97

API 30-039-06605

Plug & Abandonment Report

Cementing Summary:

Plug #1 with CIBP at 3551', spot 97 sxs Class B cement inside casing up to 3119' to isolate PC perforations and to cover up through Ojo Alamo top.

Plug #2 with 66 sxs Class B cement spotted in casing, then PUH with tubing to 1000' and squeeze 16 sxs cement outside 7-5/8" casing until it pressured up to 1000#; leave 50 sxs inside casing up to 1438' to cover Nacimiento top.

Plug #3 with 198 sxs Class B cement pumped down 7-5/8" casing from 371' to surface, circulate good cement out bradenhead.

Plugging Summary:

Notified BLM and Jicarilla Apache Tribe 8/18/00

08-18 MO, RU. Open up well and blow down 10# tubing and casing; 0# bradenhead. ND wellhead and NU BOP, test. Shut in well and SDFD.

08-21 Safety Meeting. Open up well and blow down 10# casing pressures. TOH and tally 120 joints 2-3/8", 4.7# J-55 tubing, total 3726'. RU A-Plus wireline truck and round-trip 7-5/8" gauge ring to 3551'. Set 7-5/8" PlugWell wireline CIBP at 3551'. TIH with tubing and tag CIBP at 3551'. Pump 150 bbls water down tubing to circulate well clean. Shut in well and SDFD.

08-22 Safety Meeting. Open up well, no pressure. Pump 72 bbls water down tubing to circulate to surface. Pressure test casing to 500# for 10 min, held OK. Plug #1 with CIBP at 3551', spot 97 sxs Class B cement inside casing up to 3119' to isolate PC perforations and to cover up through Ojo Alamo top. Perforate 3 HSC squeeze holes at 1650'. Establish circulation into squeeze holes 1-1/2 bpm at 750#. TIH to 1647' with tubing. Plug #2 with 66 sxs Class B cement spotted in casing, then PUH with tubing to 1000' and squeeze 16 sxs cement outside 7-5/8" casing until it pressured up to 1000#; leave 50 sxs inside casing up to 1438' to cover Nacimiento top. Shut in well with 700# pressure. TOH and WOC. RIH and tag cement at 1450'. Perforate 3 HSC squeeze holes at 371'. Pump 10 bbls water down casing and establish circulation out bradenhead. Plug #3 with 198 sxs Class B cement pumped down 7-5/8" casing from 371' to surface, circulate good cement out bradenhead. Shut in well and WOC. SDFD.

08-23 Safety Meeting. Open up well and ND BOP. Dig out and cut off wellhead; had to chip cement. Found cement down 1' in 7-5/8" casing and down 6' in 10-3/4" annulus. Mix 12 sxs Class B cement and install P&A marker. RD and move off. Bryce Hammond, Jicarilla Apache Tribe representative was on location.

BLM CONDITIONS OF APPROVAL

The following surface rehabilitation Conditions of Approval must be complied with as applicable, before this well can be approved for final abandonment (see 43 CFR 3162.3-4). Surface rehabilitation work shall be completed within one year of the actual plugging date. Notification for completion of this work can be submitted with a Sundry Notice. Questions? Call Pat Hester at (505) 761-8786.

1. All fences, production equipment, purchaser's equipment, concrete slabs, deadman (anchors), flowlines, risers, debris and trash must be removed from the location. Non-retrieved flowlines and pipelines will be abandoned in accordance with State Rule 714. Information supporting the non-retrieval will be included in the subsequent report or final abandonment Sundry Notice.

2. Production pits will be closed according to the Unlined Surface Impoundment Closure Guidelines, as approved in the Environmental Assessment of December 1993. Any oil stained soils can be remediated on-site according to these guidelines or disposed of in an approved facility.

3. The well pad will be shaped to the natural terrain and left as rough as possible. All compacted areas and areas devoid of vegetation shall be ripped to a minimum of 12" in depth before reseeding.

4. Access roads will be shaped to conform to the natural terrain and left as rough as possible to deter vehicle travel. Access will be ripped to a minimum of 12" in depth, water barred and reseeded. All erosion problems created by the development must be corrected prior to acceptance of release. Water bars should be spaced as shown below along the fall line of the slope:

% Slope	Spacing Interval
Less than 20%	200'
2 to 5 %	150'
6 to 9 %	100'
10 to 15 %	50'
Greater than 15%	30'

5. All disturbed areas will be seeded with the prescribed certified seed mix (reseeding may be required). Seed mix must be certified weed free to avoid the introduction of noxious weeds. Refer to the original APD for seed mix.

6. Notify Surface Managing Agency seven (7) days prior to seeding so that they may be present to witness.

7. The period of liability under the bond of record will not be terminated until the well is inspected and the surface rehabilitation approved.

Other Surface Managing Agencies (SMA's) may vary slightly in their restoration requirements. It is your responsibility, as the operator, to obtain surface restoration requirements from other SMA's. We need to be provided with a copy of these requirements. Any problems concerning stipulations received from other SMA's should be brought to us.

On private land, a letter from the fee owner stating that the surface restoration is satisfactory will be provided to the office. Questions? Call Pat Hester at (505) 761-8786.