

(SUBMIT IN TRIPLICATE)

Indian Agency _____

Jicarilla

Allottee _____

Lease No. Tribal 101

	2	
0		

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____	X
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF REDRILLING OR REPAIR _____	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____	
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____	
NOTICE OF INTENTION TO ABANDON WELL _____		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 4, 1964

Huron
Well No. 1-2 is located 940 ft. from $\begin{matrix} N \\ S \end{matrix}$ line and 1132 ft. from $\begin{matrix} K \\ W \end{matrix}$ line of sec. 2

SW 2
(1/4 Sec. and Sec. No.)26N
(Twp.)4W
(Range)NMPM
(Meridian)Blanco Mesaverde
(Field)Rio Arriba
(County or Subdivision)New Mexico
(State or Territory)

Tapacito Pictured Cliffs

The elevation of the derrick floor above sea level is 7171 ft. KB
7159 GL

DETAILS OF WORK

(State names of and expected depths to objective sands, show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 11/14/63. Drilled 15" hole to 309'. Set 12-3/4" casing at 309' KB. Cemented with 250 sx. reg., 2% CaCl₂. Circulated cement to surface, bumped plug @ 4:30 A.M., 11/15/63. WOC for 18 hrs. Mud drilled 10" hole to 4150'. Ran 7", 23# casing, set @ 4155' KB, cemented with 117 sx. 50/50 pozmix plus 50 sx. reg 2% CaCl₂. Bumped plug with 2000 lb. @ 3:00 A.M., 11/23/63. WOC 18 hrs. drilled with gas to 6214' KB. Ran 4-1/2", 9.5 lb. casing as liner, set from 4054 to 6218' KB. Cemented with 225 sx. 50/50 pozmix, 4% gel. Bumped plug 12/7/63. Cleaned out to liner top and float collar 12/17/63 - squeezed liner top with 50 sx. reg., 2% CaCl₂. Cleaned out to liner top, tested to 2750 psi, held okay.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company HURON DRILLING COMPANY, INC.

Address 715 Farmers Union Building

1575 Sherman Street

Denver 3, Colorado

By H. O. Hill

Title President

