JOVEMBER 1983) LOVEMBER 1983) LOVEMBER 1983) LOVEMBER 1983) DEPARTMENT OF THE INTERIC BUREAU OF LAND MANAGEMENT				· ·	Parities August AI, 1985 Express August AI, 1985 NM 03381		
(De net w	SUNDRY NO	OTICES AND REI	PORTS (ON WELLS	O. IV IMOIAM, ALLOTT	CR OA TIISE MANE	
::: D :	*** X ****	X			T. UNIT AGREGISHY PASSA		
HTHE OL OLISTICS					8. FARM OR LIABE HAME		
Caulkins Oil Company					Breech "B"		
3, ADDLESS OF OF		P. WELL NO					
4. LOCATION OF W	P.O. Box	172					
Bee also space At sortace	17 64(6W.)	Basin Dako					
,•	· 1850' F	It. SEC., T., S., M., OR SET, AND SURVEY OR AREA					
14. PERMIT NO.		11. ELEVATIONS (Sho	18, BILVATIONS (Show whether Dr. RT. GA, etc.)			Section 7, 26N 6W	
	6400 GR		00 GR	•	Rio Arriba New Mexico		
11.	Check			ature of Notice, Report, or C		New Mexico	
	FOTICE OF IN		noicole 11	•			
		PELL OR ALTER CASING		<u> </u>	PART REPORT OF;		
F8464A8 488	AT	NULTIPLE COMPLETE		PRACTURE TREATMENT	ALTERING C	·	
EH007 08 ACID	onta	******		BUDOTING OR ACIDIEING	ABANDONAE	·········· —	
REPAIR WELL	لــ ـا.	CHAMGE PLANS	_X	(Other)			
(Other)	ALD AL CHAPTETTE	Bettating (Classic state	<u> </u>	' I OM DIECION DE TACCOLUDI	of multiple completion elian Report and Log fo	`	
proposed was	rh. If well is dire	ctionally delited, give sub-	urface locali	details, and give pertisent dates, una and measured and erus vertica	including colimated da- i depths for all marker	te of starting any	
	7-22-89	Found leak i Top of cemen Set drillabl Perforate 2	Found leak in 4 1/2" casing at 1893'. Top of cement behind casing 2300'. Set drillable BP at 2500'. Perforate 2 holes at 2253'. Set cement retainer at 2000'.			6 1990 N.: DIV. IT. 3	
	7 -23- 89	Establish ci to leak at l	rculation 893'. (at 2000. on below retainer, th Cemented thru perfora LOO sacks Neat Cement	tions at 2253	' to	
	7-23-89	circulation to surface b	to surfa ut with	at 1893' with 118 Cu ace thru bradenhead, Alamo water sand top vered with cement.	cement did no	ot circulate	
	7-25-89	Drilled out decrease in		tested leak with 250		utes. No	
1. Cherty crypt	1361 At 101510101	Later and correct			(Over)		
BICHED	Kasles	Elegano	TLE SI	perintendent	патр9-21	1-89	
(This space for	Pederal or State	100 sk)	<u> </u>				
APPROVED BY	OF APPROVAL, IF	ANT:	TLE		_ ACCEPTED	<u>u record</u>	
				·	FE B	1990	
		*See 1	nitructions	on Revene Side			

Drilled out retainer and cement to below perforations at 2253'. Tested casing with 2500# for 30 minutes. No decrease in pressure. Drilled out Bridge Plug, cleaned out to TD at 7250'. Re-ran 2 3/8" tubing to 7233'.