Form 9-331 (May 1963)	SGS Durango DEPARTI	Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND BERIAL NO. COntract #116 6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)				, , , , , , , , , , , , , , , , , , , ,
OIL GA	S XX OTHER		CLEIVED	7. UNIT AGREEMENT NAME
2. NAME OF OPERAT	_		/ RLULII "	8. FARM OR LEASE NAME Tribal
Jerome P.			1 1970	9. WELL NO.
0- 004 5		. M. 87401	JUL FOOM.	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements See also space 17 below.) At surface OIL DIST. 3				Basin Dakota
	'O' fnl 920'			11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA
3.				Sec. 16, T26N, R3W
14. PERMIT NO.		15. ELEVATIONS (Show whether 7131' Gr.	DF, RT, GR. etc.)	Rio Arriba N. M.
16.	Check A	opropriate Box To Indicate	Nature of Notice, Repor	ort, or Other Data
	NOTICE OF INTER	TION TO:		SUBSEQUENT REPORT OF:
TEST WATER SE	UT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL,
FRACTURE TREA	r	MULTIPLE COMPLETE	FRACTURE TREATMEN	, ,
SHOOT OR ACIDI	ZB	ABANDON*	SHOOTING OR ACIDIZ	ZING ABANDONMENT*
REPAIR WELL (Other)	L	CHANGE PLANS	(Other)(Note: Report	t results of multiple completion on Well Recompletion Report and Log form.)
	ED OR COMPLETED OP	ERATIONS (Clearly state all pertin		nt dates, including estimated date of starting any ue vertical depths for all markers and zones perti-
5/27/70	uriling	at 40°. 12 1/4" su	rtace noie. Spudo	ded at 5:30 a.m., 5/27/70.
5/28/70	0.D., 24# with 175 hrs. dril surface c	, J-55, 8R ST&C csg sx. Class "C" with ling surface hole, (. T.E. 245' set a 2% Cacl. P.O.B. 1 6 1/2 hrs. drillin , 12 hrs. waiting	"hole. Ran 10 jts. 8 5/8" at 238' R.K.B. Cemented 11:00 a.m., 5/27/70. 2 3/4 ng, 2 1/4 hrs. running on cement and nippling hr. surveying.
6/14/70 18. I hereby certify	ST&C CF&I 8% gel? Good mud in reciprocate Baker staggilsonite cementing. Baker staggilsonite gilsonite returns when the staggilsonite returns when the s	drill pipe, ran 252 csg. set at 8190'. 200 sx. Class "C" 7 returns while cemented csg. O.K. while per sx. P.O.B. 11 per sx. P.O.B. 11 per sx. cementing pipe tool at 3861' with per sx. of cement. The cementing of the cementing of the cementing. May and install 6" blow true and correct	Dowell cemented 1/2# salt per sx. ting, Max. cementing. Cement 100 sx. Class "i:10 p.m., 6/13/70 ress. 600 psi. Ceth 100 sx. Class "P.O.B. 12:20 a.m. cementing press yout preventer.	wt. 9.2 vis 60 10.5 & 11.6#, K-55, 8R first stage with 100 sx. P.O.B. 7:45 p.m, 6/13/70. ing press. 700 psi - ented second stage through "C" 40% Diacel "D" 12 1/2# D. Good mud returns while emented third stage through "C" 40% Diacel "D" 12 1/2# a., 6/14/70. Good mud b. 500 psi - Good job.
SIGNED Orl	final signed b	y T. A. Dugan TITLE	Engineer	DATE 6/23/70
(This space for	Federal or State of	ice use)		<u>ប្ដល់ការៈសេក គេ</u>
APPROVED BY		TITLE		WE BEIVEN
CONDITIONS C	F APPROVAL, IF	ANY:		AN STATE

*See Instructions on Reverse Side

' f

i G. Edit OALONE SUR The CAN LIGHT FOR ITS