

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.
L.M. Phillips No. 3
SF 078068 - A
6. IF INDIAN, ALIOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Fresh Water Source		7. UNIT AGREEMENT NAME Carson Unit 25
2. NAME OF OPERATOR Shell Oil Company		8. FARM OR LEASE NAME
3. ADDRESS OF OPERATOR 1700 Broadway, Denver, Colorado 80202		9. WELL NO. 2-25
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FNL & 327.43' FWL of Sec. 25, T25N, R12W, NMPM, San Juan Co., N.M.		10. FIELD AND POOL, OR WILDCAT Bisti
14. PERMIT NO.		11. SEC. T. R. M., OR BLE. AND SURVEY OR AREA Sec. 25, T25N, R12W, NMPM
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6430' K.B.		12. COUNTY OR PARISH San Juan
		13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☒
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

See attached abandonment prognosis

18. I hereby certify that the foregoing is true and correct

SIGNED

R. P. Plauty

TITLE Division Operations Engr.

DATE AUG 18 1977

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

cc: NMO&GCC w/attachment

*See Instructions on Reverse Side

OK

8 5/8"
226'

32"

Prognosis
Plug and Abandonment
Carson Unit 2-25-42
Section 25, T. 25N, R. 2W
San Juan County, New Mexico

Pertinent Data

TD: 5000' PBTD: 5888'

8 5/8" Csg. @ 226'

5 1/2" Csg. @ 4969' w/ 200' sax.

7 7/8" Hole 3421' to 0' 2400' / 3421' ex

Elevation: 6450' KB

KB - GL = 11'

Permanent Datum = KB

Past and current status: *Presently T.A'd.
Conv. to water source well 4/66. Initially
pumped 1480 BOPD. Has a submersible pump
in well.*

Proposed Work: Plug and Abandon

1. Pull equipment. Run tubing . openended, lower to PBTD, load hole with mud. (Add 20 sax aquagel + 1 sack Benes per 100 bbls of mud or 20 sax salt gel per 100 bbls mud).
2. Spot 140 sax Class "G" cement mixed w/1# floccle/sack over perforations and above perforations. Minimum requirements - 100' cement plug above perforations. *w/1# 12 fms*
3. Pull tubing.
4. Rig up casing pullers. Determine casing free point.
5. Attempt to shoot and pull casing at free point (theoretical cement top at 2000'). Top of Mancos Shale 5795'. Do not spend more than 3 hrs. on attempt to pull casing. If unable to pull any casing, go to step 8.
6. If casing is recoverable, place cement plugs by cementing through casing or running tubing inside of csg. as it is pulled. Spot Class "G" cement plugs as follows:
 - a. 150' plug across stub of 5 1/2" casing. (50' in casing, 100' in open hole)
 - b. 200' plug from top of Fruitland Coal at 1100' to 1300'.
 - ~~c. 150' plug across base of Ojo Alamo sand at 4423'. (100' below base of sand and 50' above base of sand).~~
 - d. 100' plug across shoe of 8-5/8" casing (30' in casing, 70' in open hole).
 - e. 10 sack plug at surface.

2825'
2837'
2842'
2850'
2851'
2853'
2854'
2855'
2856'
2857'
2858'
2859'
2860'
2861'
2862'
2863'
2864'
2865'
2866'
2867'
2868'
2869'
2870'
2871'
2872'
2873'
2874'
2875'
2876'
2877'
2878'
2879'
2880'
2881'
2882'
2883'
2884'
2885'
2886'
2887'
2888'
2889'
2890'
2891'
2892'
2893'
2894'
2895'
2896'
2897'
2898'
2899'
2900'
2901'
2902'
2903'
2904'
2905'
2906'
2907'
2908'
2909'
2910'
2911'
2912'
2913'
2914'
2915'
2916'
2917'
2918'
2919'
2920'
2921'
2922'
2923'
2924'
2925'
2926'
2927'
2928'
2929'
2930'
2931'
2932'
2933'
2934'
2935'
2936'
2937'
2938'
2939'
2940'
2941'
2942'
2943'
2944'
2945'
2946'
2947'
2948'
2949'
2950'
2951'
2952'
2953'
2954'
2955'
2956'
2957'
2958'
2959'
2960'
2961'
2962'
2963'
2964'
2965'
2966'
2967'
2968'
2969'
2970'
2971'
2972'
2973'
2974'
2975'
2976'
2977'
2978'
2979'
2980'
2981'
2982'
2983'
2984'
2985'
2986'
2987'
2988'
2989'
2990'
2991'
2992'
2993'
2994'
2995'
2996'
2997'
2998'
2999'
3000'

5 1/2"
4969'

14"

* Ojo Alamo Sand Behind 8 5/8" Csg.

7. Install permanent abandonment marker as follows:

Steel marker at least 4 inches in diameter set in concrete and extending at least 4' above mean ground level. The name and number of the well and its location (Unit letter, section, township and range) shall be welded, stamped, or otherwise permanently engraved into the metal marker.

(Continuation from Step 5)

8. Perforate 5 1/2" casing w/4 JSPF as follows:

- a. Fruitland Coal - Pictures Cliffs interval 1150' to 1151'.
~~b. Below-ojo-Alamo sand from _____ to _____.~~

9. Run tubing, spot a 50 sack Class "G" cement plug from 1150' to 725'.
 10. Pull tubing to ±400', close bradenhead, displace 20 sax through perforations 1150' to 1151'. EOC 2 hours.
~~11. Pull tubing to perforations _____ to _____.~~
~~12. Load 5 1/2" casing with cement (± _____ sax) and pull tubing. With _____ bradenhead open, displace 20 sax cement through perforations _____ to _____.~~
 13. Spot 10 sack plug at surface.
 14. Install abandonment marker as outlined in step 7.

COC:mef

J. A. Stanzione