

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

L. M. Phillips No. 7
NM 070322

8. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Carson Unit

8. FARM OR LEASE NAME

9. WELL NO.

23-15

10. FIELD AND POOL, OR WILDCAT

Bisti

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

T25N, R12W

12. COUNTY OR PARISH

San Juan

13. STATE

N.M.

1.

OIL ☐ GAS ☐
WELL WELL OTHER

Water Injector

2. NAME OF OPERATOR

SHELL OIL COMPANY

3. ADDRESS OF OPERATOR

1700 BROADWAY, DENVER, COLORADO 80202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

1989' FSL & 1984' FEL of Sec. 15,
T25N, R12W, N.M.P.M., San Juan Co., N.M.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6234' G.R.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

SEE ATTACHED ABANDONMENT PROGNOSIS

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Division Operations Engineer

DATE SEP 19 1975

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Prognosis
 Plug and Abandonment
 Carson Unit 23-15
 Section 15, T 25N, R 2 W
 San Juan County, New Mexico

Pertinent Data


TD: 4917 PBD: 223
 8 5/8" Csg. @ 223
 4 1/2" Csg. @ 4902 w/ 160 sax. with 4% gel
 7 7/8" Hole

Elevation: 6245
 KB - GL = 11
 Permanent Datum = KB
 Past and current status: Presently TA'd
 Completed 9/20/57. Flowed 464 BOD, no water
 2300 MCF/Day gas. Converted to WI 1/2/67.

Proposed Work: Plug and Abandon

1. Pull equipment. If tubing is opened, lower to PBD, load hole with mud. (Add 20 sax aquagel + 1 sack Benex per 100 bbls of mud or 20 sax salt gel per 100 bbls mud).
2. Spot 20 sax Class "G" cement mixed w/ 1# floccle/sack over perforations and above perforations. Minimum requirements - 100' cement plug above perforations. WOC 12 hrs
3. Pull tubing.
4. Rig up casing pullers.
5. Attempt to shoot and pull casing. (theoretical cement top at 3850. Top of Mancos Shale 3703. If unable to pull any casing, go to step 8.
6. If casing is recovered, run tubing OE and spot Class "G" cement plugs as follows:
 - a. 150' plug across stub of 4-1/2" casing. (50' in casing, 100' in open hole)
 - b. 200' plug from top of Fruitland Coal at 1040 to 1240.
 - c. ~~150' plug across base of Ojo Alamo sand at 260. (100' below base of sand and 50' above base of sand).~~
 - * d. 200' plug across shoe of 8-5/8" casing. (30' in casing, 170' in open hole).
 - e. 10 sack plug at surface.

* Provides 100' cement below base of Ojo Alamo.



7. Install permanent abandonment marker as follows:

Steel marker at least 4 inches in diameter set in concrete and extending at least 4' above mean ground level. The name and number of the well and its location (Unit letter, section, township and range) shall be welded, stamped, or otherwise permanently engraved into the metal marker.

8. Perforate 4-1/2" casing w/4 JSPF as follows:

- a. Fruitland Coal - Pictures Cliffs interval 1050 to 1051.
- b. Below Ojo Alamo sand from 360 to 361.

9. Run tubing, spot a 50 sack (10.3 bbls, 630' in 4-1/2" casing) Class "G" cement plug from 1050 to 420.

10. Pull tubing to 400', close bradenhead, displace 20 sax through perforations 1050 to 1051. WOC 2 hours.

11. Pull tubing to perforations 360 to 361.

12. Load 4-1/2" casing with cement (\pm 35 sax) and pull tubing. With bradenhead open, displace 20 sax cement through perforations 360 to 361.

13. Spot 10 sack plug at surface.

14. Install abandonment marker as outlined in step 7.

BK/KWL

J. A. Stanzione
J. A. Stanzione