

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

(Other instructions on reverse side)

Budget Bureau No. 42-R1421

Phillips Pet. Co. No. 3
14-20-603-1285

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Water Injector		6. IF INDIAN, ALLOTTEE OR TRIBE NAME Hoska YeCa Wood Price	
2. NAME OF OPERATOR Shell Oil Company		7. UNIT AGREEMENT NAME Carson Unit	
3. ADDRESS OF OPERATOR 1700 Broadway, Denver, Colorado 80202		8. FARM OR LEASE NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FSL and 1888' FWL of Section 18, T25N, R11W, N.M.P.M., San Juan County, New Mexico		9. WELL NO. 23-18	
14. PERMIT NO.		10. FIELD AND POOL, OR WILDCAT Bisti-Gallup	
15. ELEVATIONS (Show whether DP, RT, CR, etc.) 6392.5' KB		11. SEC., T., S., M., OR BLK. AND SURVEY OR AREA Sec. 18, T25N, R11W, NMPM	
		12. COUNTY OR PARISH San Juan	13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

See attached abandonment prognosis



18. I hereby certify that the foregoing is true and correct

SIGNED

R. Flanigan

TITLE Division Operations Engineer

DATE

NOV 21 1978

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

cc: NMO&GCC w/attach

*See Instructions on Reverse Side

1/1000

8 5/8"
102'

Prognosis
Plug and Abandonment
Carson Unit 23-18
Section 18, T 25 N, R 11 W
San Juan County, New Mexico

Pertinent Data

TD: 5010' PBD: 4937'

8 5/8" Csg. @ 102'

4 1/2" Csg. @ 5006' w/ 150 sax.

7 7/8" Hole

Elevation: 6392' KB

KB - GL = 9'


Permanent Datum = KB

Past and current status: Presently T. A. 'd.
Converted to W.I. 1/62. AFE in File to Plug back.

No record of work. Profile survey indicates PB at 4937'.

Proposed Work: Plug and Abandon

1. Pull equipment. Run tubing . . . openended, lower to PBD, load hole with mud. (Add 20 sax aquagel + 1 sack Benex per 100 bbls of mud or 20 sax salt gel per 100 bbls mud).
2. Spot 25 sax Class "G" cement mixed w/1# flocele/sack over perforations and above perforations. Minimum requirements - 100' cement plug above perforations. WOC 12 hrs.
3. Pull tubing.
4. Rig up casing pullers. Determine casing free point.
5. Attempt to shoot and pull casing at free point (theoretical cement top at 4180'). Top of Mancos Shale 3873'. Do not spend more than 3 hrs. on attempt to pull casing. If unable to pull any casing go to step 8.
6. If casing is recoverable, place cement plugs by cementing through casing or running tubing inside of csg. if it is pulled. Spot Class "G" cement plugs as follows:
 - a. 150' plug across stub of 4 1/2" casing. (50' in casing, 100' in open hole)
 - b. 200' plug from top of Fruitland Coal at 1150' to 1350'.
 - c. 150' plug across base of Ojo Alamo sand at 270'. (100' below base of sand and 50' above base of sand).
 - d. 100' plug across shoe of 8-5/8" casing (30' in casing, 70' in open hole).
 - e. 10 sack plug at surface.



4 1/2"
5006' TD 5010'
9.5#

7. Install permanent abandonment marker as follows:

Steel marker at least 4 inches in diameter set in concrete and extending at least 4' above mean ground level. The name and number of the well and its location (Unit letter, section, township and range) shall be welded, stamped, or otherwise permanently engraved into the metal marker.

8. Perforate 4 1/2 " casing w/4 JSPF as follows:

- a. Fruitland Coal - Pictures Cliffs interval 1180' to 1181'.
- b. Below Ojo Alamo sand from 370' to 371'.

9. Run tubing, spot a 50 sack Class "G" cement plug from 1180' to 550'.
10. Pull tubing to $\pm 400'$, close bradenhead, displace 20 sax through perforations 1180' to 1181'. WOC _____ hours.
11. Pull tubing to perforations 370' to 371'.
12. Load 4 1/2 " casing with cement (\pm 30 sax) and pull tubing. With bradenhead open, displace 20 sax cement through perforations 370' to 371'.
13. Spot 10 sack plug at surface.
14. Install abandonment marker as outlined in step 7.

748-14/10/18
COC:maf

COC

FFB
11-3-78

G. L. Thompson
G. L. Thompson