

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.  
Phillips Pet Co. No. 2  
14-20-603-1284

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Hoska YeCa Wood Price

7. UNIT AGREEMENT NAME

Carson Unit

8. FARM OR LEASE NAME

9. WELL NO.

21-18

10. FIELD AND POOL, OR WILDCAT

Bisti

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

T25N, R11W

12. COUNTY OR PARISH

San Juan

13. STATE

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR  
Shell Oil Company

3. ADDRESS OF OPERATOR  
1700 Broadway, Denver, Colorado 80202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

660' FNL & 1970' FWL Sec. 18,  
T25N, R11W, N.M.P.M., San Juan Co., N.M.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6353.1' K.B.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON\* ☒

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐


ALTERING CASING ☐

ABANDONMENT\* ☐

(Note: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

See attached Abandonment Prognosis



18. I hereby certify that the foregoing is true and correct.

SIGNED

*R. Plaudy*

TITLE

Div. Ops. Engr.

DATE

MAY 26 1977

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

cc: New Mexico O&GCC

\*See Instructions on Reverse Side

8 5/8"  
106'

Prognosis  
Plug and Abandonment  
Carson Unit 21-18  
Section 18, T 25 N, R 11 W  
San Juan County, New Mexico

Pertinent Data

TD: 5024' PBD: 4925'  
8 5/8" Csg. @ 106'

4 1/2" Csg. @ 5015' w/ 150 sax.

7 7/8" Hole

Elevation: 6353' KB

KB - GL = 9'

Permanent Datum = KB

Past and current status: Presently T. A.'d.


Completed 9/58, flowed 383 BDO, 172 Mcf.  
*Suspected hole in csg. Tbg fish in hole.*

Proposed Work: Plug and Abandon

< Susp. hole  
in csg  
@ 1705' ±?

1. Has tubing. If tubing is opened, lower to PBD, load hole with mud. (Add 20 sax aquagel + 1 sack Benes per 100 bbls of mud or 20 sax salt gel per 100 bbls mud).
2. Spot 20 sax Class "G" cement mixed w/1# flocele/sack over perforations and above perforations. Minimum requirements - 100' cement plug above perforations. WOC 12 hrs.
3. Pull tubing. Pressure csg w/500 psi. If csg leaks, locate leak w/pk. Pull pvr. Spot 35' cement plug starting 50' below leak. Squeeze 15' through leak.
4. Rig up casing pullers. Determine casing free point.
5. Attempt to shoot and pull casing at free point (theoretical cement top at 4015'). Top of Mancos Shale 3867'. Do not spend more than 3 hrs. on attempt to pull casing. If unable to pull any casing go to step 8.
6. If casing is recoverable, place cement plugs by cementing through casing or running tubing inside of csg. as it is pulled. Spot Class "G" cement plugs as follows:
  - a. 150' plug across stub of 4 1/2" casing. (50' in casing, 100' in open hole)
  - b. 200' plug from top of Fruitland Coal at 1100' to 1300'.
  - c. 150' plug across base of Ojo Alamo sand at 320'. (100' below base of sand and 50' above base of sand).
  - d. 100' plug across shoe of 8-5/8" casing (30' in casing, 70' in open hole).
  - e. 10 sack plug at surface.

4 1/2"  
5015' TD 5024'  
9.5#



7. Install permanent abandonment marker as follows:

Steel marker at least 4 inches in diameter set in concrete and extending at least 4' above mean ground level. The name and number of the well and its location (Unit letter, section, township and range) shall be welded, stamped, or otherwise permanently engraved into the metal marker.

(Continuation from Step 5)

8. Perforate 4 1/2 " casing w/4 JSPF as follows:
- a. Fruitland Coal - Pictures Cliffs interval 1150' to 1151'.
  - b. Below Ojo Alamo sand from 420' to 421'.
9. Run tubing, spot a 50 sack Class "G" cement plug from 1150' to 520'.
10. Pull tubing to  $\pm 400'$ , close bradenhead, displace 20 sax through perforations 1150' to 1151'. WOC 2 hours.
11. Pull tubing to perforations 420' to 421'.
12. Load 4 1/2 " casing with cement ( $\pm$  30 sax) and pull tubing. With bradenhead open, displace 20 sax cement through perforations 420' to 421'.
13. Spot 10 sack plug at surface.
14. Install abandonment marker as outlined in step 7.

COC:maf

J. A. Stanzione