'N	rm 3160-5 ovember 1983) ormerly 9-331)		UNITED STATEMENT OF THE	INTER	_	PLICATE®	Budget Bareau Expires Augus 5. LEASE DESIGNATIO SF 078621	N AND SERIAL NO.		
ī.		form for pr	OTICES AND RE	pen or plug l	eack to a different reserv	oir.	6. IF INDIAN, ALLOTT			
		OTHE	(S.I.)		RECEIN		7. UNIT AGREEMENT P			
	Union Oil Company of California APR 17 1986						6. FARM OR LEASE NAME Federal 9. WBLL NO.			
4.	P. O. Box 2620 - Casper, WY 82602-2620  BUREAU OF LAND MANAGEMS FARMINGTON RESOURCE AR  See also space 17 below.)  At surface									
	1730' FNL & 1060' FEL (SE NE)							Sec. 24, T.25N., R.IIW.		
14.	PERMIT NO.		15. BLEVATIONS (Sh	ow whether DF 6508 G			12. COUNTY OF PARIS			
16.	Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data							INEW MEXICO		
							INT REPORT OF:			
	TEST WATER SHUT-OF: FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other)		PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS		WATER SHUT-OFF FRACTURE TREATM SHOOTING OR ACID (Other) (Note: Rep	PIZING	REPAIRING ALTERING ABANDONMI	CASING X		
(Other)  (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)  17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sones pertinent dates.										
	nent to this work.)*  6 8 ' T.D.  8-5/8" @ 723' w/5 0 sx  5- /2" @ 6 77.67' w/300 sx  Drilled in 1975				Perfs: 2 deep penetrating jet shots at each depth as follows: 5943', 5944', 5945', 5970', 5971', 5974', 5981', 5989', 5990', 5991', 5992', 5993', 5996', 6001', and 6009'					
	Plugged ar						n Graneros Sd.)			
MIRU well service unit on 4-4-86. N.U. Xtree and N.U. BOP. Released pa at 5874'. Strapped out of hole with 2-3/8" tubing.  TIH open ended with 2-3/8" tubing. Tagged bottom at 6040'. Circulated 50 bbls. fresh water, breaking circulation after pumping 20 bbls. wa Spotted 35 sacks of cement, and because of holes in the tubing, the ce was left in the tubing with no fill up. POOH and laid down 36 jts. tubing.								packer		
								water.		
	tagged Ell	Dat 6	040'. Loaded	hole w	of sub, and X- ith IO bbls. w g, laying down	water a	and numbed to	tal of		
			(Cont	nued on	Attached Sheet	)				
	i hereby certify that o	he topegoing	r is true and correct		trict Dr		DATE 4-	14-86		
	This abace for Federa	R.	G. Kadd, Jr.				DATE 4	/FF)		

Title 13 U.S.C. Section 1001, makes it a crime for any person Design and willfully to make to any de AREA: MANAGER the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

\*See Instructions on Reverse Side

TITLE

APPROVED BY \_\_\_\_\_\_\_CONDITIONS OF APPROVAL, IF ANY:

Union Oil Company of California Federal (H-24) Well No. I Basin Dakota Field San Juan County, New Mexico 4-14-86 Page 2

TIH with 2-3/8" tubing open ended and spotted 55 sacks of cement from 6035-5480' (Plug No. I). Reverse circulated 5-1/2" casing with 130 bbls. NaCl $_2$  water. Spotted 25 sacks of cement from 5000-4747' (Plug No. 2). Spotted 50 sacks of cement from 4100-3600' (Plug No. 3). Spotted 75 sacks of cement from 3000' to 2250' (Plug No. 4). POOH with 2-3/8" tubing, laying down 30 joints. N.D. BOP and casing head.

P.U. 5-1/2" casing spear, 6" sub, and one 4-3/4" drill collar and set in 5-1/2" casing at surface. Casing set with 90,000# tension. Pulled strain and removed 5-1/2" slips. Set casing with 60,000# tension. Calculated casing free at 1820'. Removed spear from 5-1/2" casing. Cut 5-1/2" casing with electric line and cutter at 1700'. POOH and laid down 41 jts. and 2 pieces (1693') of 5-1/2" casing.

TIH with 2-3/8" tubing open ended and washed through tight spot at 1200' O.K. TIH to 1800'. Spotted 40 sacks of cement from 1800-1600' ( $\underline{Plug\ No.\ 5}$ ). Spotted 90 sacks of cement from 1477-1120' ( $\underline{Plug\ No.\ 6}$ ). Spotted 70 sacks of cement from 850-580' ( $\underline{Plug\ No.\ 7}$ ). POOH, laying down tubing. Spotted 25 sacks of cement from 95' to surface ( $\underline{Plug\ No.\ 8}$ ). Cut casing off 4' below ground level and welded plate on 8-5/8" casing. Installed dry hole marker.

Well plugged and abandoned on 4-7-86.

Note: A sundry notice will be submitted to your office as soon as the location is ready for final inspection.