For 3160-3 UNITED STATES SUBMIT IN TRIP (Other instructions) (Formerly 9-331) DEPARTMENT OF THE INTERIOR verse side)  BUREAU OF LAND MANAGEMENT	
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservo Use "APPLICATION FOR PERMIT—" for such proposals.)	
OIL GAS OXESE	7. UNIT AGREEMENT NAME HUERFANO Unit 8. FARM OR LEASE NAME
2. NAME OF OPERATOR	
El Paso Natural Gas Company 3. ADDRESS OF OPERATOR	9. WBLL MO.
Post Office Box 4289, Farmington, NM	1 8 7 4 9 56
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)  At surface  SW/4	Basin Dikum Ballard Pic. Cliffs
850/s 850/w	Sec. 15, T-25-N, R- 9-
4 25 S	N.M.P.M.
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR. etc.)	San Juan NM
16. Check Appropriate Box To Indicate Nature of Notice, Rep	
NOTICE OF INTENTION TO:	SUBSEQUENT ESPORT OF:
TEST WATER SHUT-OFF POLL OR ALTER CASING WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT  HULTIPLE COMPLETE  FRACTURE TREATM	ENT ALTERING CABING
SHOOT OR ACIDIZE SHOOTING OR ACID	IZING ABANDONMENT*
Other)  (Other)  (Other)  (Other)	ort results of multiple completion on Well or Recompletion Report and Log form.)
This well has a possible casing failure.  NU BOP and test. Round trip tbg w/csg screlear perfs. Run cement retainer and set commercial production. After test, at lat production is recovered, sting out of retained 1/2" packer to locate casing failure. So Class "B" neat cement. Test squeeze to 75 tbg and sting into retainer. Return well	raper. Tag TD @ 6679' to @ 6350'. Test to recover ter date, if commercial ainer. TOOH and install squeeze w/50 sx (58.5 cu.ft.) 50 psi. TIH w/2 3/8", 4.7# to production
18. I hereby certify that the foregoing is true and correct  SIGNED AND TITLE Regulatory	DIST. 3  Affairs (68) 04-18-89
(This space for Federal or State office use)	
	APR-2 1 1939 (
APPROVED BY	Fin Skeller
individe Para Cida	FARMACOLOGO COLOGO