UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	<u>/</u>	
Sundry Notices and Reports on Wel	lls	
1. Type of Well GAS	5. Lease Number SF-078048 6. If Indian, All. or Tribe Name	
	7. Unit Agreement Name	
2. Name of Operator MERIDIAN OIL	8. Well Name & Number Hughes #12 9. API Well No. 30-045-	
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700		
4. Location of Well, Footage, Sec., T, R, M 1080'FSL, 1650'FWL Sec.29, T-26-N, R-7-W, NMPM	10. Field and Pool Ballard PC Ext 11. County and State San Juan Co, NM	
12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE		
Type of Submission Type of Ac	ction	
x Notice of Intentx Abandonment Recompletion	Change of Flans New Construction	
Subsequent Report — Plugging Back _ Casing Repair _	ction Change of Plans New Construction Non-Routine Fracturing Water Shut off Conversion to Injection	
Final Abandonment Altering Casing Other -	Conversion to Injection	
13. Describe Proposed or Completed Operations		
It is intended to plug & abandon this well per t	he attached procedure.	
OIL CON. DIV.	RECEIVED BLM 93 JUN 25 PM 2 070 FARLINGTON,	
Dist. 3	MYED PH 2: 44	
14. I hereby certify that the foregoing is true and	correct.	
Signed Manuel (MP) Title Regulatory A		
(This space for Federal or State Office use)	A P BaBeO V E D	
APPROVED BYTitle CONDITION OF APPROVAL, if any:	JUN 28 1993	
,	0-1-2	
	L DISTRICT MANAGER	

HUGHES #12 PC

UNIT N SECTION 29 T26N R07W San Juan County, New Mexico P & A Procedure

- 1. Install & test rig anchors. MI blow tank. MOL and RUSU (Bedford). Comply to all NMOCD, BLM, & MOI, rules & regulations. NU 6" BOP and stripping head. Test operation of rams. Install 2-7/8" relief line.
- 2. TOH w/119 Jts 1-1/4" tbg & lay down.
- Run guage ring on sand line to 2744' (50' above top FRT). TIH w/5-1/2" cmt ret on 2-3/8" rental tbg & set @ 2744'. Sting out of ret & pressure test to 500 psi. Sting back into ret, est rate, & sq w/ 55 sx Cl "B" cmt. This will fill PC perfs & 5-1/2" csg to 50' above top Fruitland w/100% excess cmt. PU & dump 5 sx cmt on top ret, PU, & reverse out.
- 4. Spot hole w/ 8 bbls mud: 15# sodium bentonite w/non-fermenting polymer, 8.4# gal weight, & 40 qs vis or greater.
- 5. PU to 2449' (50' below top Kirtland) & spot 46 sx cmt. This should cover the inside of the csg from 2449' to 2188' (50' above top 0jo Alamo).
- 6. Spot hole w/ 50 bbls mud: 15# sodium bentonite w/non-fermenting polymer, 8.4# gal weight, & 40 qs vis or greater.
- 7. Perf 2 holes @ 156' (50' below curface csg shoe). Est rate & circ cmt down csg & out bradenhead valve (about 50 sx).
- 8. Cut off wellhead below surface casing flange and install dry hole marker to BLM specs. Release rig.
- 9. Restore location to BLM specs.

Approve:			
	К. І	F.	Raybon
-	W. :	Ι.	Huntington

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT FARMINGTON RESOURCE AREA 1235 LA PLATA HIGHWAY FARMINGTON, NEW MEXICO 87401

Attachment to Notice of

Re: Permanent Abandonment

Intention to Abandon

Well: 12 Hughes

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases."

2. Mark Kelly with the Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 599-8907

- 3. Blowout prevention equipment is required.
- 4. The following modifications to your plugging program are to be made (when applicable):

1) Perforate 2 660', place a dement plug from 660' to 560' inside & outside the casing plus 100 % excess. (Nacimiento Top 2.610')

Office Hours: 7:45 a.m. to 4:30 p.m.

GENERAL REQUIREMENTS FOR PERMANENT ABANDONMENT OF WELLS ON FEDERAL AND INDIAN LEASES FARMINGTON RESOURCE AREA

- 1. Secure prior approval either on a Sundry Notice (Form 3160-5) or verbally from the Fluids Drilling & Production Section at this office before changing the approved plugging program.
- 2. Plugging equipment used shall have separate mixing and displacement pumps and a calibrated tank to assure proper displacement of plugs. The Operator is responsible for providing all measuring devices needed to assure proper measurement of materials being used.
- 3. A proper tank or pit will be used to contain all fluids pumped from the well during plugging operations. Unattended pits are to be fenced.
- 4. All cement plugs are to be placed through tubing (or drillpipe) and shall be a minimum of 100 feet in length with 50% excess inside casing or 100% excess when plug is set in open hole or squeezed into perforations. 15.6#/gal slurry weight is to be used when using class B near cement or when CaCl₂ is used. Use the recommended slurry weight of other type cements when they are used (Class C, Pozzolan etc.).
- 5. Any cement plugs placed when well is not full of fluid, or when well may be taking fluid, (i.e. across perfs-unless bridge plug or retainer is used, across bad csg., or fresh water formations) will be tagged (touched) after cement has set to verify proper location.
 - 5a. Testing The first plug below the surface plug shall generally be tested by either tagging the plug with the working pipe string, or pressuring to a minimum pump (surface) pressure of 1000 psig, with no more than a 10 percent drop during a 15-minute period (cased hole only). If the integrity of any other plug is questioned, it must be tested in the same manner. Also, any cement plug which is the only isolating medium for a fresh water interval or a zone containing a valuable mineral deposit should be tested by tagging with the drill string.
- 6. Mud must be placed between plugs. Plugging mud is to be made up with a minimum of 15 lbs/bbl of sodium bentonite, and a nonfermenting polymer.

 Minimum consistency of plugging mud must be 9 lbs/gal and with a minimum viscosity of 50 sec/qt. Fresh water is to be utilized for mixing mud.
- 7. Following the placement of a cement plug, the withdrawl rate for at least the length of the cement plug shall not exceed 30 ft/min, in order to minimize the contamination of the plug.

- 8. Within 30 days after plugging work is completed, file a Sundry Notice (Subsequent Report of Abandonment, Form 3160-5), in quintuplicate with Area Manager, Bureau of Land Management, 1235 La Plata Highway, Farmington, NM 87401. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. Show date well was plugged.
- 9. All permanently abandoned wells are to be marked with a regulation marker (4" pipe extending 4' above the ground line) containing the information as specified in 43 CFR 3162.6(d). Unless otherwise approved.
- 10. After plugging work is completed the surface is to be rehabilitated in accord with instructions from the Fluids Surface Management Section of the Farmington Resource Area Office.

All above are minimum requirements. The period of liability under the bond of record will not be terminated until the lease is inspected and surface work approved.

Please advise this office when the well location is ready for final inspection.

Failure to comply with the above conditions of approval may result in an assessment for noncompliance and/or a Shut-in Order being issued pursuant to 43 CFR 3163.1.

You are further advised that any instructions, orders or decisions issued by the Bureau of Land Management are subject to administrative review pursuant to 43 CFR 3165.3 and appeal pursuant to 43 CFR 3165.4 and 43 CFR 4.700.