UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau no. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.

SF079364

31 07 3004

BUREAU OF LAND MA	ANAGEMENI	WE CETAEN /	6. If Indian, Allottee or Tribe Name
SUNDRY NOTICES AND R	EPORTS ON WELL	S BLM	
Do not use this form for proposals to drill or to de		1906. 13 ATTT TE	
Use "APPLICATION FOR PERMIT	" for such proposals	FARMINOTON, NM	
SUBMIT IN TRIF	LICATE	PANIMOTOR CO.	7. If Unit or CA Agreement Designation
1. Type of Well			RINCON UNIT
Oil X Gas Well Other			8. Well Name and No.
2. Name of Operator			9 API Well No.
UNION OIL OF CALIFORNIA dba/UNOCAL	***		.4
3. Address and Telephone No.			3003906824
P.O. BOX 850 — BLOOMFIELD, NM 87413 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			BLANCO MESA VERDE
	11. County or Parish, State		
1697' FSL & 1460' FWL, SEC 31 - T27N R6W			RIO ARRIBA, NM
12. CHECK APPROPRIATE BOX(s) TO IN	DICATE NATURE OF NOTICE,	REPORT, OR OTHER DA	TA
TYPE OF SUBMISSION		TYPE OF ACTION	
X Notice of Intent	Ab and on ment		Change of Plans
	X Re∞mpletion		New Consturction
Subsequent Report	Plugging Back		Non-Routine Fracturing
	Casing Repair		Water Shut - off
Final Abandonment Notice	Altering Casing		Consersion to Injection
	Other		Dispose Water
			(Note: report results of multiple completion on Well Completion or Recompletion Report and Log form
 Describe Proposed or Completed Operations (Clearly state all perti- give subsurface locations and measured and true vertical depth 	tent details, and give pertinent dates, inclu- s for all markers and zones pertinent to thi	cing estimated date of starting ar s work.)*	y proposed work. If well is directionally drilled,
give substitute totallons and model to and the terminal depth	2000 por 100 miles		
It is the intent of Unocal to recomplete the Rincon Unit 1			
attached procedure. The Mesa Verde formation will pro	duce down hole commingled with	the existing Dakota comple	tion.
Attached for review and approval is form C-102.			•
Attached for review is authorazation to down hole comm	iingle.		
	[6]	ECEIVE	3

AUG 2 1 1936 DIVIS DIETTE 3

Work will commence within 2 months of receipt of approval.

Signed South Hum	Title PRODUCTION ENGINEER	Date <u>\$/14/96</u>
This space for Federal or State office		
Approved by Conditions of approval, if any:	Title	Cate



AUG 1 6 1996 Isl Duane Spencer

PO Box 1980, Hobbs, NM 88241-1980 PO Drawer DD, Artesia, NM 88211-0719 District III

1000 Rio Brazos Rd., Aztec, NM 87410

PO Box 2088, Santa Fe, NM 87504-2088

District IV

State of New Mexico Energy, Minerals & Natural Resources Department

OIL CONSERVATION DIVISION S PO Box 2088 Santa Fe, NM 87504-2088 RECEIVED BLM

Form C-101 Revised February 21, 199-Instructions on back Submit to Appropriate District Office

State Lease - 4 Copies Fee Lease - 3 Copies

	•	w	EII I	ario	N AND AC	96 REAGE DED	AUG 15 AM I	1:02 L	_ AMI	ENDED REPOR	
	API Numb			² Pool Co							
30-039-06834				72319	Old the state of t						
* Property	Code				⁵ Propert					Well Number	
11510 RINCON UNIT				183							
'OGRID No.				¹ Operator Name					Elevation		
023708 UNION			ON OIL	OF CALI	FORNIA db				6658' DF		
		,	·		¹⁰ Surface	Location					
UL or lot no.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West	line	County	
K	31	27N	06W	<u> </u>	1697 '	H.[nos	1460 '	WEST		RIO ARRIBA	
		r <u>- </u>				f Different Fr	om Surface			·*	
UL or lot no.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West	line	County	
Dedicated Acre	-1 13 Fai-4	- I- GIL 14 /	1					<u> </u>			
320	Y	TILLING	Consolidatio	n Code	rder No.						
	1	VIII RE A	SSICNE	D TO THE	C COV (DI ETT)						
	, and the second	OR A	NON-STA	ANDARD	UNIT HAS BE	ON UNTIL ALL EEN APPROVED	INTERESTS H	AVE BEE	N CON	ISOLIDATED	
6		·		D []	C 2 1 1996 CON. C		Signature Signature Fru dve Title Bate	that the info	mation con of my kn	IFICATION ontained herein is nowledge and belief	
/460) '	→->\(\frac{1}{2}\)					I hereby certify	that the well ! n field notes of pervision, and est of my belie	ocation sh f actual si that the s f.		

Certificate Number

RINCON UNIT 183 RINCON UNIT RIO ARRIBA COUNTY, NEW MEXICO RECOMPLETION PROCEDURE

- 1. Dig blooie/circulating pit and inspect anchors.
- 2. MIRU workover rig and equipment. Blow well down. Pump 20 barrels of 2% KCL water down the casing and 10 barrels down the tubing to kill the well.
- 3. Install BPV. Nipple down tree and nipple up BOP. Test BOP to 3500 psi.
- 4. Perform rig inspection as per Unocal guidelines and fax in all inspection and emergency response paperwork.
- 5. Drop a standing valve and test tubing to 3500 psi. Retrieve the standing valve on sandline. POOH standing back and visually inspecting 2-3/8" tubing. If tubing does not test, POOH laying down and pick up new string of 2-3/8" tubing.
- 6. Pick up 3-7/8" drag bit and 4-1/2" 11.6# casing scraper and TIH to PBTD of 7,420. POOH and lay down bit and scraper.
- 7. Rig up electric line. Run gauge ring/junk basket to PBTD of 7420'. Run and set 4-1/2" 11.6# RBP at ± 5,600'. Dump bail ±10' sand on top of RBP. POOH and test 4-1/2" casing to 500 psi.
- 8. Run a Gamma Ray/Neutron (GR/N) log from RBP to 5,100'.
- 9. Perforate the Mesaverde with 3-1/8" 2 spf and 90 degree phased casing guns based off of results of GR/N log. POOH and rig down electric line.
- 10. TIH with 2-3/8" tubing and stimulation packer. Set packer at ± 5100 '.
- 11. Fracture stimulate the Mesaverde down the 2-3/8" tubing as per recommendation.
- 12. Flow well back as soon as possible. Once the well stabilizes, test the well for 24 hours. If well dies prior to flowing stabilized, TIH with pump-down bailer and clean out sand fill. Once clean, TIH with packer and swab test the Point Lookout.
- 13. Kill well with ± 50 bbls of 2% KCl.

Rincon Unit 183

Page 2

- 14. TIH with retrieving tool to RBP @ ±5,600'. Circulate out sand above the RBP. Latch and release RBP. POOH and lay down tools.
- 15. Pick up and TIH with 2-3/8" production string to 7450'. Hang off tubing.
- 16. Nipple down BOP & nipple up tree. Test tree to 3000 psi.
- 17. Attempt to swab both zones in until flowing unassisted.
- 18. Rig down and move off workover rig.