

## (SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	Senta	Pe
Lease No.	07936	1
Ilmie	Rinco	1

## SUNDRY NOTICES AND REPORTS ON WELLS

IOTICE OF INTENTION TO DRILL		U ****				
		1	T REPORT OF WATER SHUT-OF			
		11	or or or or or or or or or normalization			
OTICE OF INTENTION TO TEST WA			SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR			
TICE OF INTENTION TO RE-DRILL						
TICE OF INTENTION TO SHOOT O						
TICE OF INTENTION TO PULL OR	ALTER CASING.	SUPPLEMENT	TARY WELL HISTORY			
TICE OF INTENTION TO ABANDON	ver vell	X				
(INDICA	ATE ABOVE BY CHECK M	MARK NATURE OF REPOR	RT, NOTICE, OR OTHER DATA)			
		***************************************	Many 21, 19			
l No. 1 is loca	ted 990 ft. fr	$\operatorname{rom}_{-} \begin{Bmatrix} \mathbf{N} \\ \mathbf{S} \end{Bmatrix}$ line and	d 990 ft. from E	line of sec.		
N SE SE (¼ Sec. and Sec. No.)	27N	2				
			(Meridian)			
Dlanco-phota (Field)	ido ari	Leg	Mane Mane	rian.		
(Field)	(Cou	nty or Subdivision)	(State or	Territory)		
names of and expected depths to	o objective sands; show ing points, and :	w sizes, weights, and ler all other important pro <b>文文章 十八 社会</b> 学	ngths of proposed casings; indeposed work)	icate mudding jobs, cemer		
anner:			en mus ann'i set M	err in the 1011		
m n127. ∮						
Clean out to 7605	PETD.					
Clean out to 7605	Penn 70EA +-	76051 and cen	ont with 200 and	******		
Clean out to 7605 Run 5-1/2" liner i Run Gamma Ray loc	Penn 70EA +-	7605' and cen e the Dakota	ent with 200 sax	cement.		
Clean out to 7605 Run 5-1/20 liner i Run Gauss Ray log 7518-7570.	from 7250 to and perforat	A CUR LEKOLE	with a jets per	loot, 7482-7504		
Clean out to 7605 Run 5-1/2" liner i Run Gamma Ray log 7510-7570. Frac with 500 gall	from 7250 to and perforat	A CUR LEKOLE	with a jets per	loot, 7482-7504		
Clean out to 7605 Run 5-1/2" liner i Run Gauss Ray log 7518-7570. Frac with 500 gall	from 7250 to and perforat lons mud acid	, 75,000 gml1	ons water and 75	loot, 7482-7504		
Clean out to 7605 Run 5-1/2" liner in Run Garma Ray log 7510-7570. Frac with 500 gall Sand. Set Magnesiwa brid Perforate Graneras	from 7250 to and perforat long and acid los plug, with	, 75,000 gail	ons water and 75, ver, at 76501.	foot, 7482-7504 ,000 pounds 20-		
Clean out to 7605 Run 5-1/2" liner : Run Gamma Ray log 7510-7570. Frac with 500 gall sand. Set Magnesium brid Perforate Graneros Frac with 500 gall	from 7250 to and perforat long and acid los plug, with	, 75,000 gail	ons water and 75, ver, at 76501.	foot, 7482-7504 ,000 pounds 20-		
Clean out to 7605 Run 5-1/2º liner i Run Gauss Ray log 7510-7570. Frac with 500 gall Send. Set Magnesium brid Perforate Graneros Frac with 500 gall	from 7250 to and perforat lons sad acid ige plup, with with h jets lone mud acid	h cal-scal co per foot, 73 , 50,000 gall	vich a jets per increased 75, ver, at 7450'. 50-7420'. ens water and 50,	foot, 7482-7504 ,000 pounds 20-		
Clean out to 7605 Run 5-1/2º liner i Run Gauss Ray log 7510-7570. Frac with 500 gall Send. Set Magnesium brid Perforate Graneros Frac with 500 gall	from 7250 to and perforat lons sad acid ige plup, with with h jets lone mud acid	h cal-scal co per foot, 73 , 50,000 gall	vich a jets per increased 75, ver, at 7450'. 50-7420'. ens water and 50,	foot, 7482-7504 ,000 pounds 20-		
Clean out to 7605 Run 5-1/2" liner : Run Gamma Ray log 7515-7570. Frac with 500 gall sand. Set Hagnesium brid Ferforate Graneros Frac with 500 gall	from 7250 to and perforat lons sad acid ige plup, with with h jets lone mud acid	h cal-scal co per foot, 73 , 50,000 gall	vich a jets per increased 75, ver, at 7450'. 50-7420'. ens water and 50,	foot, 7482-7504 ,000 pounds 20-		
Clean out to 7605 Run 5-1/2" liner : Run Gauss Ray log 7518-7570. Frac with 500 gall send. Set Magnesius brid Perforate Graneroe Frac with 500 gall send. Clean out to 7605!	from 7250 to and perforat loss sad acid los plug, with with 4 jets loss mad acid	h cai-seal co per foot, 73 , 50,000 gall whing and the	with a jets per increase water and 75, wer, at 7450'. 50-7420'. one water and 50, well into line.	foot, 7482-7504 ,000 pounds 20-		
Clean out to 7605 Run 5-1/2" liner : Run Gamma Ray log 7518-7570. Frac with 500 gall send. Set Hagnesian brid Perforate Granaroe Frac with 500 gall send. Clean out to 7605!	from 7250 to and perforat loss sad acid los plug, with with 4 jets loss mad acid	h cai-seal co per foot, 73 , 50,000 gall whing and the	with a jets per increase water and 75, wer, at 7450'. 50-7420'. one water and 50, well into line.	foot, 7482-7504 ,000 pounds 20-		
Clean out to 7605 Run 5-1/2" liner i Run Games Ray log 7518-7570. Frac with 500 gall send. Set Magnesium brid Perforate Graneroe Frac with 500 gall send. Clean out to 7605  inderstand that this plan of work	from 7250 to and perforations said seld seld seld seld seld seld seld sel	h cal-seal co par foot, 73 , 50,000 gall whing and the	with a jets per increase water and 75, wer, at 7450'. 50-7420'. one water and 50, well into line.	foot, 7482-7504 ,000 pounds 20-		
Clean out to 7605  Run 5-1/2" liner i  Run Gamma Ray log  7518-7570.  Frac with 500 gall  send.  Set Magnesium brid  Perforate Graneroe  Frac with 500 gall  send.  Clean out to 7605  inderstand that this plan of work	from 7250 to and perforat loss sad acid los plug, with with 4 jets loss mad acid	h cal-seal co par foot, 73 , 50,000 gall whing and the	with a jets per increase water and 75, wer, at 7450'. 50-7420'. one water and 50, well into line.	foot, 7482-7504 ,000 pounds 20-		
Clean out to 7605 Run 5-1/2" liner i Run Garma Ray log 7518-7570. Frac with 500 gall send. Set Magnesium brid Perforate Graneroe Frac with 500 gall send. Clean out to 7605  inderstand that this plan of work pany TEXAS NATION	from 7250 to and perforat long said acid long with a jets long mud acid PETO, run to must receive approva	h cal-seal co par foot, 73 , 50,000 gall whing and the	with a jets per increase water and 75, wer, at 7450'. 50-7420'. one water and 50, well into line.	foot, 7482-7504 ,000 pounds 20-		
Clean out to 7605 Run 5-1/2" liner i Run Garren Ray log 7518-7570. Frac with 500 gall Send. Set Magnesium brid Perforate Graneroe Frac with 500 gall Send. Clean out to 7605  Inderstand that this plan of work pany TEXAS NATION	from 7250 to and perforations said seld seld seld seld seld seld seld sel	h cal-seal co par foot, 73 , 50,000 gall whing and the	with a jets per increase water and 75, wer, at 7450'. 50-7420'. one water and 50, well into line.	foot, 7482-7504 ,000 pounds 20-		
Clean out to 7605 Run 5-1/2" liner i Run Garma Ray log 7518-7570. Frac with 500 gall send. Set Magnesium brid Perforate Graneroe Frac with 500 gall send. Clean out to 7605  inderstand that this plan of work pany TEXAS NATION	from 7250 to and perforat long said acid long with a jets long mud acid PETO, run to must receive approva	h cal-seal co par foot, 73 , 50,000 gall whing and the	with a jets per increase water and 75, wer, at 7450'. 50-7420'. one water and 50, well into line.	foot, 7482-7504 ,000 pounds 20-		
Clean out to 7605 Run 5-1/2" liner i Run Garma Ray log 7518-7570. Frac with 500 gall Send. Set Magnesium brid Perforate Graneroe Frac with 500 gall Send. Clean out to 7605  Inderstand that this plan of work pany TEXAS NATION	from 7250 to and perforat long said acid long with a jets long mud acid PETO, run to must receive approva	h cal-seal co par foot, 73 , 50,000 gall whing and the	with a jets per increase water and 75, wer, at 7450'. 50-7420'. one water and 50, well into line.	foot, 7482-7504 ,000 pounds 20-		
Clean out to 7605 Run 5-1/2" liner : Run Games Ray log 7518-7570. Frac with 500 gall send. Set Magnesium brid Perforate Graneroe Frac with 500 gall send. Clean out to 7605!  understand that this plan of work to 7605!  TEXAS MATION 1052 West Er	from 7250 to and perforat long said acid long with a jets long mud acid PETO, run to must receive approva	h cai-seal coper foot, 73, 50,000 gall  whing and tie	with a jets per increase water and 75, wer, at 7450'. 50-7420'. one water and 50, well into line.	foot, 7482-7504 ,000 pounds 20-		

Corners area

GPO 9 18 50 7