Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

Date NOV 2 5 1997

5. Lease Designation and Serial No SF 079321

6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals \$UBMIT IN TRIPLICATE		6. If Indian, Allottee or Tribe Name N/A
		7. If Unit or CA, Agreement Designation
Type of Well Oil Well Gas Well Other Name of Operator Spirit Energy 76/ A Business Unit of UNOCAL Address and Telephone No. P O. Box 3100, Midland, TX 79702 Location of Well (Footage, Sec., T., R., M., or Survey Description) 1650' FSL, 1650' FWL, Sec. 25-T27N-R7W	Oil Co. of Calif.) (915) 685-7607	8. Well Name and No. RINCON UNIT #139 9. API Well No. 30-039-06890 10. Field and Pool, or Exploratory Area Blanco Mesaverde 11. County or Parish, State Rio Arriba Co., NM
2. CHECK APPROPRIATE BOX(s) TO INDICATE	NATURE OF NOTICE, REPORT, C	R OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
X Notice of Intent Subsequent Report	Abandonment Recompletion ** Plugging Back	Change of Plans New Construction Non-Routine Fracturing
Final Abandonment Notice	Casing Repair Altering Casing Other	Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
3. Describe Proposed or Completed Operations (clearly state an perinter definite directionally drilled, give subsurface locations and measured and true vertical * ferf the Mesaver de and dow' existing completion in the Dakoto Copy of procedure & schen	nhole commingle the prod	action with the
	OLGON. DIV.	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

HOLD C-coup H *See Instruction on Reverse Side MMOCD

(This space for Federal or State office use)

Approved by AS/ Duane W. Spencer Conditions of approval, if any:

PROCEDURE AND CONDITION OF HOLE SOUTH PERMIAN ASSET TEAM

WO Supt. McF Res. Eng. Prod. Eng Prod. Supt.

Date:

October 16, 1997

AFE Number: CAP SWR

Field:

San Juan Basin

Area: South Permian

Lease/Unit:

Rincon

Well No.: 139

Reason For Work: To recomplete to the Point Look Out

Condition of Hole: See Wellbore Diagrams

Regulatory Requirements: Downhole Commingle Permit, Sundry Notice. 48 hour notification before rig up.

Procedure:

- 1. Dig and line circulating pit, install blooie line. Inspect anchors. Replace necessary anchors.
- 2. MIRU workover rig and equipment. Blow down well. Pump 20 bbls 2% KCL water down the casing and 10 bbls down the tubing to kill the well (or minimum amount needed).
- 3. Nipple down tree and nipple up tested BOP. Take tree to ERC for repairs.
- 4. Rig up Ico wellhead scan. POOH and LD 2-3/8" tubing and 4 GLV. Use blue and yellow band. Call to production for additional tubing to complete well.
- 5. Pick up 3-1/8" bit on 2-3/8" 4.7# N-80 tubing. RIH and clean out to 7550' or ETD 7575'.
- 6. (RU foam unit if cleanout is necessary). POOH and LD bit.
- 7. PU 4-1/2" 11.6# RBP. RIH and set RBP at 7200'. Dump bail 10' of sand. POOH.
- 8. RU Schlumberger wireline. RUN CBL from 5100' to 5600'. Run casing inspection log through 315'-5600'. If CBL shows no cement to isolate interval to be stimulated, abort job and go to 15 at this point.
- 9. Run gamma ray neutron log from 5100'-5600'. If cement intergrity is trusted, but casing is questionable, RIH and test casing to 200 psi. If casing fails, swab to determine if any water inflow. Isolate bad casing and determine if braidenhead squeeze will repair. At some point, if packer is ran, test BOP to 200-500 psig.
- 10. Perforate the Point Lookout 3-1/8" guns, 2 SPF 120 phasing (0.37" EHD 13.5") 5338-44', 5404-09', and 5420-28'. (may change due to results of GR/neutron log). POOH and RD electric line.
- 11. TIH w/ stimulation packer, sn, on 2-3/8" N-80 tubing. Hook up casing so that if pressure on casing during job exceeds comfortable pressure (200-500 psig) pressure will immediately relieve down blooie line to pit.
- 12. Load hole with 2% KCL and establish injection rate. If no breakdown, acidize Point Lookout with 1000 gal 15% HCL and additives. Divert with ball sealers. Flow/swab for cleanup;
- 13. Run data frac and frac per Dowell recommendation.
- 14. Flow back well. Achieve 24 hour test if well will not die, otherwise release packer, POOH w/packer and tubing.
- 15. RIH w/ retrieving head and CO to RBP. Latch on to RPB and POOH.
- 16. Run and land 2-3/8" production tubing at 7400'.
- 17. ND BOP and NU wellhead.
- 18. Swab well in, clean up to pit.
- 19. RD.

