

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. WELL OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	7. UNIT AGREEMENT NAME Rincon Unit
2. NAME OF OPERATOR Union Oil Company of California	8. FARM OR LEASE NAME Rincon Unit
3. ADDRESS OF OPERATOR P. O. Box 2620 - Casper, WY 82602-2620	9. WELL NO. 158
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1090' FSL & 1460' FWL (SE SW)	10. FIELD AND POOL, OR WILDCAT Basin Dakota
14. PERMIT NO. API 30-039-06951	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 22, T27N, R6W
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6515' GR 6525' DF	12. COUNTY OR PARISH Rio Arriba
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETION

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

Other:

(Other) Repair & Reactivate

X

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

7673' TD; 7604' ETD

Perfs: 7376-84', 7402-10', 7420-28'
(Graneros)

10-3/4" @ 309' w/220 SX

4-1/2" @ 7672' w/470 SX

7542-46', 7552-56', 7562-66'
7574-78' (Dakota)

The Rincon Unit Well No. 158 was idled in March of 1985 due to excessive water production, and the tubing is sanded in. The BLM requires that this well be repaired or plugged. Union proposes to fish the tubing, locate and correct the water problem, and reactivate the well.

Proposed Plan of Procedure

Set and test anchors. MIRU pulling unit. Blow down tubing and casing. If necessary, kill well with 2% KCl. N.U. BOP. Fish and recover tubing. Locate and squeeze hole in casing. Clean out to ±7604' PBTD. Run production tubing with packer at ±7300'. Swab well in and release rig.

18. I hereby certify that the foregoing is true and correct

SIGNED John R. Underhill

TITLE District Drilling Supt.

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

4-25-89

DATE

MAY 04 1989

DATE

AREA MANAGER
FARMINGTON RESOURCE AREA

*See Instructions on Reverse Side