UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

ви	ARTMENT OF THE INTERIOR REAU OF LAND MANAGEMENT	EDELYTI	
Sundr	y Notices and Reports on	Wells 1-6 Pil 1.	
1. Type of Well GAS	ı	070 FAGRAGION, NI	Lease Number SF-079492-B If Indian, All. or Tribe Name
2. Name of Operator		7.	Unit Agreement Name
BURLINGTON RESOURCES	OIL & GAS COMPANY	DEGETAE	1.7
3. Address & Phone No. of PO Box 4289, Farmingto:	n, NM 87499 (505) 326-97	_ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~	Well Name & Number San Juan 27-5 U#10 Well No. 30-039-07012 . Field and Pool
990'FNL 990'FEL, Sec.23	, T-27-N, R-5-W, NMPM	11	Blanco Mesaverde . County and State Rio Arriba Co, NM
12. CHECK APPROPRIATE BOX Type of Submission _X_ Notice of Inten Subsequent Repo Final Abandonme:	Type of Abandonment Recompletion rt Plugging Back Casing Repair	Action Change of P New Constru Non-Routine Water Shut Conversion	lans ction Fracturing
	Completed Operations pair the tubing on the su	bject well accord	ing to the
-			
	t the foregoing is true a		_Date 11/4/98
(This space for Federal or APPROVED BY /S/ Duane W. Spe CONDITION OF APPROVAL, if Title 18 U.S.C. Section 1001, makes it a cr:	ncer	Date to make to any department of	NUV 8 UUS

San Juan 27-5 Unit #10

Blanco Mesaverde Unit A, Sec. 23, T-27-N, R-5-W Latitude / Longitude: 36°33.79578' / 107°19.28286' Recommended Tubing Repair Procedure 10/20/98

Project Notes: This well hasn't been pulled since 1955. After squeezing off the water-producing Cliffhouse perforations in 1955. a bridge-plug used in the job was pushed to bottom. This well has an average decline of only 0.9% cer year, and an acid job performed on the well in 1998 saw only minimal success. The extremely low decline, tied with the fact that the EUR obtained with a pressure versus cumulative production plot is 1.6 BCF greater than the 98 PDP EUR, make this a worthwhile workover candidate.

NOTE: ALL DEPTHS ARE MEASURED FROM KB. KB to GL was 11'.

- Comply with all NMOCD, BLM and Burlington safety and environmental regulations. Prior to 1. moving in rig. make one-call and then verify rig anchors and dig pit.
- MIRU workover rig. NU relief line and blow well down (kill with 2% KCL water only if necessary). 2. ND WH and NU BOP. Test and record operation of BOP rams. Replace any WH valves that do not operate properly. Test secondary seal and install or replace if necessary.
- Mesaverde, 2-3/8" tubing set at 5654' (181 jts). NOTE: A seating nipple is not documented 3. in the tubing records. Release donut, pick up additional joints of tubing and tag bottom, recording the depth. PBTD should be at +/- 5689'. TOOH and stand back 2-3/8" tubing. Visually inspect tubing for corrosion, and replace any bad joints. Check tubing for scale and notify Operations Engineer if it is present.
- TIH with 4-3/4" bit, bit sub, and watermelon mill on 2-3/8" tubing and round trip to PBTD, cleaning 4. out with air/mist. NOTE: When using air/mist, mist rate must not be less than 12 bph. Speak with Operations Engineer, and if necessary, determine the best way to remove scale from the casing and perforations.
- TIH with one joint of 2-3/8" tubing with expendable check, F-nipple (one joint off bottom), then $\frac{1}{2}$ of 5. the 2-3/8" production tubing. Run a broach on sandline to insure that the tubing is clear. TIH with remaining 2-3.3" tubing. Replace any bad joints. CO to PBTD with air/mist.
- 6. PU above the top Mesaverde perforation at 5551' and flow the well naturally, making short trips for clean-up when necessary.
- Land tubing at 5635'. Obtain pitot gauge from casing and report this gauge. Broach the upper $\frac{1}{2}$ 7. of the production tubing. ND BOP and NU WH. Pump off expendable check. Connect to casing and circulate air to assure that expendable check has pumped off. If well will not flow on its own, make swab run to SN. RD and MOL. Return well to production.

10/20/48 Approved: Bruce in Bong 10 37 - 96 Drilling Superintendent

Operations Engineer:

L. Tom Loveland

Office 326-9771

Pager 324-2568

Home 564-4418