## State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division

	Sundry Notices and Re	ports on Wells	
			(assigned by OCD) 30-039-07097
1. Type of Well GAS			L <b>ease Number</b> Fee
		6. \$	State Oil&Gas Lease #
2. Name of Operator		7. 1	Lease Name/Unit Name
BURLINGTON			
	GAS COMPANY	8. 1	San Juan 28-6 Unit Well No.
3. Address & Phone No. of Operators PO Box 4289, Farmington, NM		9. 1	7001 Name or Wildcat
- Tarabian of Wall Backers Co.	- m p w		Blanco Mesaverde
4. Location of Well, Footage, Sec. 790'FNL 865'FEL, Sec.14, T-27-		=	ievacion.
Type of Submission	Type of Act	ion	
_X_ Notice of Intent		_ Change of Plan	
	<del></del>	_ New Constructi	
Subsequent Report		_ Non-Routine Fr	_
Final Abandonment	<pre> Casing Repair Altering Casing</pre>	_ Water Shut off	
Final Abandonment	Aftering casing _X_ Other -	_ conversion co	11170001011
13. Describe Proposed or Comple  It is intended to repair the attached procedure.	ne tubing on the subjec	t well according	to the
		EIVED 2 3 1998 DN. DIV. St. 3	
SIGNATURE SOUL SHOUL KEE			ecember 22, 1998
THE THE PERSON OF THE PERSON O		_ <del>_</del>	TLW
(This space for State Use)			<del></del>
	OFPUTY OIL & G	AS INSPECTOR, DIST. 43	n ma
ORIGINAL SIGNED BY GRANGES Approved by	and Company and a	CETOR, DIST.	
Approved by	Title		Date

## San Juan 28-6 Unit #67 Blanco Mesaverde

Unit A, Sec. 14, T-27-N, R-6-W Latitude / Longitude: 36°34.75524' / 107°25.79958' Recommended Tubing Repair Procedure 10/20/98

Project Notes: This well has not been pulled since 1956. The lease operator reports equalized tubing and casing pressures and suspects a hole in the tubing. Although the remaining reserves are small according to 98 PDP, there is a 599 MMCF difference between the pressure versus cumulative production EUR and the 98 PDP EUR. The possibility of increased reserves and the suspected hole in the tubing makes this a valued workover.

## NOTE: ALL DEPTHS ARE MEASURED FROM KB. KB to GL was 11'.

- Comply with all NMOCD, BLM and Burlington safety and environmental regulations. Prior 1. to moving in rig, make one-call and then verify rig anchors and dig pit.
- MIRU workover rig. NU relief line and blow well down (kill with 2% KCL water only if 2. necessary). ND WH and NU BOP. Test and record operation of BOP rams. Replace any WH valves that do not operate properly. Test secondary seal and install or replace if necessary.
- Mesaverde, 2-3/8", 4.7# tubing set at 5384' (173 jts). NOTE: There is no record of a 3. seating nipple. Release donut, pick up additional joints of tubing and tag bottom, recording the depth. PBTD should be at +/- 5400'. TOOH and stand back 2-3/8" tubing. LD perf'd joint. Visually inspect tubing for corrosion, and replace any bad joints. Check tubing for scale and notify Operations Engineer if it is present.
- TIH with 4-3/4" bit, bit sub, and watermelon mill on 2-3/8" tubing and round trip to PBTD, 4. cleaning out with air/mist. NOTE: When using air/mist, mist rate must not be less than 12 bph. Speak with Operations Engineer, and if necessary, determine the best way to remove scale from the casing and perforations.
- TIH with one joint of 2-3/8" tubing with expendable check, F-nipple (one joint off bottom), 5. then  $\frac{1}{2}$  of the 2-3/8" production tubing. Run a broach on sandline to insure that the tubing is clear. TIH with remaining 2-3/8" tubing. Replace any bad joints. CO to PBTD with air/mist.
- PU above the top Mesaverde perforation at 4674' and flow the well naturally, making 6. short trips for clean-up when necessary.
- Land tubing at 5315'. Obtain pitot gauge from casing and report this gauge. Broach the upper ½ of the production tubing. ND BOP and NU WH. Pump off expendable check. Connect to casing and circulate air to assure that expendable check has pumped off. If well will not flow on its own, make swab run to SN. RD and MOL. Return well to production.

Recommended: J. Jone-bree

Approved: Brucol Bonn 10:27-48
Drilling Superintendent

Operations Engineer: L. Tom Loveland

Office 326-9771

Pager 324-2568

Home 564-4418

\\StreetTalk\Shared@OPRprd@FAR\Tlovelan\Area 8 Wells\Tubing Repair\28-6\67\Procedure.doc