District I PO Box 1980. Hobbs. NM 88241 1980

District []

PO Drawer DD, Artesia, NM 88211-0719

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

PO Box 2088, Santa Fe, NM 87504-2088

State of New Mexico Energy, Minerals & Natural Resources Department

OIL CONSERVATION DIVISION PO Box 2088 Santa Fe, NM 87504-2088

Form C-101 Revised February 10. 1994 Instructions on back
Submit to Appropriate District Office

Sadmit to Appropriate District Offico
State Lease - 6 Copies
Fee Lease - 5 Copies
AMENDED REPORT
ICDACK OR ADD A ZOVE

A DDI IO	TION	BOD D							<u>L.</u>		IDED REPORT
APPLICA	TION	FOR PE			LL, RE-EN	TER, DE	EPE	EN, PLUGB	ACK,	_	DD A ZONE
Conoc			_				_ \	oliku v			005073
		ite. 100W 19705-45				List	F	E9 1 1 1/4	2		API Number
·										^{30 - 0} 3	9-07180
	erty Code 6608					operty Name	<u>[</u>] (GOLD. T.			Well No.
01	0008				San Ju Surface 1	an 28-7 Un	it	District			130
UL or lot no.	Section	Township	Range	Lot Idn	Feet from the	North/South	lina	East from the	l 5		
L	2	27N	7W	200 1011	1668'		ine	Feet from the		est line	County
				Bottom		South	erer	1 From Sur	face	Vest	Rio Arriba
UL or lot no	Section	Township	Range	Lot Idn	Feet from the	North/South		Feet from the		est line	County
	L	· Propos	ed Pool I			<u></u>		" Propos	ed Pool 2	<u></u>	
		Blanco M	lesaverde					Basin I			
								Dasin	Jakota		<u></u>
Work T	ype Code		Weil Type	Code	" Cable	Rotary		" Lease type Co	de	14 Grou	nd Level Elevation
Α			M		R			S (E 290-33)		6165'
Yes-Do			17 Proposed	Depth	18 Form	nation		19 Contractor		2	0 Spud Date
Commingle	w/Dako	ta	7309'	Dro							
Hole Si	1		21		ed Casiing a	nd Cemen	t Pro	ogram			
11016 31	-	C as:n	y Size	Casin	g weight/foot	Setting D	epth	Sacks of	Cemen:		Estimated TOC
Same as or	iginal			 			_				
	-5			 						_	
				 						- 	
								- 		+-	
zone. Describe	ine blowou	t prevention_	program. it	anyUse add	N or PLUG BACK ditional sheets if no verde using th	ecrssary.		present productive	zone an	d proposed	d new productive
23 I hereby cenif		formation give	en above is ti	ue and compl	ute to the best	01	T (ONCEDIA	ELON	DIME	10.11
of my knowledge Signature:	and/belief.	M.	On 1		-			ONSERVA	IIUN	ואוט	IUN
	My-	MAAA			Ap	proved by:	És	ne 12	M	1	
Printed name:		Kay Ma	ddox	······	Titl	e: 797.P l	JTY (OIL & GAS INS	PECTOR	, DIST.	13
Title:	Regulat	ory Agent	- Conoc	o, Inc	Apı	oroval Date: L. C	5]	<u>o 1999</u>	xpiration	Dale: E	16 200
Date:			Phone		Co	nditions of Appr	oval:				7 ~ 5000
Febru	ary 4, 19	99	(9	15) 686-5	798 At	tached					[

Please Refer questions to the following people:

Geologic/Logging:	Tom Johnson	(915) 686-6111
Engineering/Procedural:	Randy Herring Pager	(915) 686-6541 800-999-6710 I.D.# 991-7826
Fracturing:	Jim Russell: Pager Mobile	(505) 327-6222 (505) 324-1867 (505) 330-0005
Completion:	Greg Vick: Pager Mobile	(505) 324-5819 (505) 324-2601 (505) 320-4609
	Gilbert Hughes Pager Mobile Lino Hernandez: Pager	(505) 324-5812 (505) 327-8753 (505) 320-4785 (505) 324-5816 (505) 326-8198
#'s BLM: (505) 599-890 One Call: 1-800-321-25		(505) 320-6739 (505) 334-6178

Other #

Midland Continuous Fax:

(915) 686-6112

EMERGENCY NUMBERS:

Aztec Fire & Police: 911

Air Care:

911 or 1-800-452-9990

NM State Police

325-7547

SJ County Sheriff:

334-6107

February 2, 1999

Summary of Work Recommended

- Isolate DK zone from MV
- Run CBL across MV (Cmt Sqz if TOC is below 4350')
- Log MV using TDT/GR
- Perf & Stimulate MV Interval (expect 3 stages, May require frac string)
- Remove Isolation Plugs
- Return well to Production as MV/DK DHC

Well Data:

AFE#

51-61-8954

Downhole Commingle:

DHC-????

Location:

1668' FSL & 800' FWL, Sec. 2, T27N-R7W

Rio Arriba County, New Mexico

Elevations:

KB: 6175'

GL: 6165' PBTD: 7253' TD: 7309'

Casing:

10 3/4", 32.75 #/ft, set @ 2298'

1 stage:

232 sxs.

TOC @ Surface (circ)

4-1/2", 10.5 & 11.6 #/ft, set @ 7309'

11.6 #/ft 14 jts from 0' to 460' 10.5 #/ft 178 jts from 460' to 5,729'

11.6 #/ft 35 jts from 5,729' to 7,309'

Cmt'd w/ 3-stages & 725 sxs

	_	<u>-</u>
	300 sxs	TOC @ 6290 (TS)
DV @ 5299'	195 sxs	TOC @ 4450' (TS)
DV @ 2909'	230 sxs	TOC @ 2000' (TS)
	•	DV @ 5299' 195 sxs

Size	Wt	Drift	Capacity	Burst
10 ¾"	32.75	10.0036"	13.05 ft/bbl	1820 psi
4 1/2"	11.6	3.875"	1.532 ft/bbl	5350 psi
4 1/2"	10.5	3.927"	1.493 ft/bbl	4790 psi
2 3/8"	4.7	1.901"	258 ft/bbl	5600 psi

Tubing:

2 3/8" 4.7 3/ft @ 7120'

Replaced w/ new "A" tubing, June 1998

Perforations: DK:

DK: (7044

(7044'- 7220') 7000'- 7225'

7044'-48', 64'-68', 7159'-71', 91'-95',

7214'-20'

- 1. Hold tailgate safety meetin8gs prior to rigging up, each morning, and whenever necessary.
- 2. Test Anchors, MIRU Workover Unit. If necessary, kill well with a minimum of 1 % KCl. NU BOP. POOH w/ 2 3/8" production string.
- 3. RU wireline unit & set 4 ½" Fast-Drill plug over the Dakota +/- 5800'
- 4. RU Logging tools. Run GR/CBL from 5300' to 4300' to determine TOC. Run GR/TDT/CCL from 5350' to 4350'. Fax log into Midland @ (915) 686-6112 continuous log fax or (915) 686-5508 single page fax. Contact Randy Herring (915) 686-6541 or Tom Johnson (915) 686-6111 just prior to sending Fax to ensure machine is ready to receive. Note: Cmt squeeze if TOC is below 4350'. Contact BLM for approval prior to initiating squeeze work

Note: If Squeeze work is required adjust procedure to utilize a frac string.

1st Stage

- 5. Perforate the Lower MV (Point Lookout) across the following intervals using a 3 1/8" Select Fire gun w/ 11 gm charges. Correlate to CCL from TDT log:
 - Perforations to be determined from TDT Log. (Estimate 30 holes)
- 6. RU Acidizing equipment. Test lines to 4000 psi Break down perfs using 500 gallons 15% HCl and 50% excess 1.1 sg balls (45) spaced equally throughout the job. Run as high a rate as possible without exceeding max pressure. DO NOT EXCEED 3500 psi
- 7. Retrieve balls and check for hits. If # hits less than 80% (24), re-acidize using the above procedure. Prep to frac.
- 8. Frac per attached procedure. Leave frac equipment on location. RIH and set w/ Fast-drill plug above Point 8lookout (Depth to be determined from TDT log).

2nd Stage

- 9. Perforate the Menefee across the following intervals using a 3 1/8" Select Fire gun w/ 11 gm charges. Correlate to CCL from TDT log:
 - Perforations to be determined from TDT Log. (Estimate 30 holes)
- 10. RU Acidizing equipment. Test lines to 4000 psi Break down perfs using 500 gallons 15% HCl and 50% excess 1.1 sg balls (45) spaced equally throughout the job. Run as high a rate as possible without exceeding max pressure. **DO NOT EXCEED 3500 psi**

- 11. Retrieve balls and check for hits. If # hits less than 80% (24), re-acidize using the above procedure. Prep to frac.
- 12. Frac per attached procedure. Leave frac equipment on location. RIH and set w/ Fast-drill plug above Point lookout (Depth to be determined from TDT log).

3rd Stage

Perforate the Cliffhouse across the following intervals using a 3 1/8" Select Fire gun w/ 11 gm charges. Correlate to CCL from TDT log:

Perforations to be determined from TDT Log. (Estimate 30 holes)

- 14. RU Acidizing equipment. Test lines to 4000 psi Break down perfs using 500 gallons 15% HCl and 50% excess 1.1 sg balls (45) spaced equally throughout the job. Run as high a rate as possible without exceeding max pressure. **DO NOT EXCEED 3500 psi**
- 15. Retrieve balls and check for hits. If # hits less than 80% (24), re-acidize using the above procedure. Prep to frac.
- 16. Frac per attached procedure. Clean Location and release frac equipment.
- 17. Rig up compressors and power swivel. RIH w/ bit & collars on tbg. CO & DO Mesaverde bridge plugs to 5800'. Jet well w/ gas until well will flow on its own. Drywatch as necessary.
- 18. Test Mesaverde and obtain a stabilized flow rate for allocation purposes.
- 19. RU compressors and drill out bridge plug @ 5800' w/ gas. Clean out well to PBTD (7267'). Jet well w/ gas until well will flow on its own. Drywatch as necessary.
- 20. PU & RIH w/ 2 3/8" production string. Land SN at +/- 7120'. ND BOP and NU wellhead.
- 21. Record and notify necessary personnel for regulatory and gas allocation purposes.
- 22. RDMO workover unit and clean location
- 23. Place well on production
- 24. Thank You.

Prepared By:		
	Randy B. Herring,	
	Sr. Production Engineer	

District I PO Box 1980, Hobbs. NM 88241-1980

District IV

State of New Mexico
Energy, Minerals & Natural Resources Department

District II PO Drawer DD, Artesia, NM 88211-0719 District III 1000 Rio Brazos Rd. Aztec, NM 87410

PO Box 2088, Santa Fe. NM 87504-2088

OIL CONSERVATION DIVISION PO Box 2088 Santa Fe, NM 87504-2088 Revised February 21, 1994 instructions on back Submit to Appropriate District Office State Lease - 4 Copies Fee Lease - 3 Copies

AMENDED REPORT

WELL LOCATION AND ACREAGE DEDICATION PLAT

API Number	2 Pool Code	3 Pool Name
30-039-0718	0 72319	Blanco Mesaverde
4 Property Code	5 Property Nam	ne 6 Well Number
016608	San Juan 28-7 Un	it # 130
7 OGRID No.	8 Operator Na	
005073	Conoco Inc., 10 Desta Drive, Ste. 100W, I	Midland, TX 79705-4500 6165'

10 Surface Location

UL or lating	Section	Township	Range	Lot idn	Feet from the	North/South line	Feet from the	East/West line	County
L	2	27N	7W		1668'	South	800'	West	Rio Arrib
			11 Bo	ttom Hol	le Location I	f Different Fre	om Surface		·· / · ··
UL of lot rio.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West line	County
2 Dedicated Acres		i	Consolidatio	n Code 15	Order No.	10987 - A			<u> </u>
328 7	18.96	•			χ-	10907-71			

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION



