UNITED STATES

DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT RECEIVED

		SLT		
	Sundry Not	ices and Reports on Wells	. –	
		98 JUN -5 PM 3:		
			5.	Lease Number
ייף י	ype of Well	070 FARMINGTON, !	₩ 6.	SF-079393
i. i	GAS		٥.	If Indian, All. or Tribe Name
				
			7.	Unit Agreement Name
2. N	ame of Operator			San Juan 27-5 Unit
	BURLINGTON			
4	RESOURCES OIL	& GAS COMPANY		
			8.	
	ddress & Phone No. of Opera		•	San Juan 27-5 U #60
	PO Box 4289, Farmington, NM	87499 (505) 326-9700	9.	API Well No. 30-039-07193
	ocation of Well, Footage, S	og T P W	1.0	Field and Pool
	1650' FNL, 1060' FEL, Sec.		10.	Blanco Mesaverde
	1030 1112, 1000 122, 500.	a, I Z, N, K S N, MILI	11.	County and State
				Rio Arriba Co., NM
		DICATE NATURE OF NOTICE, REPORT	, OTHER	DATA
T	ype of Submission	Type of Action Abandonment Chang	o of Di	279
	X Notice of Intent	Abandonment Chang Recompletion New C		
	Subsequent Report			Fracturing
	Subsequenc Report		Shut o	_
	Final Abandonment	Altering Casing Conve		
		X Other - Tubing repair		o 111,0001011
13.	Describe Proposed or Comp	leted Operations		
	It is intended to repair attached procedure.	the tubing on the subject well.	accordi	ng to the
		[D] [F] (CEIN	NEW
		1 femal	י עכנו ע	
		r <i>I</i> u	UN 1 1	1998
			•	
		con an	months of the	
			CON.	DIV.
			((())). 1729	
14.	I hereby certify that the	foregoing is true and correct.		
į		foregoing is true and correct.	per.	<u></u>
14.			ator_Da	te 6/3/98
sigh	ed Somy Statuted	foregoing is true and correct.	ator_Da	<u></u>

San Juan 27-5 Unit #60 Blanco Mesaverde

Unit H, Sec. 04, T-27-N, R-05-W

Latitude / Longitude: 36° 36.31530' / 107° 21.46452' Recommended Tubing Repair Procedure 5/19/98

NOTE: ALL DEPTHS ARE MEASURED FROM KB. KB to GL was 10'.

- 1. Comply with all NMOCD, BLM and Burlington safety and environmental regulations. Prior to moving in rig, make one-call and then verify rig anchors and dig pit.
- MIRU workover rig. NU relief line and blow well down (kill with 2% KCL water only if 2. necessary). ND WH and NU BOP. Test and record operation of BOP rams. Replace any WH valves that do not operate properly. Test secondary seal and install or replace if necessary.
- 3. Mesaverde, 2-3/8", 4.7#, J-55 tubing set at 5654' (182 jts). There is no record of nipple in wellfile. Release donut, pick up additional joints of tubing and tag bottom, recording the depth. PBTD should be at +/- 5686'. TOOH and stand back 2-3/8" tubing. Visually inspect tubing for corrosion, and replace any bad joints. Check tubing for scale and notify Operations Engineer if it is present.
- TIH with 3-7/8" bit, bit sub, and watermelon mill on 2-3/8" tubing and round trip to PBTD, cleaning out with air/mist. NOTE: When using air/mist, mist rate must not be less than 12 bph. Speak with Operations Engineer, and if necessary, determine the best way to remove scale from the casing and perforations.
- TIH with one joint of 2-3/8" tubing with expendable check, F-nipple (one joint off bottom), 5. then ½ of the 2-3/8" production tubing. Run a broach on sandline to insure that the tubing is clear. TIH with remaining 2-3/8" tubing and then broach this tubing. Replace any bad joints. CO to PBTD with air/mist.
- 6. PU above the top Mesaverde perforation at 5124' and flow the well naturally, making short trips for clean-up when necessary. Obtain pitot gauge from casing and report this gauge after final clean-up.
- 7. Land tubing at 5595'. ND BOP and NU WH. Pump off expendable check. Connect to casing and circulate air to assure that expendable check has pumped off. If well will not flow on its own, make swab run to SN. RD and MOL. Return well to production.

Recommended: 4. 4 Mondow A Operations Engineer 5/19/98 Approved: Druce(). Douge

Drilling Superintendent

Contact: L. Tom Loveland Office 326-9771

> Pager 324-2568 Home 564-4418