State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division

	API # (assigned by OCD)
1	30-039-20086
1. Type of Well GAS	5. Lease Number
	6. State Oil&Gas Lease # E-290-E
2. Name of Operator	7. Lease Name/Unit Name
BURLINGTON	
RESOURCES OIL & GAS COMPANY	San Juan 27-5 Unit
3. Address & Phone No. of Operator	8. Well No.
PO Box 4289, Farmington, NM 87499 (505) 326-9700	#110 9. Pool Name or Wildcat
	Basin Dakota
4. Location of Well, Footage, Sec., T, R, M	10. Elevation:
655'FNL, 2105'FEL, Sec.2, T-27-N, R-5-W, NMPM, Rio Arriba C	County, NM
Type of Submission Type of Action	
- 	nange of Plans
	ew Construction
	on-Routine Fracturing
Casing Repair Wa	ater Shut off
	
Final Abandonment Altering Casing Co	onversion to Injection
	
Final Abandonment Altering Casing Co _X_ Other - Tubing Repair	
Final Abandonment Altering Casing Co _X_ Other - Tubing Repair	onversion to Injection
Final Abandonment Altering Casing Co_X_Other - Tubing Repair 13. Describe Proposed or Completed Operations It is intended to repair the tubing in the subject we	ell according to the attached
Final Abandonment Altering Casing Co_X_Other - Tubing Repair 13. Describe Proposed or Completed Operations It is intended to repair the tubing in the subject we	ell according to the attached
Final AbandonmentAltering Casing CoX_Other - Tubing Repair 13. Describe Proposed or Completed Operations It is intended to repair the tubing in the subject we procedure.	ell according to the attached
Final AbandonmentAltering Casing CoX_Other - Tubing Repair 13. Describe Proposed or Completed Operations It is intended to repair the tubing in the subject we procedure.	ell according to the attached
Final AbandonmentAltering Casing CoX_Other - Tubing Repair 13. Describe Proposed or Completed Operations It is intended to repair the tubing in the subject we procedure.	ell according to the attached
Final AbandonmentAltering Casing CoX_Other - Tubing Repair 13. Describe Proposed or Completed Operations It is intended to repair the tubing in the subject we procedure.	ell according to the attached
Final Abandonment Altering Casing Co X_ Other - Tubing Repair 13. Describe Proposed or Completed Operations It is intended to repair the tubing in the subject we procedure.	ell according to the attached
Final Abandonment Altering Casing Co X_ Other - Tubing Repair 13. Describe Proposed or Completed Operations It is intended to repair the tubing in the subject we procedure.	ell according to the attached 2 6 1999
Final AbandonmentAltering Casing CoX_Other - Tubing Repair 13. Describe Proposed or Completed Operations It is intended to repair the tubing in the subject we procedure. DECMAY ONL GO	ell according to the attached

San Juan 27-5 Unit #110

Basin Dakota Unit B, Sec. 2, T-27-N, R-5-W

Latitude / Longitude: 36° 36.45264' / 107° 19.51356' Recommended Tubing Repair Procedure 5/17/99

Project Justification: This well hasn't been pulled since its completion in 1968. At that time, the tubing was landed 27' above the top perforation, leading to approximately 55 psi of additional hydrostatic backpressure at the mid-perforation depth.

NOTE: ALL DEPTHS ARE MEASURED FROM KB. KB to GL was 8'.

- Comply with all NMOCD, BLM and Burlington safety and environmental regulations. Prior to 1. moving in rig, make one-call and then verify rig anchors and dig pit.
- MIRU workover rig. NU relief line and blow well down (kill with 2% KCL water only if necessary). 2. ND WH and NU BOP. Test and record operation of BOP rams. Replace any WH valves that do not operate properly. Test secondary seal and install or replace if necessary.
- Dakota, 2-3/8", 4.7#, J-55 tubing set at 7757' (245 jts). Broach tubing and set tubing plug in nipple 3. at 7756'. Fill tubing with half of its volume of 2% KCL to insure the tubing plug will be held in place. Release donut, pick up additional joints of tubing and tag bottom, recording the depth. PBTD should be at +/- 7993'. TOOH and stand back 2-3/8" tubing. Visually inspect tubing for corrosion, and replace any bad joints. Check tubing for scale and notify Operations Engineer and Drilling Superintendent if it is present.
- PU 3-7/8" bit, bit sub, and watermelon mill on 2-3/8" tubing and round trip to PBTD, cleaning out 4. with air/mist. NOTE: When using air/mist, mist rate must not be less than 12 bph. Speak with Operations Engineer and Drilling Superintendent, and if necessary, determine the best way to remove scale from the casing and perforations.
- 5. TIH with one 4' pup joint of 2-3/8" tubing with expendable check, F-nipple (above pup joint), then $\frac{1}{2}$ of the 2-3/8" production tubing. Run a broach on sandline to insure that the tubing is clear. TIH with remaining 2-3/8" tubing. Replace any bad joints. CO to PBTD with air/mist.
- PU above the top Dakota perforation at 7784' and flow the well naturally, making short trips for 6. clean-up when necessary.
- 7. Land tubing at 7950'. Obtain pitot gauge from casing and report this gauge. Broach the upper 1/2 of the production tubing. ND BOP and NU WH. Pump off expendable check. Connect to casing and circulate air to assure that expendable check has pumped off. If well will not flow on its own, make swab run to SN. RD and MOL. Return well to production.

J. Jon Journ 5/20/99 Approved: Bruce D. Boya :
Operations Engineer Drilling Superintendent

Operations Engineer: L. Tom Loveland

Office 326-9771

Pager 324-2568

Home 564-4418