## State of New Mexico Energy, Minerals and Natural Resources Department

	Oil Conservation	n Division	
	Sundry Notices and R	eports on Wells	
1. Type of Well		<b>API</b> 5.	# (assigned by OCD) 30-039-20218 Lease Number
GAS		6.	State Oil&Gas Lease #
2. Name of Operator		7.	Lease Name/Unit Name
RESOURCES OIL & GAS COMPANY		0	San Juan 27-5 Unit
3. Address & Phone No. of Operat	OF	8.	Well No. 111
PO Box 4289, Farmington, NM		9.	Pool Name or Wildcat Basin Dakota
4. Location of Well, Footage, Se 1830'FSL, 1090'FWL, Sec.2, T-			Elevation:
Type of Submission	Throng of ho		
_X_ Notice of Intent Subsequent Report	Type of Ac Abandonment Recompletion Plugging Back	Change of Plans New Construction Non-Routine Fracturing Water Shut off	
Final Abandonment	Casing Repair Altering Casing X Other - Tubing re	Conversion to Injection	
procedure.		MAR 2000 PECEIVE OIL CON. I	TO THE TOTAL PROPERTY OF THE PARTY OF THE PA
no (This space for State Use)  ORIGINAL SIGNED BY CHAR	(MH)Regulatory S		
Approved by	Title	oms inspector, dist.	Date AR - 7 2000

## San Juan 27-5 Unit #111 **Basin Dakota**

Unit L, Sec. 2, T-27-N, R-5-W

Latitude / Longitude: 36°36.02052' / 107°19.93014' Recommended Tubing Repair Procedure 2/25/2000

NOTE: ALL DEPTHS ARE MEASURED FROM KB. KB to GL was 10'.

Project Justification: The San Juan 27-5 Unit #111 was completed in 1969. In 6/99 a tubing repair was performed on this well, and a plunger lift was installed. The piston has since become lodged in the tubing. A 2" JDC was ran on wireline to 7892' on 1/13/2000, recovering only the top of the piston. Current production is 34 MCF/D. The anticipated rate from the workover is 100 MCF/D.

- Comply with all NMOCD, BLM and Burlington safety and environmental regulations. Prior to 1. moving in rig, make one-call and then verify rig anchors and dig pit.
- MIRU workover rig. NU relief line and blow well down (kill with 2% KCL water only if necessary). 2. ND WH and NU BOP. Test and record operation of BOP rams. Replace any WH valves that do not operate properly. Test secondary seal and install or replace if necessary.
- Dakota, 2-3/8", 4.7#, J-55 tubing set at **7878'** (255 jts; SN @ 7846'). NOTE: Fish (partial piston) 3. in tbg at approximately 7892'. Broach tubing and set tubing stop in tubing at 7842'. Release donut, pick up additional joints of tubing and tag bottom, recording the depth. PBTD should be at +/- 7943'. TOOH and stand back 2-3/8" tubing. Visually inspect tubing for corrosion, and replace any bad joints. Check tubing for scale and notify Operations Engineer if it is present.
- TIH with 3-7/8" bit, bit sub, and watermelon mill on 2-3/8" tubing and round trip to PBTD, cleaning 4. out with air/mist. NOTE: When using air/mist, mist rate must not be less than 12 bph. Speak with Operations Engineer, and if necessary, determine the best way to remove scale from the casing and perforations.
- TIH with one joint of 2-3/8" tubing with expendable check, F-nipple (one joint off bottom), then ½ of 5. the 2-3/8" production tubing. Run a broach on sandline to insure that the tubing is clear. TIH with remaining 2-3/8" tubing. Replace any bad joints. CO to PBTD with air/mist.
- PU above the top Dakota perforation at 7730' and flow the well naturally, making short trips for 6. clean-up when necessary.
- Land tubing at ~7892'. Obtain pitot gauge from casing and report this gauge. Broach the upper 7. ½ of the production tubing. ND BOP and NU WH. Pump off expendable check. Connect to casing and circulate air to assure that expendable check has pumped off. If well will not flow on its own, make swab run to SN. RD and MOL. Return well to production.

Approved: Druce (). Douge 3.1-00
Drilling Superintendent

Operations Engineer: Mike Haddenham

BR Office - 326-9577

Pager - 327-8427

Home - 326-3102

MDH/plh