## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

MAR 08 1990

	OIL CON. DIV.
Sundry Notices and Reports on	
1. Type of Well GAS	<ul><li>5. Lease Number</li><li>SF-080675</li><li>6. If Indian, All.or</li><li>Tribe Name</li></ul>
2. Operator INCI El Paso Natural Gas Company	<ul><li>7. Unit Agreement Name     San Juan 27-4 Unit</li><li>8. Farm or Lease Name     San Juan 27-4 Unit</li></ul>
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499	9. Well No. 92
4. Location of Well 940'N, 860'E	10.Field, Pool, Wildcat Tapacitos PC 11.Sec. T. R. M. or Blk Sec. 27, T-27-N, R-04-W NMPM
14. Permit No. 15. Elevations 7261'GR	12.County 13. State Rio Arriba NM
16. Intent to/Subsequent Report of : Repair We	11
The tubing/casing annulus of this well will be which is approximatley 100 psi greater than the psi. If pressure declines more than 10% in 15 squeeze repaired by:	most current SICP of 546 minutes, the well will be
Mol ru. Kill well as needed. Relea sand plug across perfs. Tih w/pkr a Locate hole (s) with packer. Shoot failure. Open bradenhead and circul 18 hrs. Pick up drill pipe and dril 650 psi. Resqueeze if necessary. C unload with nitrogen. Tooh. Tih w/ and reset packer.	nd test plug to 1500 psi. squeeze hole 20' below ate cement to surface. WOC l out cmt. Test squeeze to lean out sand plug and
18. Authorized by: Chalffu Jett Regulatory Affairs	1-22-90 Date
NOTE: This format is issued in lieu of US BLM F	Orm 3160-5 MAR 05 1990
	John Skill
(This space for Federal or State office use)	Chief, Branch of Mineral Resources Parmington Resource Area
CONDITION OF APPROVAL, IF ANY: MMCCO	DAIE

AND THE PROPERTY SHOW

Administration of the second o